TESTING AND EVALUATION OF SOIL BASED GROUTS FOR THE ADHESION OF CONSOLIDATED AND UN-CONSOLIDATED PAINTED LIME PLASTER AT THE MISSION SAN JOSE DE TUMACÁCORI.

Nicole Mariel Declet Díaz

A THESIS

in

Historic Preservation

Presented to the Faculties of the University of Pennsylvania In Partial Fulfillments of the Requirements of the Degree of

MASTER OF SCIENCE IN HISTORIC PRESERVATION

2017

Advisor

Frank G. Matero Professor of Architecture

Program Chair

Randall F. Mason

Associate Professor and Chair, Historic Preservation

Acknowledgments

First, I would like to thank my thesis advisor, Frank G. Matero for suggesting such a wonderful topic, and for the opportunity to work with such an outstanding structure, The Mission San José de Tumacácori. His guidance and encouragement during this process was invaluable. I would also like to thank the U.S. National Park Service, and the Tumacácori National Historic Park's staff, in particular, Alex B. Lim, for all of his help in acquiring materials for this testing program.

Thank you to the ACL Staff for providing access to all their background information on Tumacácori. I am very appreciative of Courtney Magill, for her ongoing support and assistance in making sure I had everything I needed to perform testing for this research.

I would also like to thank my classmates, the HPSV Class of 2017, in particular Araba Prah for her support during the long nights in the laboratory and for her assistance during testing. Special thanks to Nityaa Iyer for responding promptly to questions regarding her wonderful research on soil grouts.

Finally, I am extremely thankful to my family and friends for providing me immense joy and support.

Contents

Acknowledgments	ii
Table of Contents	iii
List of Figures	vi
List of Tables	xi
Chapter 1: Introduction	1
Chapter 2: Context	3
2.1 Mission San José de Tumacácori History	3
2.1.1 Materials and Construction	9
2.1.2 Plaster Composition & Description- Previous Analysis	13
2.1.3 Adobe Composition & Description	14
2.2 Conditions and Factors enabling deterioration	18
2.3 Conservation Treatment History at Tumacácori	25
2.3.1 Conservation Treatments: 1920s to 1960s	26
2.3.2 Conservation Treatments: 1970s	32
2.3.3 Conservation Treatments: 1980s	
2.3.4 Conservation Treatments: 1990s to 2000s	41
2.3.5 Conservation Treatments: 2010s to present	43
Chapter 3: Grout Injection Used for Repair on Earthen Buildings	46
3.1 Brief History on Grout Injection Used for Repair on Earthen Buildings	46
3.2 Challenges with Grouting	47
3.3 Structural and Nonstructural Repair Grouts	48
3.4 Amended and Unamended Earthen Grouts	49
3.5 Earthen Grout Design	52
3.5.1 Methodology and Testing Schedule	53
3.5.2 Earthen Grout Properties	55
3.6 Conclusive Remarks	59
Chapter 4: Methodology	61

4.1 Sample Retrieval and Ma	terial Characterization	61
4.2 Adobe and Soil Character	rization	63
4.2.1 Summary of Results.		71
4.2.2 Original Adobe Resul	Its Conclusion	80
Chapter 5: Grout Design		81
5.1 Selection of Soil "E" for g	rout binder	81
5.1.1 Grout Formulation a	nd Components	83
5.2 Grout Mixing		
5.3 Grout Testing		86
5.3.1 Wet Properties		86
5.3.2 Hardened Properties	\$	91
5.4 Mockup Assembly (plaste	er + grout + gap + adobe)	
5.4.1 Plaster Facsimiles		
5.4.2 Nanolime Consolidat	ion on Friable Plaster Facsimiles	
5.4.3 Shear Bond Strength	۱	
Chapter 6: Laboratory Testing ((Rheology)	
6.1 Flow/ Viscosity		
6.2 Wet Density		
6.3 Drying Shrinkage		
6.4 Expansion & Bleeding		
6.5 Splitting Tensile Strength	۱	
6.6 Capillary water absorptio	on	
6.7 Water Retention		
6.8 Permeability (WPT)		
6.9 Shear Bond Strength (mc	ock-up)	
Chapter 7: Conclusions and Red	commendations	
7.1 Testing Conclusion		
7.2 Future Testing and Recor	mmendation	

Bibliography	134
Appendix A: Plaster Petrographic Analysis	141
Appendix B: Characterization of Soils	156
Appendix C: Grout Rheology Calculations	164
Index	

List of Figures:

Figure 1: Present day Mission San José de Tumacácori. Source: Unknown photographer. National P	ark
Service.	3
Figure 2: (left) Missions of the Santa Cruz River Valley. Three missions are considered part of	
Tumacácori Historical National Park. Source: Missions of Tumacácori National Historic Park	
Overview Draft, South West Learning, National Parks Service (Moss, 1).	4
Figure 3: (right) Archaeological Map of San José de Tumacácori. Source: Missions of Tumacácori	
National Historic Park Overview Draft, South West Learning, National Parks Service (Moss, 3).	4
Figure 4 San Xavier del Bac, also located in Tucson, is an example of the elaborate churches	
reconstructed by the Franciscans. Source: On the Road Again For You tours,	
http://www.ontheroadagainforyou.com/san-xavier-mission-del-bac-corona-de-guevavi-tubac	:/. 5
Figure 5: Tumacácori Sketch circa 1849.	6
Figure 6: Tumacácori façade after the 1890 earthquake. Source: Source: Unknown. "In the afterma	ath
of an earthquake in 1890." NPS. 1912.	
https://www.nps.gov/media/photo/gallery.htm?id=FA98A28D-155D-451F-	
67F12C7DD7B694AE	7
Figure 7: The mission underwent reconstruction and restoration under Pinkley. Source: Unknown.	
"Tumacácori 1930." NPS. 1930. https://www.nps.gov/media/photo/gallery.htm?id=FA98A28)-
155D-451F-67F12C7DD7B694AE	8
Figure 8: West Wall of Nave section. Source: Longitudinal Section on Line A-A. West Wall of Nave a	nd
Sanctuary. Church of San José de Tumacácori. Tumacácori national Monument- Santa Cruz	
County, Arizona. HABS Drawings. 1975.	10
Figure 9: Stitched West Wall of Nave section. Source: Drachman Institute Heritage Conservation.	
Interior Condition Assessment Report. Tumacacori National Historic Park. College of	
Architecture, Planning, and Landscape Architecture. The University of Arizona. In conjunction	
with Desert Southwest Cooperative Ecosystem Studies Unit. July 2006: 72, 76, 80.	10
Figure 10: Illustrations of Façade. Source: "Detail of South Facade- San Jose de Lumacacori (Missio	n,
Ruins), Tubac, Santa Cruz County, AZ." 1949. Library of Congress Prints and Photographs Divis	lon
Washington, D.C. 20540 USA http://hdl.loc.gov/loc.pnp/pp.print	11
Figure 11: Illustrations of Altar. Source: Trujillo, Jimmy. "Detail of Sanctuary Showing Altar - San Jos	e
de Tumacacori (Mission, Ruins), Tubac, Santa Cruz County, AZ." 1949. Library of Congress Prir	ITS
and Photographs Division Washington, D.C. 20540 USA http://hdl.ioc.gov/ioc.pnp/pp.print	11
Figure 12 Nave Elevation Illustration. Source: "West Elevation of Nave, Detail Showing Altar and Pie	er-
San Jose de Tumacacori (Mission, Ruins), Tubac, Santa Cruz County, AZ." 1949. Library of	
Congress Prints and Photographs Division Washington, D.C. 20540 USA	10
http://hdl.loc.gov/loc.pnp/pp.print	12
Figure 13 Tumacácori Soil Composition. Source: McHenry, Paul Graham. Adobe and Rammed Earth	1
Buildings: Design and Construction. University of Arizona Press, 1989.	15
Figure 14 Density of Tumacacori adobe samples. Source: Brown, Paul Wencil, Carl R. Robbins, and	
James R. Clifton. "Adobe. II: Factors Affecting the Durability of Adobe Structures." Studies in	
Conservation 24, no. 1 (1979): 35.	17

Figure 15 Data collected on Boring B/3 by Marco Soil and Foundation Engineers. Source: Percious,	, D.J.
and M. Norvelle. Report on the Examination of Available Evidence on the Deterioration of th	e
Walls of the Tumacacori Mission. Tucson, AZ: University of Arizona, 1978, 64.	22
Figure 16 Tumacácori Fringe Profile. Source: Percious, D.J. and M. Norvelle. Report on the	
Examination of Available Evidence on the Deterioration of the Walls of the Tumacacori Missi	on.
Tucson, AZ: University of Arizona, 1978, 53.	22
Figure 17 Sample Locator Map. Source: Brown, Paul Wencil, Carl R. Robbins, and James R. Clifton.	
"Adobe. II: Factors Affecting the Durability of Adobe Structures." Studies in Conservation 24,	no.
1 (1979): 29.	23
Figure 18: Moisture Profiles of the West Nave Wall. Source: Crosby, Anthony. Historic Structure	
Report: Tumacacori National Monument Arizona, 1985: 105.	24
Figure 19: Roskruge, George. Nave of Tumacacori Mission looking toward choir loft and entrance.	
1889. Classification No: 266.2791, Negative No. 1060, U.S Department of the Interior, NPS,	
Coolidge, Arizona.	25
Figure 20 Collier, Marguerite L. Church interior, nave, looking toward sanctuary. 1919. Classification	on
No: File 502. U.S. Department of the Interior, NPS, Coolidge, Arizona.	25
Figure 21: Reed, Harry. Interior of Tumacácori Mission Altar View. 1945. Classification No: 266.275	Э1.
Negative No. 1/470, 915. U.S. Department of the Interior, NPS, Coolidge, Arizona.	25
Figure 22: Grouting white cement to lower edge of plaster. Source: Henderson, Sam R. Stabilization	on
Report: Tumacacori National Monument 1972. Arizona Archaeological Center, Ruins	
Stabilization Unit: Tucson, AZ, 1972: 42.	26
Figure 23: A worker tapping a pin into the previously bored hole. The inserted pins were later grou	uted
over. Source: Sudderth, W.W. The Nave and Bell Tower Stabilization Report 1973. Tumacace	ori
National Monument. Ruins Stabilization Unit. Arizona Archaeological Center. Tucson, Arizona	а,
1974: 48.	31
Figure 24: Holes drilled through cement plaster. Source: Chambers, George J. Tumacacori	
Preservation Project: Field Activities 1977, 1978, and 1979. Western Archeological Center, 1	981,
13.	34
Figure 25 Cement removal procedures on the exterior walls consisted of cutting on a grid pattern	with
builder's saws equipped with masonry blades. Source: Chambers, George J. Tumacacori	
Preservation Project: Field Activities 1977, 1978, and 1979. Western Archeological Center, 1	981,
26.	35
Figure 26 Major dome repair and replastering with lime plaster. Source: Chambers, George J.	
Tumacacori Preservation Project: Field Activities 1977, 1978, and 1979. Western Archeologic	cal
Center, 1981, 52.	37
Figure 27: Diagrams showing efflorescence formation. Source: Crosby, Anthony. Historic Structure	ž
Report: Tumacacori National Monument Arizona, 1985: 184.	38
Figure 28: Plaster showing remain of Acyrloid B-72 treatment. Source: Crosby, Anthony. Historic	
Structure Report: Tumacacori National Monument Arizona, 1985: 183.	39
Figure 29: Repairing plaster on the exterior of the west sanctuary window, cornice and dome apro	on.
Source: Tumacácori National Historic Park. Unknown Publisher. July 6-8, 2009: 3.	43
Figure 30: Report on Plaster Cracking and Leaks Associated with the West Sanctuary Window. Sou	irce:
Tumacácori National Historic Park. Unknown Publisher. July 6-8, 2009: 3.	43

Figure 31 Flaking yeso finishes on the plaster were treated using a 1982 technique, which consiste	ed of
a 5% solution of gelatin in warm water. Source: Bass and Porter. Assessment, Emergency	
Stabilization and Treatment of Painted Plasters in the Mission Church at Tumacacori Nationa	ıl
Historic Park, School of Architecture and Planning, 2012: 53.	45
Figure 32: Salt sample dome locations. Source: Bass and Porter. Assessment, Emergency Stabilizat	ion
and Treatment of Painted Plasters in the Mission Church at Tumacacori National Historic Par	·k,
School of Architecture and Planning, 2012: 32.	45
Figure 33 : The poultice, composed of cellulose and distilled water, is being applied at Tumacácori	to
remove salts. Source: Bass and Porter. Assessment, Emergency Stabilization and Treatment	of
Painted Plasters in the Mission Church at Tumacacori National Historic Park, School of	
Architecture and Planning, 2012: 48.	45
Figure 34: Vargas testing for tensile strength on adobe sandwiches. Source: An Experimental Stud	y of
the Use of Soil-Based Grouts for the Repair of Historic Earthen Walls and a Case Study of an	
Early Period Buddhist Monastery. Terra 2008: The 10th International Conference on the Stud	dv
and Conservation of Earthen Architectural Heritage. The Getty Conservation Institute and th	e
Mali Ministry of Culture. 1096.	51
Figure 35: Grouting delaminated earth plasters at Cave 85. Source: Implementation of Grouting a	nd
Salts-Reduction Treatments at Cave 95 Wall Paintings. In Conservation of Ancient Sites on th	e
Silk Road. Second International Conference on the Conservation of Grotto Sites (Rickerby et	al.
2008, 483).	54
Figure 36: Figure 34: Grouting of west window plaster at Tumacácori. Cotton was used to catch	
overflows and prevent further detachment due to any pressure exerted by the grout. A solution	tion
of 1 part NHL 3.5: 1 part ceramic microspheres was used. Source: Assessment, Emergency	
Stabilization and Treatment of Painted Plasters in the Mission Church at Tumacacori Nationa	ıl
Historic Park, School of Architecture and Planning (Bass and Porter, 49).	57
Figure 37: Potential disadvantages of earthen grout components. Source: Development and Testir	ng of
the Grouting and Soluble-Salts Reduction Treatments of Cave 85 Wall Paintings. In Conserva	tion
of Ancient Sites on the Silk Road, Second International Conference on the Conservation of	
Grotto Sites (Rickerby et al. 2008, 473).	59
Figure 38: Soil retrieval location identification in Nogales, Arizona. Source: Declet 2017.	62
Figure 39: The three soil types (A, B, and E) and the original adobe were sieved and placed on	
weighing boats. Source: Declet 2017.	64
Figure 40: Combined wet/ dry sieving procedure. Source: Declet 2017.	66
Figure 41: Before and after of the soil sedimentation. Source: Declet 2017.	66
Figure 42: Plastic limit process (left) of rolling soil into a thin 3mm thread. The liquid limit test (right	nt)
was also tested using the Casagrande device. Source: Declet 2017.	, 67
Figure 43: After an hour of combining the soil and the solutions, pH readings were taken. Source:	
Declet 2017.	68
Figure 44: The total organic content was calculated by subtracting the second and first weight loss	5.
Source: Declet 2017.	69
Figure 45: Using a dropper, a few drops of deionized water were dropped over a small amount of	soil.
This mix was later stirred, and the Merck strip was placed in the solution. Source: Declet 201	7.70
Figure 46: Using a dropper, a few drops of deionized water were dropped over a small amount of	soil.
This mix was later stirred, and the Merck strip was placed in the solution. Source: Declet 201	7.70

Figure 47: After preparing the 10g/L methylene blue solution, 5ml doses of methylene blue trihy	drate
were added and with a glass rod, a drop is placed onto filter paper.	71
Figure 48: Fine particles attached to the coarse particles of the soil types. Source: Declet 2017.	72
Figure 49: Components of the grout: 2.5 Soil E: 1 part HMP. Source: (Right Images) Declet 2017 (Left
Images) DMW 2016; Humboldt Manufacturing.	83
Figure 50: First, 1725 mL of water was poured through the cone twice and two flow measureme	nts
were recorded. Afterwards, the prepared grout was poured, and three stop watches were	
started once the finger stopper was removed. Source: Declet 2017.	87
Figure 51: The syringe was filled with 12 mL of grout instead of 5 mL, and was tapped to remove air bubbles. It was finally weighed to calculate the wet density of the grout. Source: Declet	any
2017.	88
Figure 52: These were observed for 28 days, while monitoring the temperature and relative	
humidity.	89
Figure 53: The molds were pre lubricated several times with mineral oil to prevent the wooden r	nold
from drawing water out of the grout. After pouring, the molds were observed to make sure	e no
sagging occurred. The total percent shrinkage of the specimens was calculated at the end.	
Source: Declet 2017.	90
Figure 54: After mixing, the grout was poured into a 500 mL graduated cylinder until the sample	
reached 400 mL. The top was covered with parafilm to prevent evaporation of any possible	ž
bleeding water. Source: Declet 2017.	91
Figure 55: The earthen grout was prepared by pouring directly into pvc molds, 4 inches in length	and
2 inches in diameter. Source: Declet 2017.	. 93
Figure 56: The maximum load, also known as the breaking load was recorded in psi to calculate t	the op
splitting tensile strength. Source: Declet 2017.	93 • The
Figure 57: All columns were stored for a minimum of two weeks before removing from containe	r. The
glass tray was placed inside a larger container with a petitidish filled with desiccant to prev	eni ۵5
Figure 58: After performing the test, the underside of the dish is dahled with a damp cloth. Source	rce.
Declet 2017	97
Figure 59: After preparing the grout mix 200 ml of the solution is poured into a beaker which is $\frac{1}{2}$	then
poured into the perforated dish. Source: Declet 2017.	98
Figure 60: The grout was first mixed and poured into pvc disk molds. 2 inches in dimeter and 1 ir	nch
tall. Source: Declet 2017.	99
Figure 61: In order to achieve a tight seal between the grout disk and beaker, paraffin was melte	d on
a hot plate and was dropped alongside the rim of the beaker with a dropper. Once finished	l, the
test assembly was weighed.	100
Figure 62: Felker Mason Mite II masonry wet saw used to cut the adobe. Source: Declet 2017.	102
Figure 63: Adobe assemblies measuring 3.5in x 3.5in x 3in. Source: Declet 2017.	102
Figure 64: Friable plaster formulation consisted of 1 part Type S Lime: 5 parts sand: 1.3 parts	
water.	104
Figure 65: All molds were continuously coated with mineral oil 24 hours before preparing the mi	x. 105
Figure 66: Two 0.5in wood strips were glued onto the bottom of the base (3.5in x 3.5in x 0.75in)	. The
sides consisted of two 3.5in x 2.25in and two 4.875in x 2.25in plywood pieces Source: Dec	let
2017.	105

Figure 67: The new molds improved the demolding process. The sides of the mold were attached	with
masking tape. Source: Declet 2017.	106
Figure 68: Nanolime consolidant was applied in three cycles. Source: Declet 2017.	107
Figure 69: Assemblies prior to grouting. Source: Declet 2017.	109
Figure 70: Grout Assembly diagram. Source: Declet 2017.	109
Figure 71: Adobe faces were pre-wetted prior to the grouting procedure. Grouting was done by	
attaching a tube unto a catheter tip syringe. Source: Declet 2017.	110
Figure 72: Assemblies before and after testing for shear bond strength. Source: Declet 2017.	111
Figure 73: Silva et al. grout formulations. Source: Silva et al. "On the development of unmodified r	nud
grouts for repairing earth constructions: rheology, strength and adhesion." ISISE, University	of
Minho, Portugal and Catholic University of Leuven, Belgium, 2012: 29.	114
Figure 74: Mixed developed and characterized by Pingarrón in 2006. Source: Pingarrón Alvarez,	
Victoria I. Performance Analysis of Hydraulic Lime Grouts for Masonry Repair. Masters These	25
(Historic Preservation), University of Pennsylvania, 2006: 26.	116
Figure 75: O'Bannon compressive strength results for Tumacácori adobe soil. Source: O'Bannon,	
Charles E. Stabilization of Prehistoric Adobe Architecture by Electro-osmosis and Base Excha	nge
of Ions (Phase II). Arizona: Arizona State University, 1978: 36.	119
Figure 76 Angelyn Bass's tested grout formulations (1998). Source: Bass, Angelyn. Design and	
Evaluation of Hydraulic Lime Grouts for In Situ Reattachment of Lime Plaster to Earthen Wal	ls.
Masters Thesis, University of Pennsylvania, 1998: 73.	124
Figure 77: Close-up geological map location of Tumacácori. Source: Oland, G.P and D.M. Hirschbe	rg,
Digital Geologic Map of the Tucson and Nogales: A Digital Database for the 1990 Peterson a	nd
others' Map. USGS Department of the Interior U.S. Geological Survey, 2001.	
http://geopubs.wr.usgs.gov/open-file/of01-275	142

List of Tables:

Table 1: Methodology Schedule. Source: Declet 2017	61
Table 2: Testing Schedule for Characterization of soil types and original adobe. Source: Declet 201	7.63
Table 3: Soil Profile for Soil Types and Original Adobe. Source: Declet 2017	71
Table 4: Granulometry of soil types and original adobe. Source: Declet 2017	72
Table 5: Particle Gradation. Source: Declet 2017	72
Table 6: Combined Dry Sieving Soil Profile. Source: Declet 2017	73
Table 7: Combined Dry Sieving Particle Gradation for soil types and original adobe. Source: Declet	
2017	74
Table 8: Source: Amount of particles that did and didn't pass through Sieve no.200. Declet 2017	74
Table 9: Hydrometer Readings for soil types and original adobe. Source: Declet 2017	75
Table 10: Plasticity soil results for soil types and original adobe. Source: Declet 2017	77
Table 11: Liquid Limit Test for soil types and original adobe. Source: Declet 2017	78
Table 12: Soil pH results. Source: Declet 2017	78
Table 13: Organic Content Results. Source: Declet 2017	79
Table 14: Semi quantitative salt analysis results. Source: Declet 2017	79
Table 15: Required properties for a successful grout. Source: Declet 2017.	81
Table 16: Overview of results for characterization of soil types and original adobe. Source: Declet	
2017	82
Table 17: Testing schedule for grout testing. Source: Declet 2017	86
Table 18: Plaster coupon ratios. Source: Declet 2017.	. 104
Table 19: Flow and viscosity test results for grout. Source: Declet 2017	. 112
Table 20: Wet Density Results for grout. Source: Declet 2017.	. 114
Table 21: Drying Shrinkage results for grout prisms. Source: Declet 2017.	. 115
Table 22: Splitting Tesnsile Strength results for grout. Source: Declet 2017.	. 117
Table 23: Splitting Tensile Strength results graph. Source: Declet 2017	. 118
Table 24: Splitting Tensile Strength results for consolidated plaster obtained by Jean Jang	
(unpublished)	120
Table 25: Water retention and release comparison results. Source: Declet 2017	. 121
Table 26: Grout water retension and release results. Source: Declet 2017	. 122
Table 27: Average wpt rates for 6 grout specimens.	. 123
Table 28: Observations for all assemblies tested for shear bond strength. Source: Declet 2017	. 129
Table 29: Shear Bond Strength results for assemblies. Source: Declet 2017	. 129
Table 30: Analysis of shear bond strength results for assemblies. Source: Declet 2017	. 130
Table 31: Graph comparing shear bond strength results of un-consolidated and consolidated	
assemblies.	130
Table 32: Overall results for grout testing. Source: Declet 2017	. 131

Chapter 1: Introduction

The interior painted plaster finishes of Mission San José de Tumacácori are a rare survival of late 18th century-early 19th century artistic traditions of northern Sonora and the Kino mission churches. Despite earlier attempts to stabilize these interior finishes, the original painted lime plaster has continued to detach from the adobe substrate.1

The current research evaluates soil-based injection grouting in order to re-adhere the detached plaster from its adobe substrate. Earthen grouts were chosen over the more commonly used hydraulic lime grouts in order to consider a more compatible system with the original adobe substrate. A well-designed earthen grout must be fluid enough to insure good injectability and full void penetration, exhibit low shrinkage, and strong bond strength equal to its own cohesive strength for successful repair.

Samples of the original adobe, mortar, and plaster were analyzed and local soils were sampled and tested in order to design a grout displaying optimal properties. The proposed grout formation made use of 2% sodium hexametaphosphate (HMP) in the mixing water. HMP is a common ingredient for sedimentation processes in soil analysis and has been employed to reduce shrinkage and viscosity in earthen grouts (Silva and Oliveira 2009; Silva et al. 2012; Lourenco et al. 2013; Iyer 2014). The test grout was subjected to several geo-technical tests including viscosity, density, shrinkage, and

¹ Previous techniques to conserve the paintings began with research by J. Rutherford Gettens in 1949-1952 and subsequent attempts in 1984 to reattach detached plaster have proven ineffective. The last time exhaustive work was done in the interior nave was in 1984.

expansion/ bleeding; as well as its hardened properties such as splitting tensile strength, capillary water absorption, water retention and permeability.

The selected grout's performance was finally analyzed within a mock-up assembly composed of friable plaster facsimiles and adobe, simulating 1/2" and 1/4" gaps. Half of the plaster facsimiles were consolidated with nanolime due to their friable nature based on recent complementary research (Jang 2016). The research expands current knowledge on the use of earthen grouts for reattachment of earthen and lime plasters on earthen substrates.

Chapter 2: Context

2.1 Mission San José de Tumacácori History



Figure 1: Present day Mission San José de Tumacácori. Source: Unknown photographer. National Park Service.

The Mission San José de Tumacácori is one of two Spanish-Colonial buildings to be designated a National Monument in 1908 by President Roosevelt under the Antiquities Act (Moss 2008, 3). The site became a National Historic Park in 1990, 72 years after federal management. Today, the structure stands amid a 360 acre park, located south of Tucson, Arizona within the Santa Cruz River Valley. Unlike other Spanish Colonial missions within the United States, Tumacácori was never completed and its belltower remains unfinished to this day.



Figure 2: (left) Missions of the Santa Cruz River Valley. Three missions are considered part of Tumacácori Historical National Park. Source: Missions of Tumacácori National Historic Park Overview Draft, South West Learning, National Parks Service (Moss, 1).

Figure 3: (right) Archaeological Map of San José de Tumacácori. Source: Missions of Tumacácori National Historic Park Overview Draft, South West Learning, National Parks Service (Moss, 3).

Built in the early 19th century on Tohono O'odham (Pima)lands, the mission church is a cultural hybrid that embodies the traditions of two cultures. The monument is comprised of remains of the original Jesuit church of the mid-18th century, a new (current) church by the Franciscans in the early 19th century, three *convento* rooms, remains of a buried *convento*, a cemetery, a chapel, a lime kiln, and an orchard and acequia. At one point, the mission contained 5,000 cattle, 2,700 sheep and goats, and 750 horses (Graham 2011, 3).

The mission was established by the Jesuit Father Eusebio Kino who also founded the nearby church of San Xavier del Bac outside Tucson, Arizona. After his death in 1711, most missions were abandoned. The Jesuits were later removed from the Americas in 1767 due to political conflicts that arose between King Charles III and the Jesuit Order. The Jesuits were replaced by the Franciscans who rebuilt larger and often more elaborate and permanent churches. For instance, San Xavier del Bac went from a simple adobe church to the elaborate place of worship it is today (See Figure 4).



Figure 4 San Xavier del Bac, also located in Tucson, is an example of the elaborate churches reconstructed by the Franciscans. Source: *On the Road Again For You* tours, http://www.ontheroadagainforyou.com/san-xavier-mission-del-bac-corona-de-guevavi-tubac/.

Animosity between the O'odham (Pima) Indians and the Spanish led to several

revolts in the 18th century, which explains why the Tumacacori mission was relocated to the west side of the Santa Cruz River Valley (Moss, 2). As a result, the mission was renamed San José de Tumacácori. A new church was eventually built by the Pima and Papago Indians under the Franciscan friars, but funds were lacking to complete the construction in a timely manner. After Mexico gained its independence from Spain in 1821, the missionaries began abandoning the area partly due to Apache raids (Graham 2011, 3). Eventually, the few remaining residents left in 1848. For these reasons, the mission remained unfinished and preservation efforts have procured to maintain Tumacácori as a partially restored ruin.



Figure 5: Tumacácori Sketch circa 1849.

Source: H.M.T. Powell. "Tumacácori: HMT Powell sketch ca 1849. Powell drew this sketch in his journal on his way to California." 1849. NPS. https://www.nps.gov/media/photo/gallery.htm?id=FA98A28D-155D-451F-67F12C7DD7B694AE



Figure 6: Tumacácori façade after the 1890 earthquake.² Source: Source: Unknown. "In the aftermath of an earthquake in 1890." NPS. 1912. https://www.nps.gov/media/photo/gallery.htm?id=FA98A28D-155D-451F-67F12C7DD7B694AE

Throughout the years, NPS preservation methods have changed in an effort to preserve the mission complex as a stabilized ruin. It was Frank "Boss" Pinkley, the site's original superintendent and later administrative leader of the entire Southwest Monuments Group who developed the philosophy of repair and stabilization based on original construction methods and in kind replacement materials. Correspondingly, the

² The largest earthquake documented on the southern geological Basin and Range Province, caused irreparable damage to the building's fabric. The 7.4 magnitude earthquake is said to have caused a large crack in the interior west wall of the mission church, as well as damaging the base of the façade columns and the pediment and choir loft.

intention early on was to restore the mission without the appearance of it looking restored (Attwell and Gordon 1935).₃



Figure 7: The mission underwent reconstruction and restoration under Pinkley. Source: Unknown. "Tumacácori 1930." NPS. 1930. https://www.nps.gov/media/photo/gallery.htm?id=FA98A28D-155D-451F-67F12C7DD7B694AE

³ Afterwards, maintenance of existing conditions became a more popular preservation philosophy depending instead on new chemical treatments, especially for waterproofing.

2.1.1 Materials and Construction

The Mission's design and construction embodies Spanish colonial, Mexican, Native American, and Euro-American influences. The Spanish (Jesuits and later Franciscans) introduced the use of lime mortars and sun dried mud bricks or adobes to the native community, while the building's construction and decoration was executed by Native American laborers and artists.

The mission's exterior was originally finished in polychromatic painted lime plaster, with decorative painting in its interior. Fired brick was used for the church façade and unfinished bell tower, laid with lime mortar, while the majority of the structure was built of adobe. The exterior and interior plasters used to finish the adobe and brick surfaces are generally composed of two 1" thick lime plaster layers, followed on the interior only by a thin gypsum wash layer.⁴ Described as green while still wet, the surface was hand polished or by using rawhide skin (Jackson to Davis 1948, 2).⁵

⁴ The walls are mostly composed of adobe bricks with mud mortar beds as thick as the adobe itself, all laid in a traditional manner. However, fired brick is located at the top of the walls, functioning as a cap. The fired bricks were laid with lime mortar.

⁵ This was included in a letter written by Tumacácori custodian, Earl Jackson, to Raymond E. Davis, and University of California Division of Civil Engineers on April 13, 1948.



Figure 8: West Wall of Nave section. Source: Longitudinal Section on Line A-A. West Wall of Nave and Sanctuary. Church of San José de Tumacácori. Tumacácori national Monument- Santa Cruz County, Arizona. HABS Drawings. 1975.



Figure 9: Stitched West Wall of Nave section. Source: Drachman Institute Heritage Conservation. Interior Condition Assessment Report. Tumacácori National Historic Park. College of Architecture, Planning, and Landscape Architecture. The University of Arizona. In conjunction with Desert Southwest Cooperative Ecosystem Studies Unit. July 2006: 72, 76, 80.



Figure 10: Illustrations of Façade. Source: "Detail of South Facade- San Jose de Tumacacori (Mission, Ruins), Tubac, Santa Cruz County, AZ." 1949. Library of Congress Prints and Photographs Division Washington, D.C. 20540 USA http://hdl.loc.gov/loc.pnp/pp.print



Figure 11: Illustrations of Altar. Source: Trujillo, Jimmy. "Detail of Sanctuary Showing Altar - San Jose de Tumacacori (Mission, Ruins), Tubac, Santa Cruz County, AZ." 1949. Library of Congress Prints and Photographs Division Washington, D.C. 20540 USA http://hdl.loc.gov/loc.pnp/pp.print



Figure 12 Nave Elevation illustration. Source: "West Elevation of Nave, Detail Showing Altar and Pier- San Jose de Tumacacori (Mission, Ruins), Tubac, Santa Cruz County, AZ." 1949. Library of Congress Prints and Photographs Division Washington, D.C. 20540 USA http://hdl.loc.gov/loc.pnp/pp.print

Most of the materials employed for its construction were locally sourced or made on site (Steen and Gettens 1949, 10). The lime used for the plaster was probably made in the lime kiln located a hundred yards north of the building. Historical documents describe the plaster as mostly made of lime putty with sand tempering (Jackson 1948). Historic accounts obtained from Raymond E. Davis, claim the lime was made by burning impure limestone from deposits found in nearby hills.⁶ Davis also speculated that the plaster was made from a weak hydraulic lime or cement (Davis 1948); however, no pozzolanic compounds have been identified during more recent analysis.

⁶ The Roman custom, volcanic ash and sand containing volcanic glasses, was also speculated to have been used for the plaster mix.

The dome was built using similar sized fired bricks to provide more stability. The dome's interior was coated with two plaster coats followed by a gypsum wash. The exterior was covered by lime plaster, and later, cement stucco (Mulhern 1985).7

The foundation was made out of cobblestones from the river bed located less than half a mile away. The floor was made with broken brick laid with lime mortar covered with a red painted plaster wash (Steen and Gettens 1949, 11).

2.1.2 Plaster Composition & Description- Previous Analysis

Plaster samples were first analyzed by Earl Jackson in 1948. Results confirmed the binder was composed of slaked lime, which had completely carbonated. There was no evidence of any hydraulic compounds (Davis 1948).⁸ The quicklime used for the plaster contained 92% calcium carbonate, and 4 % iron oxides and aluminum. The plaster analysis estimated the original proportions of the mix to be: 1 part lime putty to 3.5 parts bank sand. No evidence of organic fibers was found in the plaster. The sand's fineness modulus was around 2.1 (Davis 1948). According to Steen and Gettens (1949), the plaster was estimated to contain 20-25% lime and the finish coat was:

...mainly burned gypsum, which has reverted back to the dihydrate, CaSO4.2H20. (...)in addition to the fine crystalline calcium sulphate dihydrate which makes up the bulk of the white finish coat, there is a fair amount of coarser fibrous crystalline material not ordinarily found in gypsum plaster. (...)The gypsum layer is only 1-2mm thick and was probably applied as a water paint or whitewash. (Steen and Gettens 1949, 35).

⁷ This is part of a memorandum prepared by Tom Mulhern in May 31, 1985.

⁸ Hydraulic compounds, or a substance that might have been used as a hardener nor any calcium silicate formation, which could have stemmed from lime and reactive silica formation.

More recent petrographic analysis of the exterior plaster was performed by *Highbridge Materials Consulting* in 2014. The sample was retrieved from the sacristy roof, and was identified as a "high-calcium lime mixture containing a well-graded, natural sand. No hydraulic or pozzolanic material was detected..." (Highbridge Materials Consulting, Inc. 2014). The report also noted the original materials were well mixed and well consolidated. The amount of sand in the mix was significant, doubling the putty lime used. Overall, the plaster was a light gray color and its binder was soft and permeable, yet cohesive.

2.1.3 Adobe Composition & Description

The adobe was characterized during the 1970s. In 1976, Charles E. O'Bannon was consulted to find a treatment to strengthen the adobe against erosion, with a particular focus on electro-chemical treatment.⁹ To assess how feasible this irreversible treatment was, two sites were selected: Casa Grande National Monument and Tumacacori National Monument. O'Bannon realized most of the preservation efforts throughout the years focused on plaster characterization.

Soil near the site was analyzed by O'Bannon due to the likelihood that this was the same soil used for the adobe construction. The soil was described as well graded, containing 66% sand and 34% silt and clay.

...medium gray when dry, dark gray when wet, inorganic, fine grained, sandy silty clay with low plasticity and dry strength, classified as CL under

⁹ Chemical solutions applied to the material goes into the pores, and attempts to replace weaker bonding ions in the soil with stronger ones, with the purpose of increasing strength properties. Such treatment is irreversible (O'Bannon 1978).

the unified soil classification system. The index properties are as follows: 1) Specific gravity: 2.55, 2) Plasticity index: 6 (O'Bannon 1978, 13-15).

His overall conclusion found the soil to be a weak construction material. Paul

Graham McHenry also analyzed the soil composition used for the adobes at Tumacacori,

of Total Sample		5, MOI (al)	and mud r	145101-	Average	Percent
Location	Gravel	C Sand	F Sand	Silt	Clay	Porosity
Tumacacori, Arizona*						
Adobes						
P1 10 samples	14.4	20.2	24.8	27.8	13.9	32.3
P2 8 samples	10.7	23.7	30.1	25.8	9.7	33.1
P3 12 samples	10.5	22.2	28.9	27.0	11.2	34.6
P4 8 samples	12.1	24.4	29.8	24.9	9.0	31.0
P5 13 samples	8.0	18.6	30.1	26.7	18.0	34.2
P6 10 camples	82	197	29.4	31 1	11 5	

and found a larger amount of sand and silt (McHenry 1989, 50).

Figure 13 Tumacácori Soil Composition. Source: McHenry, Paul Graham. Adobe and Rammed Earth Buildings: Design and Construction. University of Arizona Press, 1989.

Additional characterization of adobe specimens was performed in December 1976 by Micromeritics Instrument Corporation, Paul W. Brown, Carl R. Robbins and James R. Clifton to analyze pore structure, particle size distribution, density, and mineralogic and petrographic characterization. Some of the specimens sampled were poor in clay size material, moist and poorly consolidated (Robbins 1976; Brown et al. 1979). The overall color was dark brown, Munsell color 7.5 yr 4/2, and the adobe contained many fine pores. Gypsum particles measuring up to 0.5mm were found, as well as carbonates, perhaps

calcite.

Tumacacori adobe indicated that the sand was subjected to abrasive action. Particles of this size tend to become rounded through the action of running water. This suggest that the soil or sand was obtained from a stream near the site (Brown et al. 1979, 31).

Adobe specimens collected for consolidation contained the following minerals: quartz, rounded fragments of quartzite, euhedral crystals of unaltered alkaline feldspar, angular to rounded grains of calcic feldspars, muscovite, altered amphibole, biotite mica, ilite, gypsum, rutile, titanite, hematite, kaolinite clay (Brown et al. 1979, 30).

The silt and the fine quartz sand fraction is quite angular and forms interlocking particles in the clay-silt matrix, In the coarse fraction (aggregate) the quartz is subangular to rounded. Alkaline and calcic feldspars were observed in both the aggregate and finer fractions (Robbins 1976, 2).

In other specimens the feldspar was heavily altered to illite and kaolinite clays. A

characteristic feature of this adobe shows most of its feldspar has chemically altered to clay. Organic matter, such as straw preserved in the finer fractions was found in all the adobe specimens. Only one of the soil specimens contained expansive or swelling clays, however there was no evidence of expansion cracks on the adobe specimens (Robbins 1976, 3). X-ray diffraction identified montmorillonite clays present. The team also found traces of calcium, sulfur, potassium, and chlorine (Brown et al. 1979, 34).10

¹⁰ The diffraction pattern of a small fraction of one of the soil samples was that of 14.7 Å. Some of the specimens expanded to 17 Å with glycolation.

Overall, the samples from Tumacácori contained a large amount of silt and clay, but the team suggested coarser fractions might have been added to achieve the desired proportion (Brown et al. 1979, 35). It was ultimately concluded that the presence of soluble salts found in the samples was due to rising ground water. The mix used to build the adobe for the church appeared to be composed of one part soil with four parts sand (Brown et al. 1979, 38). Mineralogical analysis also indicated the deterioration in the samples was not due to the presence of swelling clays.

Adobe samples were also analyzed in 1978 as requested by George Chambers using a variety of tests, such as x-ray diffraction of the clays. Overall, the clay fraction was low when compared to the sand and silt fractions, and the plasticity index was 5, indicative of low shrink-swell potential. According to Chambers, "(...) the soil should be acceptable as an unamended mud plaster (or mortar) but it would be advisable, if possible, to make a test application before acquisition" (Physical Science Technician 1978,

_	۱	
	1	
-		12

TABLE 8				
DENSITIES AND POROSITIES OF SELECTED ADOBE SAMPLES				
Sample designation	Density g/cc	Net pore volume cc/g	Average pore diameter μm	Measured total porosity* %
T010	2.56	0.233	4.2	37.4
To11	2.56	0.213	14.0	34.5
T012	2.60	0·199	2.5	33.9
T017	2.46	0.318	4.8	43·0
Fort Bowie	2.68	0.150	3.4	27.9
Escalante	2.80	0.227	2.8	38.2

Figure 14 Density of Tumacácori adobe samples. Source: Brown, Paul Wencil, Carl R. Robbins, and James R. Clifton. "Adobe. II: Factors Affecting the Durability of Adobe Structures." *Studies in Conservation* 24, no. 1 (1979): 35. These analyses confirm the probable source of the adobes as local soils given the geological context of Tumacacori.¹¹ The Santa Cruz River valley contains a considerable amount of alluvium, "which generally has a high permeability typical of sand and gravel deposits but which locally may be characterized by a predominance of fine sands and silts" (Percious 1978, 3).

2.2 Conditions and Factors Enabling Deterioration

The mission buildings sit atop a natural drainage system that travels from the Tumacácori Mountains to the Santa Cruz River (Moss 2008, 12). As a result, a vast quantity of soil moisture collects without any space to evaporate and the moisture is wicked up through the wall through rising damp.12

The largest earthquake documented on the southern geological Basin and Range Province in 1890 caused irreparable damage to the building's fabric. The 7.4 magnitude earthquake is said to have caused a large crack in the interior west wall of the mission church, as well as damaging the base of the façade columns and the pediment and choir loft (Moss 2008, 5). The nave roof collapsed a few years after it was fully abandoned in 1848, exposing the interior to outside elements; however the Sanctuary dome and

¹¹ A rotary drilling rig was used to dig twelve holes around the mission in 1970 with the purpose of determining the source of moisture causing rising damp in the nave and sacristy walls: "two distinct strata noted: the first at one foot below present ground surface (...). The top was a dark gray stratum; the bottom contained a zone of lime plaster fragment with fine, burnt clay fragments throughout. Damp soil extends about two feet lower than in Hole #1" (Richert memo 1970, 2).

¹² In the early 1950s, draining issues were repaired to some extent which reduced run-off and flooding, but overall subsurface water still continued to travel up the mission's west wall. By 1955 it was reported that the repair was apparently successful since there were no leaks in the roof or walls during Arizona's rainy season (Ringenbach 1955).

Sacristy barrel vault remained intact. The nave roof was later rebuilt in 1921 during Pinkley's stabilization efforts. In addition to seismic damage and exposure to weather for a significant number of years, vandalism has caused considerable damage.13

As early as the 1940s, the interior plaster had been found to be friable, quickly powdering, resulting in loss of plaster and painted decoration. Most of the plaster on the lower walls has been lost, presumably from rising damp and vandalism. The uppermost walls have also lost plaster as well as their original brick coping due to roof collapse. The plaster that remains to date, despite earlier preservation efforts, is largely detached from its adobe substrate in many areas, producing hollow sounds when tapped. Aside from this detachment, animal activity, mainly that of bats and birds, inside the building, has exacerbated conditions, causing plaster discoloration and in some instances, nesting had caused plaster fragments to fall (Clemensen 1977, 69; Steen and Gettens 1949).

By 1935, the church was reported as "unfloored" and dusty to which Engineer Gordon recommended flooring the nave using red colored cement to recreate the original red plaster floor (Woodward 1935, 3). For the most part, the walls and floors varied in their state of preservation. Some of the floors had a plaster finishg while others remained as packed adobe.

It is reported that from 1936 to 1939, both the interior and exterior conditions of the church worsened as indicated by severely detached and large missing areas of plaster

¹³ Swarms of treasure hunters tore walls and floors searching for hidden gold and jewels for more than 70 years. In addition to treasure hunters, other visitors would collect painted plaster as souvenirs, as well as inscribe their names on the plaster, which is documented today as graffiti.

due to the weather and the visiting public (NA- Report on Current Conditions of Each Historical Structure 1941, 1). Detachment of the interior lime plaster from the adobe was also due to poor bonding between both materials from the start. The exterior lime plaster has weathered differently due to varying exposure and inconsistency in the plaster composition and its subsequent repairs (Jackson to Gettens 1949).14

Water seeping through exterior cracks was another avenue allowing water to enter the interior. By 1946, it was reported the exterior plaster had continued to decay, particularly on the west and the north walls (Clemensen 1977, 72).¹⁵ Torrential storms in the summer of 1944 worsened conditions even more, when a portion of the remaining pilaster fell, painted plaster peeled from the capitals, and cracks continued expanding through the moldings and windows (Steen 1946, 2).¹⁶ A large exterior crack, measuring 12 feet long by ¾ inches wide, developed at the north end of the nave due to roof flashing failure.¹⁷ This allowed heavy rains to access the crack and fill the arch beneath with water (Jackson 1946, 1).¹⁸

¹⁴ The Superintended, Earl Jackson, sent fallen samples from both the exterior and interior plaster to Gettens. The sample of exterior plaster had previously fallen and retained a dark pigment, indicative of a decorative band. The interior plaster was much smaller in size, and Jackson indicated there were two layers, "...the last of which covered an older layer of bluish pigment. I presume this bluish pigment is typical of other bluish pigment which forms part of the existing surface decoration in the sanctuary" (Jackson to Gettens, 1949). This was included within a letter.

¹⁵ It was reported that Charlie Steen found the mission in "disturbing condition" after his February 1946 visit (Clemensen 1977, 72)

¹⁶ This was included in a memorandum prepared by Steen for the Associate Regional Director in March 5, 1946.

¹⁷ The crack was filled by Jackson with cement and gravel (Jackson 1946, 1).

¹⁸ This was included in a memorandum prepared by Earl Jackson, custodian, for the Regional Director Region Three, May 25, 1946.

Rutherford J. Gettens and Charlie Steen arrived at Tumacácori in 1949 to carefully analyze the finishes. They found the interior plaster to be flaking, particularly in the sanctuary dome. As part of a routine maintenance checkup in April of 1950, Jackson noted most of the original plaster had continued to weaken and fall. Two months later one square foot of plaster fell from the interior Sacristy wall (Clemensen 1977, 30). Jackson linked the recurring events to a roof leak, which he later sealed with a sand, lime, cement mortar. Between 1952 and 1953, heavy rains caused one square foot of the red painted plaster to fall, as well as a significant portion of the original plaster on the cemetery's east side (Clemensen 1977, 79).

The entire roof system was failing by 1974, and so it was recommended to remove the roofing and sheathing while still retaining the existing beams. Due to termite infestation, it was recommended the beams be termite-proofed (Herreras 1974).

Previous investigations by D. D. Evans in the 1970s concluded that the moisture gradient in the church's southwest corner was 3.4% near at the inside surface, 20.4% at a depth of 18 inches, and finally lowered to 15.4% at 28 inches (Percious 1978, 12). Chemical salt testing performed in 1977 also concluded soluble salts and calcium concentration was fairly high. Efflorescence on the plaster was causing the paint to peel from the wall (Yancey to Cattanach 1979).¹⁹ The ground water table was found to be at 25 feet (Percious 1978, 27).

¹⁹ This was included in a letter written by structural engineer, Charles Yancey, to George S. Cattanach, Chief of Division of Adobe and Stone Conservation on July 24, 1979.



Figure 16 Tumacácori Fringe Profile. Source: Percious, D.J. and M. Norvelle. Report on the Examination of Available Evidence on the Deterioration of the Walls of the Tumacacori Mission. Tucson, AZ: University of Arizona, 1978, 53.

Figure 15 Data collected on Boring B/3 by Marco Soil and Foundation Engineers. Source: Percious, D.J. and M. Norvelle. Report on the Examination of Available Evidence on the Deterioration of the Walls of the Tumacacori Mission. Tucson, AZ: University of Arizona, 1978, 64.

The moisture content at the pendentives was close to 10%. This reinforced the hypothesis the water was filtering from above the dome and roof and was migrating to both the exterior and interior surfaces of the dome, pendentives and wall (Yancey to Cattanach 1979). By January of 1977, there was additional loss of 5% painted plaster in the Sanctuary. By March of 1977, the plaster loss had extended to 35% (Davis to Hall, 1977, 1).20

²⁰ This was included in a letter written by John H. Davis to Dorothy Hall, State Historic Preservation Officer on March 25, 1977.



Figure 17 Sample Locator Map. Source: Brown, Paul Wencil, Carl R. Robbins, and James R. Clifton. "Adobe. II: Factors Affecting the Durability of Adobe Structures." Studies in Conservation 24, no. 1 (1979): 29.

Analysis and recommendations regarding moisture penetration were made on November 1976 by Dr. James Clifton and Erik Anderson of the National Bureau of Standards. The ideal moisture content for the adobe was calculated to be 1 - 3% (Clifton to Cattanach 1976, 2).²¹ Moisture measurements made by Anthony Crosby in 1985 showed the adobe at Tumacácori exceeded the optimum moisture content. All reiterated that the sources of the excess moisture in the mission were the ground water table located 25 feet deep with a pressure head of 5 feet, rain penetrating the exterior cement repair plaster, and rain entering the roof (Clifton to Cattanach 1976, 3).

²¹ This was included in a letter written by James Clifton to George Cattanach of Western Archeological Center on December 3, 1976. This letter includes a report prepared by Clifton.



Figure 18: Moisture Profiles of the West Nave Wall. Source: Crosby, Anthony. Historic Structure Report: Tumacacori National Monument Arizona, 1985: 105.

2.3 Conservation Treatment History at Tumacácori

As was common in many past preservation and restoration treatments of historic buildings, artificial or Portland cement became the preferred repair material, especially after the 1940s, and remained popular for decades. Waterproofing compounds as well as cementitious coatings exacerbated conditions. Because Portland cement is more



1889: Missing roof at the nave looking toward the sanctuary of the Tumacácori Mission.

Figure 19: Roskruge, George. *Nave of Tumacacori Mission looking toward choir loft and entrance*. 1889. Classification No: 266.2791, Negative No. 1060, U.S Department of the Interior, NPS, Coolidge, Arizona. **1919:** Before construction of new roof and before the pulpit was restored and plastered. A large area of plaster on the walls is missing. Floor cleared.

Figure 20 Collier, Marguerite L. *Church interior, nave, looking toward sanctuary.* 1919. Classification No: File 502. U.S. Department of the Interior, NPS, Coolidge, Arizona.

1945: Roof has been in place for around 25 years, floor has been restored as well.

Figure 21: Reed, Harry. *Interior of Tumacácori Mission Altar View. 1945*. Classification No: 266.2791. Negative No. 1/470, 915. U.S. Department of the Interior, NPS, Coolidge, Arizona.

impermeable than lime plaster or adobe, it traps and diverts moisture, causing erosion

beneath the plaster and around the edges of cement repairs. It also causes disintegration

of original adobe. Inserting metal mesh with layers of cement was also a popular
treatment solution to hold the lime plaster on exposed areas throughout the 1920s and

1940s.22



2.3.1 Conservation Treatments: 1920s to 1960s

Figure 22: Grouting white cement to lower edge of plaster. Source: Henderson, Sam R. Stabilization Report: Tumacacori National Monument 1972. Arizona Archaeological Center, Ruins Stabilization Unit: Tucson, AZ, 1972: 42.

The Mission's first major stabilization efforts were undertaken by Frank Pinkley during the 1920s (Caywood 1944). The work included rebuilding the pediment near the choir loft window, extensive re-plastering of the exterior north end of the building, and replacement of the missing nave roof (Clemensen 1977). As other conditions worsened due to exposure to the elements, The Civil Works Administration workmen repaired walls with missing plaster in 1934 by affixing a one-inch mesh, eighteen-gauge netting onto the wall using three-inch box nails (Clemensen 1977, 68). The mesh was then covered with a

²² Metal lash application mostly done by Earl Jackson following King's work.

cement mix of one part cement to four parts sand, and a final coating of lime plaster. Strips of metal lath plastered over exposed adobe was later applied in 1947 (Clemensen 1977, 75).

Initial treatments to deteriorating adobe in 1935 consisted of applying a 3% solution of NPSX, a custom formulated vinyl resin solution in acetone and toluene made for the National Park Service (Crosby 1985, 12). Two coats were sprayed with compressed air at 60 lbs pressure on the east side (exterior) of the south entrance, and on the Nave's interior, mostly spraying exposed adobe and colored plaster (Clemensen 1977, 69). Other recommendations for the decaying adobe was to nail tar paper to the frames, and later apply linseed oil to the canvas frame (Richey 1941, 1-2).

One inch wide cracks were commonly found along the Sacristy barrel vault, the roof gutters and downspouts. On July 9, 1941, the cracks were initially cleaned, widened and sealed by Louis Caywood, with a soluble black mastic solution that worked as a waterproofing coating. The mastic solution entered the moist cracks to form a tight bond with the lime plaster. Sand was used as an infill to account for shrinkage (Caywood, 1941).23 Oakum was also used along with mastic as a temporary solution to seal the top area of the cracks to prevent water penetration that was causing original plaster to detach. The treatment was later deemed satisfactory (Richey 1941).

²³ This was included in a memorandum prepared by Louis R. Caywood, custodian, for the Superintendent of the Southwestern National Monuments on July 11, 1941.

Three years later, cracks located on unplastered sections of the bell tower's north wall and east side of the mission were grouted with either a mixture of Stabinol[®], a proprietary asphalt emulsion stabilizer for adobe and clay roadbeds, and fortified soil or cement plaster (Clemensen 1977, 71).²⁴ The formulation for the Stabinol[®] solution consisted of 6 shovels of screened soil and 1.5 shovels of Stabinol (Richey 1941, 1).

Structural mortar formulations in 1946 consisted of 3 parts sand: 1 part cement: 1/3 part lime putty (soaked hydrated lime). The partially hydrated putty was slaked a day before application. Cement used to fill holes consisted of 3 parts sand: 1 part lime (Jackson 1951, 2).₂₅ Cement to cover surface cracks and losses in the original lime plaster were patched with a formulation of 3 parts sand: ³/₄ parts hydrated lime, and ¹/₄ part cement. The mix was applied using a pointing trowel while carefully pressing the mortar into the cracks. Once the plaster became dry, it was painted with a mixed paste consisting of 3 oz. burnt umber, 6 oz. yellow ochre and water which was added to 3 lbs. of processed lime putty, and further mixed with 2 gallons of water. Afterwards, the surface was washed with mud water and a tinge of red clay (Lancaster 1947, 1-2).₂₆

To stabilize the interior and exterior plaster, the lime mortar or cement mix was keyed properly unto the adobe. Grouting material often flowed into cracks and voids to achieve

²⁴ Stabinol was commonly used in the mid-1940s for soil stabilization. This chemical method was typically used to make soil waterproof.

²⁵ This was included in a memorandum prepared by Earl Jackson, Tumacácori Superintendent, for the General Superintendent of the Southwestern National Monuments on July 31, 1951.

²⁶ This was included in a memorandum prepared by James A. Lancaster, Archaeologist Aide, for the Regional Director Region Three on July 31, 1947.

proper binding. The weight of the grout or cement used was supposed to fall mostly on the adobe, not the plaster (Steen and Gettens 1949).

Regarding the interior painted decorations, the term "fresco" was deemed inappropriate as the decoration was originally applied to the dry plaster, also known as "secco". At one point, an employee sought to clean dirt of the painted decorations and the pigment was inadvertently removed. This led Earl Jackson to believe that the paint was applied to a dried surface and that the colors were mineral and not vegetable (Jackson 1948, 2).27

In 1947, the west exterior façade was patched with two coats of Horn Duocrex[®], a weather resistant sealant (1947 Jackson memo, 1).²⁸ ²⁹Duocrex was again used in 1958 to treat the fired adobe floors that were wearing due to visitor traffic. In 1948, heavy scratch coats of lime plaster were applied to the interior walls at ¾" thick. The finish coat was half the thickness of the scratch coat and was lightly floated to give the appearance of a thin layer of pure lime (Jackson 1948, 3).³⁰ Spackling paste, a gypsum plaster and glue putty, was used to patch interior cracks in 1949. Metal lath strips were once again nailed to the interior wall and plastered (Steen and Gettens 1949, 48).

²⁷ This was included in a memorandum prepared by Earl Jackson, Tumacácori Custodian, for the Regional Director Region Three on February 5, 1948. Subsequent analysis has confirmed the painting is indeed secco work.

²⁸ This was included in a memorandum prepared by Earl Jackson, Tumacácori Custodian, for the Regional Director Region Three on September 26, 1947.

²⁹ Duocrex[®], sold by the A.C.Horn Company at the time, was used as a sealant to make floors damage resistant.

³⁰ This was included in a memorandum prepared by Earl Jackson, Tumacácori Custodian, for the Regional Director Region Three on February 5, 1948.

Gettens formulated a polyvinyl acetate (PVA) lacquer solution, which was sprayed over the interior walls after thoroughly cleaning the plaster surfaces. A thinner coating was sprayed afterwards to facilitate the penetration of the lacquer into the plaster and to diminish any glossy appearance (Steen and Gettens 1949). Getten's formula consisted of:

Vinylite A, medium viscosity (PVA), 50 grams was mixed into solvent mixture of toluene 700ml, ethylene dichloride 200 ml, cellosolve (trade name for ethylene glycol monoethylether) 40 ml, cellosolve acetate 40 ml, cellosolve acetate 40 ml, and dibutylphthalate 2ml (Steen and Gettens 1949, 25).

The substance was used to keep plaster from chalking and to preserve the colors on the lime plaster. By 1950, the PVA treatment had been sprayed on the interior surface of the Sanctuary, Nave and Baptistry.

In 1951, Jackson introduced Dehydratine Number 2A[®], a colorless kerosene-based wax substance, from the A. C. Horn Company, to treat the original exterior plaster, but the treatment proved unsuccessful (Clemensen 1977, 76). Dehydratine 22 was later considered to seal the interior floors (Rigenbach 1958, 1).₃₁ Jackson's scratch coat and finish coat formulation was later used in April 1952 to reconstruct the plaster on the Mission's west exterior wall (Clemensen 1977, 76). The scratch coat was applied over galvanized metal lath.

Other usual repairs for loose plaster consisted of securing the edge of the interior plaster with nails and covering with plaster. In addition to the walls, this treatment was

³¹ This was included in a letter prepared by Ray Rigenbach to the Superintendent of the Fort Union National Monument on April 1958.

also applied on the vault. The overall thickness remained at 2" and the surface remained wet for two days. Soon after in March 1959, Joel Shiner was tasked to repair the mission's vaulted Sacristy roof. The treatment consisted of removing and replacing the plaster with a cement, perlite, lime and sand formulation. Metal lath strips were nailed to the roof before application. Once finished, the roof was covered with two coats of "latex paint and silicone." Shiner also mended eroded plaster edges with Rock Hard Putty® (Clemensen 1977, 80).32 33



Figure 23: A worker tapping a pin into the previously bored hole. The inserted pins were later grouted over. Source: Sudderth, W.W. The Nave and Bell Tower Stabilization Report 1973. Tumacacori National Monument. Ruins Stabilization Unit. Arizona Archaeological Center. Tucson, Arizona, 1974: 48.

³² Joel Shiner mainly patched the entrance arch with Rock Hard Putty. He also placed a large patch on the baptistery window sill.

³³ Rock Hard Putty has been on the market for more than 80 years. It's composed of Plaster of Paris, talc, dextrin, crystalline silica-quartz, and yellow iron oxide.

2.3.2 Conservation Treatments: 1970s

Mission San José de Tumacácori's foundations were exposed near the nave walls in August 1970. After replastering the foundation, an elastomeric membrane called Thiokol[®] was applied to the dry surface to function as a moisture barrier. A twenty millimeter thick polychloride vinyl liner was later adhered to both the east and west nave foundation. The apron was buried 15 feet from the mission (Clemesen 1977, 83). The vinyl apron was later removed in the summer of 1977 (Percious 1978, 2).

In 1972, the nave exterior was covered with a tinted wash and bonding agent solution composed of cement, mortar color, and Daraweld[®] plaster adhesive to eliminate the uneven "polka dot" wall appearance (Henderson 1972, 7).

Building inspections in the 1970s estimated that approximately 60%-75% of the interior and exterior plaster was not bonded to the adobe substrate (Herreras 1974, 3). The plaster was described as hollow and unsafe. Cement grouting with wire mesh strips to reattach the plaster to the substrate was performed on the interior walls of the nave. The 1970s also included the use of F-325 repellent and sealer[®] and epoxy grouting techniques, an irreversible method, to treat the plaster (Herreras 1974, 32).³⁴ Exterior repair plaster was made of lime-cement mortar while the interior plaster used lime mortar, and had a sand finish.

Major preservation efforts began in 1976 and carried through until 1982. In 1977, the NPS hired the Office of Arid Lands Studies (OALS) to investigate the mission's

³⁴ F 325 acrylic used to treat adobe with sealing compounds was known to change the color of the adobe. Such is the case of the observation building at Ft. Bowie (Herreras 1974, 32).

deteriorating wall condition, the source of wetting, and efflorescence. This was investigated through soil borings conducted by Marco Soil and Foundation Engineers, Inc. The base of the walls, particularly the southwest corner, appeared to be receiving the most moisture, which was identified as coming from the underlying soil. The roof and scuppers (canales had been repaired) and a vinyl apron had been installed at the base of the wall to channel drainage water.

Throughout testing the source of the moisture remained inconclusive, however the soil was further characterized. The report ruled that the water table was far too deep for capillary rise to occur at a significant level.

Particle-size distribution for all borings indicate poorly sorted and heterogeneous soils for the soil columns sampled by the borings; thus, the soil can be characterized as being dominated by fine-grained particle sizes (Percious 1978, 1).

The team also found that "the presence of a retarding layer, not greater than 10 feet deep" may be a factor contributing to a "soil moisture reservoir" (Percious 1978, 1).

Recommended treatments included sealing the adobe foundations and installing a rain gutter system to minimize a soil moisture reservoir close to the mission's foundations (Percious 1978, 33). The report also warned against using cement plaster as it is not as breathable as the adobe substrate. (Percious 1978, 3). It was later recommended that the Portland cement plaster repairs should be removed during the dry season and replaced with an adobe plaster. The cement was working as a vapor barrier trapping in moisture.



In addition to drilling holes through the cement plaster to determine its depth, holes were also drilled near the south end of the west nave wall to hasten drying of the moist adobe walls.

Figure 24: Holes drilled through cement plaster. Source: Chambers, George J. Tumacacori Preservation Project: Field Activities 1977, 1978, and 1979. Western Archeological Center, 1981, 13.

Prior to removal of the cement plaster, test holes were drilled into the exterior cement plaster to determine the depth of the patchwork. During the removal process, the team found the cement plaster attached to 1 inch mesh strips fixed to adobe walls with rusted large nails (Chambers 1981, 17). Other cement removed was described as pink cement with thicknesses ranging from ¼ to 1/2 inches. These were carefully removed with a pointing trowel and a builder's saw. Some of the cement removed from the exterior

dome was replaced with lime plaster 2 inches wide and whitewash was applied. The

whitewash proved to be an unsuccessful treatment, since it did not adhere to the surface (Miller 1985).35



Figure 25 Cement removal procedures on the exterior walls consisted of cutting on a grid pattern with builder's saws equipped with masonry blades. Source: Chambers, George J. Tumacacori Preservation Project: Field Activities 1977, 1978, and 1979. Western Archeological Center, 1981, 26.

The new lime plaster mix consisted of 1 part lime paste, 1.5 part fine soil, and 4 parts washed mortar sand. The coarser sand was used to match that of the original plaster. Lime mortars used a similar mix, except for 4 parts instead of 5 parts sand. "Pebble lime" (quicklime) was acquired from the Paul Lime Plant in Arizona, and slaked on site (Chambers 1981, 20-21).

To treat the exposed adobe undergoing surface erosion, mud plaster, lime plaster and a chemically altered mud plaster were considered. One of the mud plasters considered was made to simulate the original materials, especially in terms of porosity. Another plaster mix was made to have a greater capillary potential in order to draw

³⁵ This was presented by Hugh Miller in a news release article for the National Park Service on February 6, 1985.

moisture out of the walls. As a temporary measure, small holes that were found on the original lime undercoat of the exterior east nave wall were filled with mud mortar until plastering efforts could begin in 1978 (Champers 1981). To treat eroded areas, bowl shaped areas were cut back and were filled with small adobe bricks, 4 inches square by 10 inches long and mud mortar. Joints were recessed to provide keys for the plaster (Chambers 1981, 20). McHenry recommended a mix for mud plaster consisting of local soil tempered with ¼ volume of sand, and dry straw or grass to increase stiffness and adhesion. Floating was recommended at the end to fill possible shrinkage cracks (McHenry 1978, 12).

Cracks at the Mission San José have been monitored since 1977 using linear variable differential transformers (LVDTs), mechanical points, and additional leveling equipment. In addition to these methods, erosion and discoloration were monitored photographically (Crosby 1985). Crosby also tested samples of efflorescence and found that "most of the anionic salts were carbonates and sulfates, a significant amount of nitrates were also present. Chlorides were also present in a small percentage of the sample tests" (Crosby 1985, 73). The anionic salts did not show any direct correlation to the plaster decay.

The dome had major repairs done in 1979. The cement stucco, lime plaster and adobe were all removed, and 2.5 inches of lime plaster were applied to broken edges to match the original construction. Charles Yancey of Structural Engineering Group Center for Building Technology, expressed his concern to George Cattanach Jr. regarding the

adobe and stone conservation, writing:

The removal of the cement stucco which currently covers the exterior of the dome will have some effect on the interior dome conditions. If the stucco is replaced with a lime plaster the exterior heat fluctuations will affect the conditions on the interior more than at present. The difference may be insignificant but a slightly greater temperature fluctuation will probably result (Yancey to Cattanach 1979, 25).₃₆



All cement plaster was removed from the dome and replaced with lime plaster.

Figure 26 Major dome repair and replastering with lime plaster. Source: Chambers, George J. Tumacacori Preservation Project: Field Activities 1977, 1978, and 1979. Western Archeological Center, 1981, 52.

After the lime wash application, a traditional water repellent of two coats of modified white wash was applied to the dome consisting of 8 gallons of lime paste with 10 gallons of water, 12 pounds of table salt, 6 ounces of powdered alum in 4 gallons of hot water, 1 quart of molasses after 30 minutes mixing and finally 12 ounces of

³⁶ This was included in a letter written by structural engineer, Charles Yancey, to George S. Cattanach, Chief of Division of Adobe and Stone Conservation on July 24, 1979.

formaldehyde. One gallon of whitewash was expected to cover 200 square feet and last for two to three years (Chambers 1981, 45).

2.3.3 Conservation Treatments: 1980s

Several methods were used in the 1980s restoration campaign, such as Acryloid B-72, Rhoplex and PVA emulsions for plaster consolidation. These treatments were mostly carried out by NPS architect Tony Crosby. He found loose, flaking gypsum and organic stains on the dome as well, and also investigated several cracks that were later repaired. It was later concluded by Crosby that the rate of deterioration increased considerably after Gettens and Steen's conservation and restoration work in 1949. However, when the University of New Mexico compared 1949 images of the interior plaster and 2011, they essentially concluded that these had endured little loss over time (Porter et al. 2013).



Figure 27: Diagrams showing efflorescence formation. Source: Crosby, Anthony. Historic Structure Report: Tumacacori National Monument Arizona, 1985: 184.

B-72, an ethyl methacrylate-methyl acrylate copolymer was tested in the interior prior to application and was considered a more effective treatment during the testing period than barium hydroxide (Crosby 1985, 82). B-72 was also used at plaster edges to reattach gypsum wash. Missing plaster ground was reconstructed using a thick lime putty, calcium hydroxide and a fine sand at a lime-sand ratio of approximately 1:4 by volume (Crosby 1985). Other methods used during the stabilization of the plaster edges included the injecting of a PVA (polyvinyl acetate) emulsion, or methyl methacrylate fixative, behind detached and flaking plaster layers (Crosby 1985). Additional treatments for the interior plaster used unamended lime plaster, plain water, and tissue (Raithel 1982).37



Figure 28: Plaster showing remain of Acyrloid B-72 treatment. Source: Crosby, Anthony. Historic Structure Report: Tumacacori National Monument Arizona, 1985: 183.

PVA was also injected behind the lime plaster in order to attach it to the adobe

substrate. This method was not completely successful. The PVA emulsion was deemed

³⁷ This was included in a memorandum prepared by Kenneth Raithel, Jr., Assistant Manager, for the Regional Director of the Western Regional Office on December 6, 1982.

successful in certain areas, while in others the PVA penetrated through the surface layer (Crosby 1985, 65). Some recommended the use of nylon screws famously used on Italy's mural paintings (Raithel, 1982).₃₈ Other plaster edges were treated using a 2 to 5% solution of Rhoplex.

Painting conservators from the International Center for the Study of the Preservation and Restoration of Cultural Property (ICCROM) participated in the conservation of the Mission San José de Tumacácori during the summer of 1982, completing 60% of the work. The exterior dome plaster and the interior walls were damaged during the winter of 1982, which brought heavy rains followed by freezing night temperatures.

The plaster tends to reconsolidate as warmer and drier weather arrives in the spring, making it difficult to detect the damaged areas if an inspection is not made before drying takes place (...) torrential rains totaling 9.07 inches (two-thirds) the anticipated annual precipitation) turned the church exterior into a sponge (...) some of the interior conservation work was damages as a result of this entry of water (Sewell 1984, 1).³⁹

In August of 1985, the dome was repaired again using lime plaster painted with

several coats of a vinyl-acrylic-latex base exterior masonry solution called Vin-L-Tex®

(Unknown Tumacacori Mission Dome 1986, 2-3).40 The repairs made to the dome were

later questioned in 1985 by Hugh Miller as he was assessing the current condition. Miller

³⁸ This was included in a memorandum prepared by Kenneth Raithel, Jr., Assistant Manager, for the Regional Director of the Western Regional Office on December 6, 1982.

³⁹ This was included in a memorandum prepared by Joseph L. Sewell., Tumacácori Superintendent, for the SOAR, WACC and DSC offices on April 4, 1984.

⁴⁰ Author and origin of documents is unknown. The title of the document is "Tumacacori Mission Dome-Project Update History".

believed the waterproofing coating covered structural failures (Miller memo 1985).41 Burnt adobe bricks that were installed in 1979 on the mission's west ledge were also failing citing "poor firing". The edges of these bricks (exterior) deteriorated quickly and were allowing rainwater that fell on the ledge to run through the interface of the adobe wall and lime plaster (Chambers 1986, 1).42 Plaster and paintings were also found to have detached from the dome (Albert 1988).43

2.3.4 Conservation Treatments: 1990s to 2000s

During the 1990s, detached plaster was consolidated with injections of a 15% solution of Rhoplex[®], water and alcohol. Rhoplex alone is generally not recommended for this use since the detached layers require a gap filling material. For a stronger adhesion, a higher concentration of Rhoplex is required, but this would potentially stain the plaster (Porter et al. 2013, 8). Plaster reattachment treatments in 1992 also included injection grouting with an Italian commercial grout, Ledan[®], used to fill voids in masonry walls and to reattach layers.⁴⁴ Ledan[®] injection grouting lasted a week. Losses were covered with 1 part lime to 3 parts sand mortar.

⁴¹ This was included in a memorandum prepared by Henry Miller, Assistant Manager, for the Regional Director of the Western Regional Office on December 6, 1982.

⁴² This was included in a memorandum prepared by George J. Chambers, Cultural Resource Specialist, for the Chief of Division of Archeology on March 12, 1986.

⁴³ This was included in a memorandum prepared by Lewis S. Albert, Regional Director of the Western Region, for the Superintendent of Tumacacori and Chiricahua on November 2, 1988.

⁴⁴ Ledan[®] is a lime based ready-made mortar sometimes used for grouting cracks in painted plasters. Other variations of Ledan[®], such as Ledan TB1[®] is composed of Portand cement and calcium hydroxide as the binder. When used as a filler, Ledan TB1[®] is mostly composed of quartz powder and slate powder. Technical information is found on the Tecno Edile Toscana website.

In the early 2000s, ammonium caseinate was used for reattachment purposes. This treatment had poor gap filling properties and like Rhoplex[®], required surfaces to be in close contact. With time, ammonia casein solutions yellow and become brittle, insoluble and irreversible. Ethyl silicates were used as a consolidant as well. Resins and previous treatments were removed and cleaned with the use of acetone and ethanol. Efflorescence was treated using cellulose poultices with deionized water. Repairs were also made by Tohono Restoration using 3.5 parts lime to 1 parts sand (Porter et al. 2013, 9).

Other stabilization projects extending over the site took place in 2009. Dried mud was found running down the south interior window over on the sanctuary's west side. Evidence of cracks and water leaking was visible on the south side of the mission's exterior. To repair and fill the cracks, different mixes consisting of 3.5 parts sifted sand and 1 part lime were used (Unknown Sanctuary Leak Report 2009, 3).45

⁴⁵ Author and origin of documents is unknown. The title of the document is "Report on plaster cracking and leaks associated with the west sanctuary window", prepared July 6-8, 2009.





Figure 29: Repairing plaster on the exterior of the west sanctuary window, cornice and dome apron. Source: Tumacácori National Historic Park. Unknown Publisher. July 6-8, 2009: 3.

Figure 30: Report on Plaster Cracking and Leaks Associated with the West Sanctuary Window. Source: Tumacácori National Historic Park. Unknown Publisher. July 6-8, 2009: 3.

2.3.5 Conservation Treatments: 2010s to present

Heavy rains once again accelerated plaster loss in the dome interior in January 2010. The winter storm produced four inches of rain. There was roof leakage to be repaired as well as adobe failure, and partial collapse of the window around the Sanctuary. The total plaster area lost was 23.4m² around west the Sanctuary window. A few days after the storm, a scratch coat was applied on the east exterior Sacristy wall (Arendt 2010, 2). Three months later, major repairs were made on the upper west exterior Sanctuary wall. Bricks were replaced and were keyed to the existing wall by drilling into the adobe with a ½ masonry bit. The mixture used initially for repairs was considered to

be far too clay rich which began cracking and pulling away from the wall. To adjust this formulation, 3 parts clay: 2 parts sand and 1 part gravel were used (Arendt 2010, 7).

In 2011, the School of Architecture & Planning at the University of New Mexico were invited to perform an assessment and stabilization of the painted plasters in the Mission San José de Tumacácori. As observed in Figure 31, flaking gypsum layers were restored by using wet strength tissue adhered with 5% gelatin in water while larger fragments made use of crepeline in a 10% solution of B-72 in acetone (Porter et al. 2013, 50). Injection grouting in the dome was composed of 1 part hydrated hydraulic lime (NHL 3.5) and 1 part ceramic microspheres. The grout was injected into the voids using 10ml and 30ml syringes depending on the width of the void or crack. Setting time for the grout was about 10 minutes, and it was expected to cure for a year (Porter et al. 2013, 51). To stabilize the plaster edges, some were injected with a 5% solution of El Rey Superior 200 in distilled water. UNM also monitored environmental conditions in the dome, including temperature, relative humidity, and surface temperature.



Figure 32: Salt sample dome locations. Source: Bass and Porter. Assessment, Emergency Stabilization and Treatment of Painted Plasters in the Mission Church at Tumacacori National Historic Park, School of Architecture and Planning, 2012: 32.

Figure 31 Flaking yeso finishes on the plaster were treated using a 1982 technique, which consisted of a 5% solution of gelatin in warm water. Source: Bass and Porter. Assessment, Emergency Stabilization and Treatment of Painted Plasters in the Mission Church at Tumacacori National Historic Park, School of Architecture and Planning, 2012: 53.



Figure 33 : The poultice, composed of cellulose and distilled water, is being applied at Tumacácori to remove salts. Source: Bass and Porter. Assessment, Emergency Stabilization and Treatment of Painted Plasters in the Mission Church at Tumacacori National Historic Park, School of Architecture and Planning, 2012: 48.

Chapter 3: Grout Injection Used for Repair on Earthen Buildings

The purpose of this chapter is to provide an overview on injection repair grouts for earthen buildings, focusing especially on grouts composed of soil since less research has been done on the subject in comparison to air lime- and hydraulic lime-based grouts. Although the application of grouts for Tumacacori is nonstructural, i.e., for plaster reattachment, the literature on structural repairs has been included and discussed. Throughout the chapter, amended grouts, modified grouts, and stabilized grouts are used interchangeably, as well as unamended and unmodified grouts.

3.1 Brief History on Grout Injection Used for Repair on Earthen Buildings

Scientific research on injection grouting for conservation uses began with lime based grouts developed by ICCROM (Ferragni et al. 1984). A few years later, scientific testing of additives to improve grout performance commenced in the field (Ferragni et al. 1984). ICCROM researchers concluded that a moderately hydraulic lime and crushed brick (1 to 1 by volume ratio), and the addition of an acrylic emulsion to increase adhesion displayed good performance. Laboratory specifications were also defined for the ideal properties for grouts based on the use of hydraulic lime (Ferragni et al. 1984).

For nonstructural grout repairs, conservators studied in-situ stabilization such as plaster and mosaic reattachment using hydrated lime with casein, and later with PVAC, a synthetic resin emulsion (Ferragni et. al 1984). By 1986, a low-alkali hydraulic lime amended with PVAC, began to be used to reattach murals on earthen plaster by three ICCROM researchers: Schwartbaum, Na Songkhla, and Massari. It was not until 1990 that modified soil based grouts were proposed to fill cracks in adobe (Roselund, 1990). Following the ICCROM research, several commercial grouts became available after the 1990s. Although these products were easy to prepare, their compatibility with historic materials was not always guaranteed and they have been found to display excessive strength and high salt content (Bicer-Simsir et al. 2009).

Research at The Architectural Conservation Laboratory on hydraulic lime grouts formulated with fine sand, glass or ceramic microspheres, and hydraulic lime with and without the use of acrylic emulsions was begun in early 2000 with good results (Matero et al. 2003). Regardless of the extensive research on hydraulic lime based grouts in the past few years, there is still a need for further research.

3.2 Challenges with Grouting

Failure of structural and nonstructural grouts can be due to many factors. Significant causes include: shrinkage during drying cycles which causes the grout to loose adherence and therefore fail (Vargas et al. 2008) and stress fatigue and failure during hygric and thermal fluctuations where the grout and substrate meet (Simon and Geyer 2008), and If good chemical, physical and mechanical compatibility is not achieved between the grout and the plaster/adobe layers, moisture can enter the porous system, causing dissolution and re-crystallize soluble salts present in the plaster (Padovnik et al. 2016). Minor components in the grout formulation may be modified for testing purposes, but most researchers and scholars agree that reproducible testing instead of casedependent research is more important than the type of grout used (Simon and Geyer 2008, 260). One such problem applies to earthen grouts, as few formulations have been tested using standard testing. If such is the case for unamended earthen grouts for the use of structural repairs, less standardization of test methods has been developed specifically for non-structural grouts in general (Padovnik et al. 2016).

Laboratory specifications for hydraulic lime based grouts have been researched to a greater degree, tested and applied by ICCROM researchers and conservators in the field, and more recently by The Getty Conservation Institute. However, most ASTM standards focus on the preparation of cement mortars. The Getty publication suggests that more appropriate and relevant procedures be standardized for non-cementitious grouts (Bicer-Simisr et al. 2009).

3.3 Structural and Nonstructural Repair Grouts

Different grout formulations have been utilized to conserve earthen architecture. However, most of the research and application has focused on the structural use of grouts, such as repair of structural cracking from seismic activity threatening a building's stability (Vargas et al. 2008). In these instances, grout injections are used to re-establish the building's monolithic character and structural strength with minimal disruption of its surfaces. Less research has focused on nonstructural grout repair, such as reattaching delaminated layers using soil-based formulations. This loss of adhesion can occur between the substrate and the plaster layer, and in between plaster layers resulting in bulging, disintegration, delamination and detachment of the surfaces (Padovnik et al. 2016). Cave 85 of the Mogao Grottoes located in Dunhuang, is one such case where detached layers were treated using a soil based grouts, and egg whites as the additive.⁴⁶ The painted Buddhist caves of Mogao were suffering from separation and partial collapse of their painted earthen plasters from a rock support (Rickerby et al. 2004, 471).

Overall, grouts have repeatedly been used for earthen buildings to readhere detached layers by filling in voids, cavities and cracks in the plaster. What has changed in the past years is the type of binder, filler and additives used for grouting.

3.4 Amended and Unamended Earthen Grouts

Two types of earthen grouts used for structural repair are amended earthen grouts, using mineral (lime or cement) or polymer amendments (PVA) and unamended soil grouts based primarily on the clay found in the soil as the binder. While a significant portion of the research focuses on amended or modified earthen grouts, others have tested the use of unamended earthen grouts to restore strength on earthen structures (Vargas et al. 2008; Silva et al. 2012; Lourenco et al. 2013). Many have gravitated towards modified earthen grouts because by incorporating binders with lime, cement or gypsum, shrinkage can be controlled and higher strengths achieved.

⁴⁶ Deterioration of the Mogao Grottoes and conservation treatments were addressed by the Dunhuang Academy and the Getty Conservation Institute.

Past research has tested the application of soil grouts in adobe assemblies (Simon et al. 2008; Vargas et al. 2008; Padovnik et al. 2016).47 Assemblies made with unstabilized soil grouts, and soil and gypsum grouts proved to be stronger than those assemblies composed of lime or cement additives (Vargas et al. 2008). However promising unstabilized soil grouts might seem, not enough testing has been performed (Silvia et al. 2012).

In Simon's testing of amended grouts, the three different soil types researched were local adobe from a nearby site and two typical building soils that matched the case study's soil. Selective additives included: carboxy methylcellulose, Tylose MH 300, Klucel E, rabbit skin glue, glass microballoons, and quartz powder (Simon et al. 2008). Ultimately the best performing amended grout contained local adobe soil with a particle size of 150 μ m, quartz, powder and Tylose additives.48 49

Other researchers, such as Silva, Schueremans, Oliveira, Dekinng and Gyssels, tested both modified (amended) and unmodified (unamended) grouts for repairing structural cracks using amended soils (Silva et al, 2012). One grout consisted of earth, silica sand, fly ash and hydrated lime. Another modified mud grout consisted of clay

⁴⁷ The grout was tested by replicating the substrate, in many instances adobe, and arranging it in a sandwich like assembly joined together by the grout. In some of these assemblies, sand was clumped on the wet mockups and removed once dry to simulate cavities. Afterwards, grout was injected and the mock-ups were cut in order to analyze the degree of filling and shrinkage cracks (Simon et al. 2008). ⁴⁸ Tylose MH 300, or methyl-hydroxyethyl cellose with standard etherification, is a water-soluble non-ionic polymer. It is typically used as an additive to provide water retention, adequate binding, thickening and colloid properties.

⁴⁹ Infrared thermography imaging, was used to confirm complete gap filling.

powder, lime and wallpaper paste. Overall, the modified grouts were more successful than the unmodified grouts, which presented excessive shrinkage (Silvia et al. 2012).

A year later, Silva, Oliveira, Lourenco, Schueremans and Miranda tested two grouts: an "artificial" soil grout composed of kaolin and limestone powder, and a "natural" soil grout composed of soil with a maximum particle size of 0.18mm (No.80 sieve) and limestone powder (Silva et al. 2013, 2-5). Both grouts included the addition of sodium hexametaphosphate to improve fluidity. Overall, the "natural" soil grout (B) had better adhesion, had a better recovery rate (66%) for shear strength, and was stronger than the artificial grout.



Figure 34: Vargas testing for tensile strength on adobe sandwiches. Source: An Experimental Study of the Use of Soil-Based Grouts for the Repair of Historic Earthen Walls and a Case Study of an Early Period Buddhist Monastery. Terra 2008: The 10th International Conference on the Study and Conservation of Earthen Architectural Heritage. The Getty Conservation Institute and the Mali Ministry of Culture, 1096.

Other scholars, such as Vargas et al. (2008) tested modified and unmodified mud

grouts and determined the latter had a better adhesion capacity as well, recommending the use of unmodified grouts over modified grouts. Modified grouts are said to be extremely stiff which may not satisfy the mechanical compatibility of lime and adobe plasters. Additionally, unmodified earthen grouts have proven to provide better adhesion in adobe walls; their drying shrinkage may not affect adhesion to the substrate (Lourenco et al. 2013).

3.5 Earthen Grout Design

Achieving compatibility of the grout with the original adherents is a difficult task, since often the components are of more than one material, i.e., lime plasters on adobe. The commonly used binder, hydraulic lime, is often used due to its compatibility with original lime-based materials, but it can also be extremely strong.⁵⁰ ⁵¹ In the case of Tumacácori, the lime plaster has detached due to the deterioration of the adobe at the interface with the plaster. In order to compensate for this failure due to adobe deterioration, the decision was made to look at soil-based grouts as both a material and method of remedial repair. Local naturally occurring soils rather than formulated artificial soils were only considered in order to satisfy the larger requirement of practicality of material access and the concept of sustainability as defined by "local solutions" to conservation problems (Matero, personal communication).

Required properties for designing soil grouts, such as strength, fresh state rheology and stability, chemical stability, and microstructure, are determined by the

⁵⁰ With lime based grouts, properties achieved depend on the chosen binder: such as hydrated lime or hydraulic lime.

⁵¹ Additionally, matching the composition of original plasters may pose a problem with injection grouts, since the same composition does not guarantee well working properties, such as flow and it may also introduce additional damage and durability problems (Bicer-Simisr, 2009; Lourenco et al. 2013).

characteristics of the soil use. Adjusting the composition in order to improve some properties may alter or jeopardize other properties (Silva et al. 2012). Compatibility does not always translate into using the same materials as the adherends since a grout is delivered in a manner very different from the original construction assembly or process. "...the same materials cannot be automatically transferred to a grout mixture, which needs to be easily injected, and substitute materials may need to be added to enhance grout performance" (Rickerby et al. 2004, 472).

3.5.1 Methodology and Testing Schedule

The first step to design grouts is to define the performance requirements for the grout. These can be separated into mechanical behavior and durability of the injected substance requirements. Mechanical behavior requirements means that a grout must display good injectability and bonding properties in order to flow through small cracks and voids. The mechanical properties sought for the grout depend on the structure's level of deterioration or damage, as this will decide what the behavior of the injected structure should be (Silva et al. 2009). An overall design methodology for earthen grout injections does not yet exist. However, many reference Griffin's work in 1997, 1999 and 2004, as a means to developing one.



Figure 35: Grouting delaminated earth plasters at Cave 85. Source: Implementation of Grouting and Salts-Reduction Treatments at Cave 95 Wall Paintings. In Conservation of Ancient Sites on the Silk Road, Second International Conference on the Conservation of Grotto Sites (Rickerby et al. 2008, 483).

For the Dunhuang, Cave 85 Project, working properties and artificial aging were tested.⁵² Performance characteristics included the following: minimal volume change, similar water vapor permeability to plaster, low density, retreatibility, good adhesion, and similar mechanical strength to plaster (Rickerby 2004, 474).⁵³ Working properties, while the grout is in a liquid state, included: injectability, viscosity, setting time, low toxicity, slow water release, and minimal water content (Rickerby et al. 2004, 474).⁵⁴

⁵² Characterization of the mud collected from the Daquan River was performed, as well as characterization on the plaster samples. These samples were found to be minerologically identical, thus insuring compatibility. The riverbed mud was used as the grout binder. The filler materials were preselected based on existing deficiencies of the earth binder.

⁵³ Like Tumacácori, a grout with a very low wet and dry density was required. Similar to Tumacácori, Cave 85's plaster had been previously subjected to several repair attempts, such as pinning which concentrated stresses on the weakened plaster layers.

⁵⁴ More than eighty grout formulations were preliminarily evaluated, while only a few were subjected to full testing.

3.5.2 Earthen Grout Properties

Fluids, such as grouts, exhibit time dependent change in viscosity, known as thixotropy. The longer the grout is subjected to shear stress, the lower its viscosity, which is considered a desirable property. An increase in an earthen grout's viscosity during mixing may occur when formulated without additives. On the other hand, modified grouts with additives decrease in viscosity during mixing time, requiring up to three days to recuperate. This in turn implies that aside from additives, stirring plays an important role in acquiring a certain viscosity level, as agitating the grout mix alters the grout's suspension (Simon, 2008).

Soaking the grout can also decrease the viscosity, but stirring it speeds up its production. According to Simon, stable suspensions can only be acquired with grain sizes measuring 125 μ m (Simon and Geyer 2008, 263). Mixing for long periods of time can help achieve lower viscosity and good fluidity for modified grouts. Modified earthen grouts and soil grouts made with a very high water content attain adequate fluidity, but the fluidity also decreases viscosity and the likelihood of excessive drying shrinkage on the hardened grout increases (Simon et al. 2008; Silva et al. 2012).

Overall, a high amount of clay increases chances of shrinkage and cracking therefore a careful selection of the soil should have an adequate ratio of clay/silt and sand content (Simon, 2008). The most common clay minerals are kaolinite, illite and montmorillonite. Reducing the amount of clay in an earthen grout reduces the demand for water in the mix (Silva et al. 2012). Researchers have been able to reduce the amount of water needed by incorporating kaolin suspensions with limestone powder (Silva et al. 2012). Others, such as Iyer, have determined the ideal soil grout has low viscosity and high homogeneity, 2.5:1 solid to liquid ratio. Also, stable clays, such as kaolinite, do not swell in the presence of water and have a low ion fixing capacity (Iyer 2014).

Another frequent method to reduce shrinkage is to incorporate a dispersion agent, such as sodium hexametaphosphate, into the water (Lourenco et al. 2013). Some researchers, have expressed concern when employing water as a fluidizer in an earthen grout formulations. The latter may result in serious implications, such as the activation of soluble ions in an already salt contaminated plaster (Rickerby et al. 2004, 471).

Regarding the clay content in the mix of the grout, some results have demonstrated that the flexural and compressive strength that the grout can achieve depends on a higher clay content. Basically, the rheological behavior of the soil grout is dependent upon the colloid behavior of the clay particles. A higher clay content in the grout means a higher fluidity, drying shrinkage and swelling, but good binding. However, the fluidity of the grout should be limited. Fluidity is also necessary to develop adhesion and strength in the grout, so a careful balance of the clay content should be achieved for a successful grout (Silva et al. 2012; Silva et al. 2009).

It's also not ideal for a potential grout to have a low solid fraction, as this would result in high shrinkage. It is also important to add coarse aggregate in order to create an interlocking effect and increase cohesive strength within the grout. Conversely, aiming for a larger volumetric solid fraction would create a grout with poor injectability properties, making its injection at low pressure difficult (Silvia et al. 2012).

56



Figure 36: Figure 34: Grouting of west window plaster at Tumacácori. Cotton was used to catch overflows and prevent further detachment due to any pressure exerted by the grout. A solution of 1 part NHL 3.5: 1 part ceramic microspheres was used. Source: Assessment, Emergency Stabilization and Treatment of Painted Plasters in the Mission Church at Tumacacori National Historic Park, School of Architecture and Planning (Bass and Porter, 49).

Fillers used can help to reduce shrinkage numbers and control the grout's mechanical strength. For the dome at Tumacacori, Bass and Porter chose a grout mix containing one part hydrated hydraulic lime (NHL 3.5) and one part ceramic miscrospheres by volume (Bass et al. 2013, 50).55 Glass microspheres have also been used as lightweight fillers for earthen grout formulations. While exhibiting a low wet and dry densities, and promoting a good viscosity and injetability, their spherical shape, reduces the grout's internal cohesion. The greater the amount of glass microspheres, the weaker the solution (Rickerby et al. 2004, 475).

⁵⁵ The grout mixture was designed to act as a void filler and as an adhesive for the detached plaster layer; they have a low water content which can minimize shrinkage but are fluid enough to flow. These can also set in oxygen deprived conditions within the walls, have a water vapor transmission rate similar to the existing material, and can achieve a sufficient bond strength or shear strength while being lightweight at the same time (Bass and Porter. 2012).

Additives and extended mixing is not only successful in decreasing viscosity levels and achieving good flow but also increasing grout strength, such as the use of methylcellulose additives in earthen grouts. Tylose is another additive that has proven to increase pull-off strength (Simon et al. 2008).

For paint reattachments, compatible earthen grout with additives such as egg whites have been successfully employed. The use of egg white is described by Griffin's research as a strong adhesive that improved injectability and viscosity, augmenting rather than substituting for clay binding properties" (Rickerby et al. 2004, 476;Griffin 1999, 24–31, 39–42, 44–45, 51–60, 63–65). The egg white also reduces the amount of water released from the grout.⁵⁶

However, the use of additives for strengthening purposes is refuted by other scholars such as Vargas. His testing concluded that assemblies repaired with unamended grouts were 20% more likely to be stronger than the original samples. In this instance, additives were not necessary for the grout to recover the strength of the cracks. Some grouts have been formulated with PUCP soil and soil stabilized with gypsum. (Vargas et al., 2008).

⁵⁶ Egg white was whisked and introduced into the mixture, as an air-entraining foam.

Grout Component	Function	Potential Disadvantages
Binder earth	bind the solid components of the grout mixture	• high wet and dry densities
		 long drying time
		high shrinkage
Fluidizer water	activate clay component	• damage to water-sensitive/soluble plasters and
		paint materials
		activates salts
Filler(s)	• provide bulk and enhance internal cohesion	may compromise compatibility
	 counter shrinkage 	• may result in too low or too high strength
	 improve porosity and water vapor permeability 	
	 reduce density 	
	 improve viscosity (injectability) 	
	increase drying rate	
Additive(s)	modify grout properties further (optional)	may compromise compatibility

Figure 37: Potential disadvantages of earthen grout components. Source: Development and Testing of the Grouting and Soluble-Salts Reduction Treatments of Cave 85 Wall Paintings. In Conservation of Ancient Sites on the Silk Road, Second International Conference on the Conservation of Grotto Sites (Rickerby et al. 2008, 473).

Durability of the injected structure is achieved with intimate contact between the grout and the wall. The use of earthen grouts implies the use of raw materials that closely resemble the plaster's support on the substrate. Bonding is also key for a successful grout repair selection, as it limits unwanted chemical reactions (Silvia et al. 2009). In particular, well-designed earthen grouts should be fluid enough, exhibit low shrinkage and strong bond equal to its own cohesive strength for successful repair (lyer, 2014).

3.6 Conclusive Remarks

Both hydraulic lime grouts and earthen grouts have proven successful depending on the specific grout mix. Preference for hydraulic lime grouts is undoubtedly due to the fact that hydraulic lime is readably available in the market as a binder as well as in prepared commercial conservation grouts. Another aspect contributing to the popularity of lime based grouts is the perceived drawbacks of soil based grouts, such as excessive shrinkage and low strength, which have limited their use as a binder for conservation purposes.

Where lime based grouts have been employed, some have resulted in poor adhesion between the lime and earthen materials (Griffin 1999, 13, 60). Silvia et al. (2012) argue that adding hydraulic lime as a binder can greatly increase the grout's modulus of elasticity making the grout less compatible to the existing material. Grouting with hydraulic lime as an additive is not always compatible with the shrinkage and swelling behavior of earthen structures as the bond between the grout and the existing adherend may be weakened by the water introduced. When water is introduced, the water in the grout can become absorbed by the wall, shrinking the grout after drying (Silva et al. 2009).

Soil-based grouts instead must be formulated and tested for each case when using locally sourced materials; however these can display true compatibility when used with locally sourced adobe substrates. Material compatibility should be possible by developing an earthen grout based on local soil sources that match those sources used for construction such as the adobe. If local soil grouts can be formulated that display good injectibility and low shrinkage, their solid state should display similar strength, hardness, abrasion resistance, and water vapor transport values as the adobe itself. (Simon et al. 2008; Vargas et al. 2008; Silvia et al. 2012).

Chapter 4: Methodology

Table 1: Methodology Schedule. Source: Declet 2017.

4.1 Sample Retrieval and Material Characterization

The first portion of the research project involved analysis of the current conditions

of the historic painted lime plaster located in the interior nave of the Mission San José de

Tumacácori. A recent condition assessment of the interior plasters of the mission church

performed by the University of Arizona, revealed detachment and cracking of the nave
and lower sanctuary (UA 2011). Three soils from local sources used on site for repair were sampled with the help of Alex Lim, Exhibit Specialist and tested at the ACL. 57



Figure 38: Soil retrieval location identification in Nogales, Arizona. Source: Declet 2017.

Once back at the laboratory, Phase 1 focused on material characterization of the

local soil samples. Overall, the three soil types, adobe, mortar, and plaster were collected.

The sample schedule for material characterization of both adobe and soils is listed below.

⁵⁷ The local soils types selected at Tumacácori National Historical Park. Soil A and Soil B came from manufacturer Tucson Pioneer Soil. Soil E came from manufacturer Rio Rico Topsoil.

Material Characterization Testing	Standard/ Reference	Minimum Quantity
Particle (grain) size distribution	ASTM C136-06	90g
Plastic Limit, Liquid limit, and plasticity index of soil	ASTM 4318	20g (Plastic); 100g (Liquid)
Combined dry/wet sieving	ASTM D422; ASTM D1140; Nityaa Iyer 2014 (P.36)	1 <i>5</i> 0g
pH of Soil-Acid Solubility	ASTM D4972-13	10g (in water); 10g (in calcium chloride)
Organic Content Analysis	ASTM D2974-14	50g
Semi-Quantitative Salt Analysis	Merck Strips	5g
Methyl blue adsorption test	AFNOR NF D 94-068-1998; Nityaa Iyer 2014 (p.57)	60g

Table 2: Testing Schedule for Characterization of soil types and original adobe. Source: Declet 2017.

4.2 Adobe and Soil Characterization

Original adobe samples TUMA S-7 and TUMA S-11 taken from the east nave wall were selected for characterization. This included performing several tests on the adobe samples in order to characterize the soil used to prepare the adobe and compare these results to the local soil samples collected. The samples were prepared first by crushing with a mortar and pestle. Afterwards a portion of the 463 g adobe sample was oven dried while a small amount was left to air dry in preparation for the Plastic and Liquid Limit Test and Methylene Blue Test. Soils A, B and E were already in soil form so no additional preparation aside from oven drying was necessary. These were subjected to the same characterization tests as the adobe.

The soil selected to make the grout should be similar to and therefore compatible with the original earthen substrate in order to achieve similar strength, water vapor permeability rates, and adhesion strength. The soil type's microstructure and rheology is analyzed through the following tests in order to do so. The soil will then compose the grout's binder which will be subjected to several tests. The optimal grout properties were organized within a test matrix. These included good distribution ratio of sand, silt and clay content in order to control shrinkage as well as pass through the desired injection orifice.

• Particle Size Distribution

The soil was classified by grain size, shape and sorting which define the soil's microstructure. Sieving followed ASTM C136-06. Using the percentage retained on each sieve, the soil's grain size distribution or granulometry were identified as either coarse sand (passing No.4 and retained on No.10), medium sand (passing No.10 and retained on No.40 sieve), fine sand (passing No.40 and retained on No.200 sieve) and silt and clay fines (retained in pan).



Figure 39: The three soil types (A, B, and E) and the original adobe were sieved and placed on weighing boats. Source: Declet 2017.

• Combined Dry and Wet Sieving

In addition to the typical sieving method, Combined Dry and Wet Sieving was also performed following ASTM D422, with the use of a dispersion agent, 4% sodium hexametaphosphate (HMP) (40g/L) and deionized water. It is typical of fine particles to agglomerate and adhere to coarser particles, which occurred in the particle distribution (sieving) test. HMP prevents particles from flocculating during the particle size determination test. A viscous material is semifluid in consistency due to internal friction. When added to scattered particles in suspension, there is a reduction in viscosity due to the neutralization of the forces of attraction.



Figure 40: Combined wet/ dry sieving procedure. Source: Declet 2017.



Figure 41: Before and after of the soil sedimentation. Source: Declet 2017.

• Plastic limit, Liquid limit, and Plasticity Index of soil

The Plastic and Liquid limits are used to characterize and classify soils based on the relationship between the soil and water content. The test followed ASTM 4318. The properties of clay depend on the amount of water present. The higher the water content, the more the soil flows as a liquid. As the water content decreases, the soil becomes a sticky paste, described as plastic. The plasticity index indicates a clay's strength when subject to changing soil conditions. Both the liquid limit and the plastic limit show the relative consistency or liquid index. The liquid limit of soils increases when the soil is subjected to constant wetting and drying cycles. The amount of increase indicates a measure of the soil's susceptibility to weathering.



Figure 42: Plastic limit process (left) of rolling soil into a thin 3mm thread. The liquid limit test (right) was also tested using the Casagrande device. Source: Declet 2017.

• pH of Soil-Acid Solubility

The soil pH is measured depending on its acidity and alkalinity. By measuring the concentration of hydrogen ions and the material's activity, the pH indicates the solubility of soil minerals and the mobility of ions within the soil. Following ASTM D4972-13, the measurement of the pH was done in both a water solution and a calcium chloride solution, and made use of a potentiometer for more accurate results.



Figure 43: After an hour of combining the soil and the solutions, pH readings were taken. Source: Declet 2017.

• Organic Content Analysis

The organic content is expressed as a percentage of the mass of the soil's organic matter to the mass of the dry soil solids. ASTM D2874-14 was used as the standard. It is used to determine the organic matter, the moisture content and any ash content present. Soil structure, water retention capacity, compressibility and shear strength are some properties influenced by the organic content in a given soil. Typically, organic material can be added to accelerate the drying process, to control cracking or to increase the formulation's tensile strength. For these reasons, a substantial amount of organic matter is in some cases beneficial.



Figure 44: The total organic content was calculated by subtracting the second and first weight loss. Source: Declet 2017.

• Semi-quantitative Salt Analysis

The presence of soluble salts in the grout could introduce damaging salts into the adherends that could later crystallize and damage the plaster and adobe. Semiquantitative Merck strips were used to detect the presence of soluble salts such as chloride (Cl-), nitrate (NO₃-) and sulfate (SO₄²).



Figure 45: Using a dropper, a few drops of deionized water were dropped over a small amount of soil. This mix was later stirred, and the Merck strip was placed in the solution. Source: Declet 2017.



Figure 46: Using a dropper, a few drops of deionized water were dropped over a small amount of soil. This mix was later stirred, and the Merck strip was placed in the solution. Source: Declet 2017.

• Methylene Blue Adsorption test

Most clays found in soils are stable, others are swelling and expansive. The original spot test is based on AFNOR NF P 94-068-1998 and ASTM C1777, but for this procedure, lyer's adaptation for soil grouts was employed (lyer 2014, 57). To detect the presence of these clays and quantify the cation exchange and ionic absorption capacity of the soils, increasing amounts of Methylene blue trihydrate were added to a liquid soil solution (Türköz and Tosum 2010, 1782). This test determines the amount of methylene blue necessary to cover the surface area of clay particles in the soil.



Figure 47: After preparing the 10g/L methylene blue solution, 5ml doses of methylene blue trihydrate were added and with a glass rod, a drop is placed onto filter paper.

4.2.1 Summary of Results

Particle Size Distribution •

The soil gradation results were grouped into coarse sand, medium sand, fine sand and fines (silts and clays).58 The results show all three soils were similar in grain size



distribution.59

Table 3: Soil Profile for Soil Types and Original Adobe. Source: Declet 2017.

⁵⁸ Sand particles between 0.02 mm and 2 mm (20 microns and 2000 microns) indicate the clay will have less porosity, increasing its compressive strength.

⁵⁹ Soil A has the largest amount of fine sand (49.71%) and silt and clay (13.07%). Soil B follows with 46.69% fine sand and 10.64% silt and clay Soil E possesses 48.68% fine sand and 7.71% clay and silt.



Table 4: Granulometry of soil types and original adobe. Source: Declet 2017.



Table 5: Particle Gradation. Source: Declet 2017.



Soil B- Sieve No.8, 5x magnification

Soil A- Sieve No.30, 5x magnification

Soil E- Sieve No.30, 10x magnification

Figure 48: Fine particles attached to the coarse particles of the soil types. Source: Declet 2017.

• Combined Dry and Wet Sieving

The Combined dry/wet sieving test required the use of a dispersing agent (sodium hexametaphosphate) which help disperse the particles, which once fully dried, were sieved.⁶⁰ The results for the "Dry Sieving" portion of the combined dry/wet sieving show Soil B had the largest amount of fine sand and fines, followed by Soil A and Soil E.



Table 6: Combined Dry Sieving Soil Profile. Source: Declet 2017.

⁶⁰ The results show Soil B has the largest amount of Fine sand (55.61%) and Fines (22.95%) which would be better for the grout. Soil A follows with 45.94% Fine Sand and 25.22% Fines. Soil E is last with 47.43% Fine Sand and 17.16% Fine Sand.



Table 7: Combined Dry Sieving Particle Gradation for soil types and original adobe. Source: Declet 2017.



Table 8: Source: Amount of particles that did and didn't pass through Sieve no.200. Declet 2017.

The specific gravity of the suspension (of the particles that pass through sieve no.200) is based on Stokes Law, which states that the terminal velocity is proportional to the square of the particle diameter. Larger particles in suspension will settle quicker than smaller particles. Therefore, the longer the smaller fines take to settle, the higher the hydrometer reading. Soil E started with the highest number, and has settled at a slightly different rate. See Appendix B for overall results.



Table 9: Hydrometer Readings for soil types and original adobe. Series 1: Soil A, Series 2: Soil B, Series C: Soil E, andSeries 4: Original Adobe. Source: Declet 2017.

Plastic limit, Liquid limit, and plasticity index of soil

Any optimal grout, and especially soil-based grouts, should not display excessive

shrinkage. A soil with a high amount of clay increases chances of shrinkage and cracking.

For these reasons, the selected soil must have a balanced ratio of clay, silt and sand.

Grouts with a reduced amount of clay need less water to achieve fluidity.

The Plasticity Index relies on the amount of clay present in the soil, indicating the fineness of the soil and its capacity to change form without altering its volume. A high Plasticity index indicates an excess of clay or colloids, which may become too expansive. Soils with a low Plasticity Index are very sensitive to changing soil mass, meaning that a very small amount of water will cause the soil to change from a semi-solid to liquid form. Soils with a plasticity index near 16% have the best compaction characteristics, meaning the moisture content in the soils allows it to be compacted with the least effort. All of the soils tested had a plasticity index ranging from 14 to 17.

The soils tested did not have a high plasticity index. Soil E had the highest plasticity index out of the soils tested with Soil B following closely behind. Soil A had a plasticity between 11 and 16, indicative of clay loam (medium plasticity).⁶¹ Soil B had a plasticity index of 14 to 18, also characteristic of a clay loam (medium plasticity). Soil E had a higher plasticity index of 16 to 19 but still falls under the category of a clay loam (medium plasticity). However, the original adobe sample proved to have very low plasticity, characteristic of a high sand and silt content with very little clay.

Soil E also had a higher liquid limit than the rest of the soils, followed by Soil B. In terms of the soil's activity, which is calculated taking the ratio of the PI to the percentage of smaller clay particles, all of the soils were less than 0.75, meaning the clay in these soils is inactive. The coefficient of activity means that the clay has a small volume change,

⁶¹ The soils fall under USC group CL, a fine grained soil described as inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays.

suitable for grout formulation. Typical values of inactive soils are: Kaolinite: Activity of 0.3-0.5, similar to the adobe soil (0.31); Halloysite (hydrated): Activity of 0.1-0.2 similar to Soil A (0.25), Soil B (0.21) and Soil E (0.21).

Compressibility is based on the liquid limit of soils that are mostly composed of silt and clay. Soil A has a 29-30 LL (low compressibility), Soil B has a 29-33 LL (low/medium compressibility), and Soil E has a 32-36 LL (medium compressibility).

As seen in the Graph for Soil Plasticity, soils above line A are inorganic clays of low, medium, or high plasticity. While soils below line A are inorganic soils of varying compressibility, organic silts and clays. Since the adobe tested from Tumacacori has a plasticity index lower than 10 and a liquid limit lower than 23%, this soil is termed



Table 10: Plasticity soil results for soil types and original adobe. Source: Declet 2017.

cohesionless. On the contrary, the soils tested for the grout have a plasticity index higher than 10% and a 30% LL. This makes them well suited for grout.



Table 11: Liquid Limit Test for soil types and original adobe. Source: Declet 2017.

• pH of Soil-Acid Solubility

Soil B (8.84) and Soil E (8.71) are strongly alkaline while Soil A (8.31) is slightly alkaline. The high pH can affect the stability of clay minerals since it can lead to the formation of stable clay minerals in suspension. On the contrary, a low pH can promote clay flocculation. All the soils scored close to each other, so no definite selection was made based on this test.

			pH reading	Temperature	
	pH reading	Temperature	Soil+Calcium	Soil+Calcium	
Samples	Soil+Water	Soil+Water (°C)	Chloride	Chloride (°C)	
ADOBE	7.8	16.3	6.25		16.6
SOIL A	8.31	16.3	6.4		16.3
SOIL B	8.84	16.3	6.78		16.4
SOIL E	8.71	16.3	6.83		16.5

Table 12: Soil pH results. Source: Declet 2017.

• Organic Content Analysis

Soil E had the highest organic content with a 5.16%, which is beneficial for grout formulation since it can prevent formation of micro cracks within the grout. Soil A and B followed with a weight loss of around 2.6%.

Samples	Sample Weight before oven (g)	Sample Weight after 110°C (g)	Sample Weight after 220°C (g)	Total Weight Loss in percent	% Weight Loss from Water and CO2	% Weight Loss from Organic Material
ADOBE	73.55	72.56	72.15	3.25	1.35	1.90
SOIL A	103.09	101.13	100.33	4.58	1.90	2.68
SOIL B	104.35	102.51	101.7	4.30	1.76	2.54
SOIL E	103.78	99.19	98.43	9.58	4.42	5.16

Table 13: Organic Content Results. Source: Declet 2017.

• Semi-quantitative Salt Analysis

All three soils possessed very low chloride, nitrate, and sulfate content.

Samples	Chloride Cl-	Nitrate NO ₃ -	Sulfate SO ₄ ² -
ADOBE	0 mg/L (LOW)	+ 50 mg/L (LOW-MED)	<200 mg/L (LOW)
SOIL A	0 mg/L (LOW)	+ 25 mg/L (LOW)	<200 mg/L (LOW)
SOIL B	0 mg/L (LOW)	+ 25 mg/L (LOW)	<200 mg/L (LOW)
SOIL E	0 mg/L (LOW)	+ 50 mg/L (LOW-MED)	<200 mg/L (LOW)

Table 14: Semi quantitative salt analysis results. Source: Declet 2017.

Methylene Blue Adsorption test

All of the soils had similar results. Soil B displayed a slight blue halo after 95 ml of the methylene blue tryhydrate solution. Soil A reacted after the addition of an 80 ml solution, followed by Soil E with 75 ml and the original adobe with 70 ml. The light blue halo was very difficult to observe throughout all of the samples.

4.2.2 Original Adobe Results Conclusion

Past analysis of the original adobe described the soil as fine grain and having low plasticity (6) (O'Bannon 1978, 13-15).⁶² It has been described as poor in clay size with large amounts of sand and silt (Brown et al. 1979, 31). Others agree with the soil's low shrink-swell potential, such as Chambers who concluded the plasticity index was 5 (Physical Science Technician 1978, 7). This corresponds with the plasticity index found for the original adobe, an average of 6, characteristic of a sand or silt soil with very little clay. Due that the Adobe soil tested from Tumacácori has a plasticity index lower than 10 and a liquid limit lower than 23%, this soil is a cohesionless. The percentage of fine particles was also found to be extremely small in comparison to the soil types characterized. The original adobe has a 7.8 pH reading, a very low amount of organic material, and only contained 50 mg/L of nitrates.

⁶² Historic analysis of original adobe is found on Section 2.1.3.

Chapter 5: Grout Design

In order to ensure the soil grouts displayed optimal grout performance, specific properties and performance characteristics were tested. These include working properties (wet grout) such as flow and viscosity, wet density, shrinkage and expansion and bleeding; properties during setting and curing and hardened properties such as capillary water absorption, water retention, water vapor transmission permeability, and splitting tensile strength.

Desired Properties for Grout			
Wet	Good injectability	Working	
Wet	Low viscosity/ good fluidity	Working	
Wet	Good penetration	Working	
During Setting	No bleeding	Working	
During Setting	Reasonable setting time	Working	
During Setting	Low toxicity	Working	
During Setting	Setting ability in humid environment	Working	
During Setting	Minimal shrinkage	Performance	
Dry	Good workability	Working	
Dry	Low content of soluble salts	Performance	
Dry	Compressive strength (similar or less than substrate)	Performance	
Dry	Adhesion strength (shear strength) (similar or less than substrate)	Performance	
Dry	Good water vapor permeability	Performance	
Dry	Low density	Performance	
Dry	Low water absorption	Performance	
Dry	Sufficient water retention	Performance	

Table 15: Required properties for a successful grout. Source: Declet 2017.

5.1 Selection of Soil "E" for grout binder

Out of the soils tested (A, B and E), soil E was selected. No definite selection was made based on the soil pH test, The Semi-quantitative Salt Test and the Methylene Blue Test results all scored close to one another. In addition, a substantial amount of fine particles were agglomerated and attached to the coarser particles in all the sieves for all the soils.

For this reason, these readings are misleading and were discarded.

A high clay content in the mix often leads to higher flexural and compressive strength. A grout mix with too much clay may lead to more shrinkage, swelling, poor fluidity, but good binding. Although Soil E has the highest plasticity index and liquid limit values, it falls under the clay loam category (medium plasticity). The higher the liquid limit of the soil, the higher the plasticity and compressibility of soils.63

Material Characterization	Standard/ Reference	Results
Testing		
		Soil A has the largest amount of fine sand and silt and clay, followed by Soil
		B and Soil E. Results were discarded in favor of combined wet dry sieving,
		since fine particles were agglomerated to the coarse particles upon higher
Particle (grain) size distribution	ASTM C136-06	magnification.
		Soil E had the highest plasticity index and liquid limit out of the soils
Plastic Limit, Liquid limit, and		tested (but not excessively high) with Soil B following closely behind.
plasticity index of soil	ASTM 4318	Coefficient of soil activity was below 0.75, indicating the soils are inactive.
	ASTM D422; ASTM	Soil B had largest amount of fines, closely followed by Soil E. Soil A had a
Combined dry/wet sieving	D1140; Nityaa Iyer	very small amount. The original adobe also had a very low amount of fines.
	2014 (P.36)	
pH of Soil-Acid Solubility	ASTM D4972-13	All the soils scored close to each other, so no definite selection was made
,		based on this test.
		Soil E had the highest organic content, which is beneficial for grout
Organic Content Analysis	ASTM D2974-14	formulation since it can prevent formation of micro cracks within the grout.
		All three soils possessed very low chloride, nitrate, and sulfate content. No
Semi-Quantitative Salt Analysis	Merck Strips	definite selection was based on this test.
	AFNOR NF D 94-068-	All the soils scored similar results, so no definite selection was made based
Methyl blue adsorption test	1998; Nityaa Iyer 2014	on this test.
	(p.57)	

Table 16: Overview of results for characterization of soil types and original adobe. Source: Declet 2017.

Soil E stood out in the "Sedimentation" portion of the combined wet/dry sieving test

that measures the amount of finer particles (desirable for the grout). Soil E also had the

⁶³ Throughout the plastic limit test, Soil E was rolled 8 continuous times without crumbling, taking a larger amount of water without crumbling. Soil A on the other hand, only reached 2 rolls before crumbling. Soil A was eliminated first due to its low plastic and liquid limit result. It did not contain enough clay, proving hard to roll and crumbling during the plastic limit test.

highest organic content with a 5.16%, which is beneficial for grout formulation since it prevents formation of micro cracks within the grout.

5.1.1 Grout Formulation and Components



Figure 49: Components of the grout: 2.5 Soil E: 1 part HMP. Source: (Right Images) Declet 2017 (Left Images) DMW 2016; Humboldt Manufacturing.

The formula used for the grout was 2.5 parts soil to 1 part water with 2% sodium hexametaphosphate. The 2.5:1 ratio is based on Iyer's research on soil grout formulations for earthen structures. After subjecting several formulations of the grout to numerous tests that characterized the grout's rheology and shrinkage, Iyer concluded a 2.5:1 solid to liquid ratio (by volume) performed the best. 2.5:1 soil to 2% sodium hexametaphosphate fared better than the soil to water alone. In some instances, the samples prepared with this ratio showed signs of cracking in the qualitative drying shrinkage test.⁶⁴

⁶⁴ Higher ratios such as 3:1 proved to be too viscous and complicated to pour and so lyer discarded these from her testing early on.

Soil "E" for the grout was sieved through a #10 ASTM sieve (2mm particle size). Typically, grouts for structural repair are sieved through a #8 sieve (2.36 mm particle size) based on the assumed width of the cracks and the diameter of the cannula to be used. But for reattachment of the lime plaster to the substrate, a smaller particle size is preferred given the crack and detachment dimensions. The use of a #10 ASTM sieve eliminates large sand particles, producing a finer and more diluted grout while reducing micro cracking due to drying shrinkage (Vargas et al. 2008; Silva et al. 2012).

Sodium Hexametaphosphate (HMP) was used as an amendment to increase fluidity without increasing the amount of water used. The 2% HMP solution acts as a deffloculant, dispersing clay particles and ensuring uniform separation amongst the particles. HMP prevents flocculation, known as suspended matter that combines into large aggregates big enough for gravity to accelerate their settling. Adding HMP improves fluidity and reduces shrinkage and viscosity (Lourenco et al. 2013).

5.2 Grout Mixing

As mentioned in the previous section, the selected recipe for the grout was 2.5 parts soil sieved through #10: 1 part 2% HMP solution. A five gallon bucket was used as the mixing bucket to make larger quantities of the grout.⁶⁵ The quantities required for the sand and soil were first calculated prior to mixing. 20% more than the minimum requirement for each testing was made to account for any grout retained on the container. The ingredients were mixed with the use of a Milwaukee hand held corded 3/8

⁶⁵ Around 2.5 gallons of the bucket was used to make one batch.

electric drill with a speed range of 0-850 rpm. A metal 5 gallon spiral paint mixer was attached to drill to mix the grout for 4-5 minutes. A timer was set each time, and at the 3 minute mark the bucket was scrapped before continuing to mix. A total of 9 batches were made on 5 separate days to complete all the grout testing.

Since the soil was moist inside its container, around 900 mL of the soil was placed on a glass dish and was left in the oven to dry at 40°C for 16 hours to remove some of the moisture. It was later placed in the desiccator for 1 to 2 hours before sieving through #10 sieve. The sodium hexametaphosphate solution was prepared 500 mL at a time. Per every 500 mL of deionized water, 10 mL of Na₆P₆O₁₈ in solid powder form was added to get a 2% HMP solution. Deionized water was used to prepare the HMP solution in order to prevent any introduction of salts, impurities or any alteration of pH that might come from tap water.

5.3 Grout Testing

	Sample Schedule						
Wet Grout Testing	Test	Standard	Shape	Size			
	Flow/ Viscosity	ASTM C939; ASTM C230; ASTM C780; DIN 18555; Nityaa Iyer 2014 (p.69)	Funnel	Orifice diameter of 4.76mm (less than 1/4") at 50 mm long (around 2")			
	Wet Density	ASTM C937; ASTM D4016 and CRD C-78; Bicer- Simsir and Rainer 2011 (p.21)	Cylindrical cup	400 ± 1 mL cup; 88 mm depth			
	Drying Shrinkage Test (qualitative- saucers and prisms)	Ferragni 1984; Nityaa Iyer 2014 (p.74-79, 92-93)	Prism	1" x 1" x 6-3/4"			
	Expansion & Bleeding	ASTM C940C; EN 447:1996; Bicer-Simsir and Rainer 2011 (p.18)	Glass cylinder	500 mL cylinder 25mL cylinder			
Dry Grout Testing	Capillary water absorption*	NORMAL 11/85; Zajadacz and Simon 2006; Bicer- Simsir and Rainer 2011 (p.35)	PVC pipe	4" high tube, 1" diameter			
	Water retention	RILEM 11-6; ASTM C1506; DIN 18555, part 7; Zajadacz and Simon 2006; Bicer-Simsir and Rainer 2011 (p.51)	/	200 mL			
	Permeability (water vapor transmission)	ASTM E96/ E96M-15; Bicer-Simsir and Rainer 2011 (p.40)	Circular disk	2" diameter 1" height			
	Splitting Tensile Strength	ASTM D3967, ASTM C348-72; ASTM C496 M-11 (splitting tensile test) EN 196-1; Ferragni 1984, Bicer-Simsir 2009; Bicer-Simsir and Rainer 2011 (p.28); Nityaa Iyer 2014 (p.77)	PVC pipe	2" hollow pipe; 4" height			
Mock-up	Shear Bond Strength (adhesion)	ASTM D 905, BS EN 196-1; Bicer-Simsir and Rainer 2011 (p.62)	Square	3.5" X 3.5" X 1" Plaster 3.5" X 3.5" X 3" Adobe 0.25"-0.50" Grout Thickness			

Table 17: Testing schedule for grout testing. Source: Declet 2017.

5.3.1 Wet Properties

• Flow/ Viscosity

This test method was performed to determine the time of efflux for a known quantity of grout to flow through standardized flow cone funnel. It is to be tested on grouts with fine aggregates smaller than 2.36mm. The rate of the grout is then compared to the rate of water flowing through the same assembly. Values obtained are not direct viscosity measurements, but the test helps to characterize the rate of flow of the designed grout. The test is based on ASTM C939, and Iyer's 2014 adaptation for mud grouts.



Figure 50: First, 1725 mL of water was poured through the cone twice and two flow measurements were recorded. Afterwards, the prepared grout was poured, and three stop watches were started once the finger stopper was removed. Source: Declet 2017.

• Wet Density

The aim of this test is to determine the density of the wet grout. Two similar methods were used to test the grout, GCI's Laboratory Testing Procedure and Field Testing Procedure. In the former, a 400 mL container is filled with grout and weighed, while in the latter a syringe is filled with grout and weighed.

The test follows GCI's Section 2.3 and 4.5 Wet Density test for grouts, as well as ASTM C185. However, GCI's standards did not call for the compaction of the grout since grouts are less viscous than mortars and a tamper can cause air entrapment. Two batches were done for both methods, but the procedure is essentially the same. The containers were weighed and later slowly filled with the grout. The tamper was only used to tap the sides. For the cylindrical metal container, the top was made flush with a trowel. Afterwards, the cup was weighed again. Similarly, the syringe was filled with 12 mL of grout instead of 5 mL, and was tapped to remove any air bubbles. It was finally weighed to calculate the wet density of the grout.



Figure 51: The syringe was filled with 12 mL of grout instead of 5 mL, and was tapped to remove any air bubbles. It was finally weighed to calculate the wet density of the grout. Source: Declet 2017.

• Drying Shrinkage

The grout shrinkage was evaluated using two tests, a visual qualitative method and a quantitative test measuring the drying shrinkage of grout prisms. The former consisted of visually identifying shrinkage on a grout sample poured on a terra cotta saucer for a period of 28 days. Grout shrinkage was identified by visible surface cracking and diameter change. The aim of the quantitative prism test is to measure the decrease in length of the

prisms under controlled drying conditions. However, many other factors influence the material's dimensional change in the actual assembly, such as restraint, ambient temperature, and humidity.

For the visual qualitative method, the grout mix was poured into four terra cotta saucers within a minute of mixing. This test method is based on Washa (1966, 190) and lyer's 2014 adaptation.



Figure 52: These were observed for 28 days, while monitoring the temperature and relative humidity. Source: Declet 2017.

The drying shrinkage prism method followed ASTM C1148-92A and ASTM C490.66

From one mold, 3 prism samples could be made, each measuring up to 1 in x1 in x 6.75 in.67 According to ASTM, the specimens are to be removed from the mold 72 hours after being poured. However, that standard is for masonry mortar. The samples were left in

the container for an additional 24 hours to let them set properly.68

⁶⁶ A minimum of five specimens were required for this test. The effective gage length was that of 5.25 in.⁶⁷ The molds had been previously prepared by Nityaa Iyer in 2014.

⁶⁸ The length of the prisms was measured after 4, 11, 18 and 25 days of air drying using a length comparator device.

The gauge studs attached to each end of the specimen are carefully placed in the device to obtain a length reading, and record length change for the specified period. The minimum reading of the dial was recorded when rotation of the sample occurred. The specimen was always measured from the same end.



Figure 53: The molds were pre lubricated several times with mineral oil to prevent the wooden mold from drawing water out of the grout. After pouring, the molds were observed to make sure no sagging occurred. The total percent shrinkage of the specimens was calculated at the end. Source: Declet 2017.

Expansion & Bleeding

The amount of expansion and bleeding characteristics of the soil grout were analyzed by measuring the total change of volume and accumulation of bleed water in a tight sealed cylinder for a certain period of time. A desirable grout should not visibly segregate or bleed after being prepared. Otherwise, it might clog while being injected in the assembly. A suggested bleeding percentage for a grout should be less than 0.4%. The test follows GCI's Section 2.2 Expansion and Bleeding test for grouts, as well as ASTM C940-16. The GCI's reference mostly follows the ASTM procedure, with the exception of the grout volume. Instead of the original 800 mL used to test concrete, 400 mL was used to test grouts. The ambient temperature of the room should be at 23°C to run the test. The temperature of the grout should also be collected, and it should be at 23°C +/- 2°C.



Figure 54: After mixing, the grout was poured into a 500 mL graduated cylinder until the sample reached 400 mL. The top was covered with parafilm to prevent evaporation of any possible bleeding water. Source: Declet 2017.

5.3.2 Hardened Properties

Splitting Tensile Strength

The tensile strength of the tested grout should be equal to or less than the original plaster and adobe substrate to prevent damage to the original fabric. The grout is more likely to fail due to tensile stresses rather than shear stresses, and even less so in compressive strength. Consequently, the cylindrical sample will most likely fail as a response to horizontal tension forces, rather than vertical compression forces, which ultimately leads to failure in the center of the specimen. This tensile strength obtained through this test, however, is expected to be 10% to 50% higher than direct tensile strength measurements. The universal mechanical testing machine used must match the description found in ASTM D3967-16, or any equipment capable of compressive loading.

Grout cylinders were prepared 28 days prior to testing to allow for enough curing time. Rather than preparing the specimens according to the GCI's 2.5 Splitting Tensile Strength procedure, which requires the use of an injectability apparatus using the sand column test, the earthen grout was prepared by pouring directly into pvc molds, 4 inches in length and 2 inches in diameter. ASTM C 496/C 496M was used as a reference document to the GCI's grout manual specifications. An additional 2 inches was taped to the upper length of the cylindrical pvc mold to account for any slumping of the grout. Right after pouring, the molds were lightly hit against the surface 10 times to allow any air bubbles to exit the surface.

The specimens were allowed to initially cure for 7 days before removing the upper section that was taped. In addition, one of the molds was take out to study the curing process of the grout column. However, the column sagged, and so the rest were left in the molds to cure for an additional two weeks before removing the mold all together. Conversely, hydraulic lime based grouts and other cements are required to be covered with plastic sheeting prior to testing. The specimens were oven dried two days before testing to ensure uniform drying. Two wooden strips were then taped to both the top and bottom sides of the samples in order to apply the load evenly. Prior to testing, the diameter and length were measured three times to reach an average to the nearest 0.01 in.



Figure 55: The earthen grout was prepared by pouring directly into pvc molds, 4 inches in length and 2 inches in diameter. Source: Declet 2017.



Figure 56: The maximum load, also known as the breaking load was recorded in psi to calculate the splitting tensile strength. Source: Declet 2017.

• Capillary water absorption

The aim of the test is to estimate water absorption behavior on hardened grout using the gravimetric method. An empty transparent plastic tube, measuring 4.5 in by 1.625 in, was filled with the grout using a syringe with a catheter tip while the tube is geld vertically. After curing, the grout columns are placed in a water filled container and the weight change of the specimen is recorded for a defined period of time.

The test follows GCI's Section 2.7 and 4.8 Capillary Water Absorption test for grouts, which are based from NORMAL 11/85 and RILEM test.II.6. A clear linear fluorescent Tube Guard, was cut using a bandsaw to make at least three specimens. All columns were stored for a minimum of two weeks before removing from container. After removal, samples were dried in an oven at 40°C for 24 hours, until the difference between two successive measurements was less than or equal to 0.1% of the weight of the sample. The column's length and diameter were measured using a digital caliper.

A tray with a perforated metal stand was filled with deionized water until reaching 2mm above the stand. The glass tray was placed inside a larger container with a petri dish filled with desiccant to prevent condensation. The column was then placed on a stand and the amount of water absorbed was recorded periodically following standard procedures. The lid was placed on the plastic box to minimize evaporation and to control the RH.

94



Figure 57: All columns were stored for a minimum of two weeks before removing from container. The glass tray was placed inside a larger container with a petri dish filled with desiccant to prevent condensation. Source: Declet 2017.

• Water retention 69

The following test aims to determine the water retention value of the grout when subjected to suction. The suction portion recreates the absorption mechanism that occurs amongst the building materials. The test is usually for hydraulic cement based mortars and plasters, however this test can also be used on nonhydraulic injection grouts. The grout's ability to retain water also provides insight regarding the grout's injectability and flow. The water retention value, WRV, is computed from the water loss that occurs between the original grout and the grout after being subjected to suction. A higher water

⁶⁹ The water retention apparatus, a filtration assembly, was built for the use of this thesis by John Hinchman, HSPV Penn lecturer and research specialist for the ACL, with assistance from Courtney Magill, HPSV lab manager and recent program graduate.

retention capacity indicates the grout's strong resistance to having its water absorbed by the substrate which will allow the grout to flow a greater distance.

The test was mostly based on GCI's Section 3.2 Water Retention and Release test for grouts. ASTM C1506-16b and RILEM TC 116-PCD were used as reference standards. However the GCI's reference for grouts does not calculate the WRV using flow calculations, as required in the ASTM. The change was made to accommodate grouts, since the flow table is designed for mortars and plaster which have a higher viscosity than grouts. The perforated dish was also not filled to the top edge and the total volume of the grout was reduced to 200 ml to ease transportation in order to record the weight of the assembly, as well as limit the amount of material lost in the process. For this particular assembly, the perforated brash dish was replaced with a pa perforated plexiglass dish. The brass funnel was also replaced with a zinc plated galvanized funnel. The glass stopcock, vented Erlenmeyer armed flask vacuum pump, vacuum regulator closely match the ASTM description.

The filtration assembly consists of a grout mix collected in a perforated dish that rests on a funnel that is connected by a three way stopcock to a vacuum flask, to which a controlled vacuum is applied. First, a 2.5 μ m filter paper, 150 mm diameter is wetted and placed on the perforated dish, and is weighed to the nearest 0.01g. After preparing the grout mix, 200 ml of the solution is poured into a beaker which is then poured into the perforated dish. If the grout has a thicker consistency, a non-absorptive tamper is used to tamp across the surface 15 times. Afterwards, the assembly is once again weighed. The

rim of the funnel is then greased with Vaseline and the perforated dish containing the grout is placed at the top. The stopcock should be closed at this point.

Once the vacuum is adjusted to 2.4 ± 2 kPa, the stopcock is turned (and opened) to apply the vacuum to the funnel, and the stopwatch is started. Once suction is applied for 120 seconds, the stopcock is turned again to expose the funnel to atmospheric pressure. The dish is then removed from the funnel, and the underside of the dish is dabbed with a damp cloth. Finally, the dish is weighed. The test is performed twice.



Figure 58: After performing the test, the underside of the dish is dabbed with a damp cloth. Source: Declet 2017.


Figure 59: After preparing the grout mix, 200 ml of the solution is poured into a beaker which is then poured into the perforated dish. Source: Declet 2017.

Adaptations: With the stopcock closed, the pressurewas adjusted to 2.4 kPa, instead of 7 kPa (53 mm Hg). To maintain the vacuum at a constant rate, the suction was applied for a total of 120 seconds, instead of 60 seconds. For the first 60 seconds, the vacuum should achieve a constant reading. The suction is let to run for an additional 60 seconds at that constant rate before closing the stopcock.

• Permeability (WPT)

The vapor permeability of the grout was determined by measuring the rate of water vapor transmission. Water vapor permeability is the time rate of water vapor transmission through a unit area of a flat specimen of unit thickness induced by unit vapor pressure difference between two specific surfaces, under specified temperature and humidity conditions. Water absorption is different from water transmission since the former is a process where the water goes through the pores of the materials and is retained without transmission. The desiccant method was used for the measurement of permeance.⁷⁰



Figure 60: The grout was first mixed and poured into pvc disk molds, 2 inches in dimeter and 1 inch tall. Source: Declet 2017.

⁷⁰ In such method, the specimens is sealed against a tri-cornered beaker filled with water. The assembly is placed in a controlled atmosphere, and the assemblies are weighed periodically to measure the rate of water vapor movement through the specimen and into the desiccant.



Figure 61: In order to achieve a tight seal between the grout disk and beaker, paraffin was melted on a hot plate and was dropped alongside the rim of the beaker with a dropper. Once finished, the test assembly was weighed. Source: Declet 2017.

The aim of the test is to measure the values of water vapor transfer through permeable and semipermeable materials, which helps determine the permeability of porous building materials. Properties such as vapor transmission are key to understand moisture management and durability of building materials. The test closely follows ASTM E96/E96M-15 and the desiccant method.71

⁷¹ To activate the desiccator's desiccant, a single layer of new desiccant and color indicative blue spheres were oven dried at 400°C for an hour, and were let cool before being placed inside the desiccator.

5.4 Mockup Assembly (plaster + grout + gap + adobe)

Replicated mockup samples were made early on to be tested. To complete the mockup assembly, unstabilized adobe from a commercial manufacturer in New Mexico, Earth Adobes, was used due to its availability, and traditional way of producing the mud bricks. Once the samples were made, the grout was tested in shear bond strength. Lime scratch coats were formulated to be friable and half of the samples were consolidated with Nanolime, following Jang's recent thesis (Jang 2016). The lab samples simulated conditions anticipated in the field conditions and focus on the efficacy of the grout on consolidated and nonconsolidated lime plasters.

The adobe blocks were previously cut with a Felker Mason Mite II[®] masonry wet saw to fit the dimensions required for the assembly. The large blocks were cut down to 3.5" x 3.5" x 3 blocks. Wood spacers measuring 3.5 inches x 1.5 inches, and 3.5 inches x 1.25 inches were placed under the plaster coupons to create the ½ and ¼ gaps.



Figure 62: Felker Mason Mite II masonry wet saw used to cut the adobe. Source: Declet 2017.



Figure 63: Adobe assemblies measuring 3.5in x 3.5in x 3in. Source: Declet 2017.

5.4.1 Plaster Facsimiles

Throughout the course of this research project, two different plaster mix batches

were made on two separate occasions using two separate mold designs with the same

dimensions: 3.5in x 3.5in x 1in. The first mold was a wooden grid that could make three samples at a time. These were used for the first batch but two samples out of eleven broke during the demolding process, so new molds were made to complement those. The second wooden mold was designed to make the demolding process easier. Preparation of the plaster remained consistent.

Material analysis of the original plaster suggests it is composed of a high-calcium, nonhydraulic lime containing less than 5% magnesium (Highbridge Materials Consulting, Inc., 2014). Following previous plaster characterization descriptions and Jang's facsimile preparation, Type S hydrated lime was used as the binder. Local sand, sieved through ASTM sieve No.8 was used as the aggregate. The local sand closely resembled that of the Tumacácori mission plasters (Jang 2016, 41). The selected formula to recreate the friable plaster found at the mission consisted of 1 part Type S Lime: 5 parts sand: 1.3 parts water. This produced a friability similar to that observed on site.

The ingredients were mixed using a mechanical mixer, Hobart C-100, following ASTM C305-14 Standard Practice for Mechanical Mixing of Hydraulic Cement Pastes and Mortars of Plastic Consistency. 24 hours before mixing, all the molds were generously coated with up to eight layers of mineral oil to prevent the wood from absorbing the mix's water. The original grid mold did not have a base, so a plywood sheet with blotting paper was placed underneath the mold.



Figure 64: Friable plaster formulation consisted of 1 part Type S Lime: 5 parts sand: 1.3 parts water. Source: Declet 2017.

The binder and aggregate were first lightly mixed by hand before adding water. Less than 10% of the total amount of water was added to the bowl before starting the mixer. The mixer was kept at the slower speed for 30 seconds, and was later scraped. The same portion of water was added before beginning the mixer once again. Once the mixer was stopped for a resting period of 3 minutes, the bowl was enclosed to prevent water evaporation. Afterwards, the speed was adjusted to medium, and was kept running for a minute before adding more water. The mixer was stopped and covered once again for 3 minutes, before adding more water and continuing at a medium speed for 3 minutes. This last step was performed twice for the mix to be ready.

Ingredients	Ratio	Batch 1 (1/12/17)	Batch 2 (1/22/17)
Type S Lime	1	500 mL	700 mL
Local Sand	5	2500 mL	3,500 mL
Water	1.3	650 mL	910 mL
Total Samples	-	11 square coupons	16 square coupons

Table 18: Plaster coupon ratios. Source: Declet 2017.

The samples were left to cure for a period of 28 days in an indoor controlled environment with an average of 20.5°C and 39.7 % RH. The samples were kept covered for the first week. After 7 days of drying and curing, the samples were demolded.



Figure 65: All molds were continuously coated with mineral oil 24 hours before preparing the mix. Source: Declet 2017.



Figure 66: Two 0.5in wood strips were glued onto the bottom of the base (3.5in x 3.5in x 0.75in). The sides consisted of two 3.5in x 2.25in and two 4.875in x 2.25in plywood pieces.. Source: Declet 2017.



Figure 67: The new molds improved the demolding process. The sides of the mold were attached with masking tape. Source: Declet 2017.

5.4.2 Nanolime consolidation on friable plaster facsimiles

As previously mentioned, twelve plaster coupons were consolidated with nanolime. After curing for 28 days, and the samples were placed on a tray with a metal grill. Nanolime is created by combining nanoscale calcium hydroxide particles with alcohol such as ethanol.

Nanolime consolidation, which works through the carbonation process, has demonstrated to improve grain cohesion of friable plaster, as well as increase durability to weathering without affecting the physical properties of the substrate. After application, the alcohol solvent evaporates to enable the carbonation process. Additionally, calcium hydroxide particles and alcohol display a very low viscosity. The effectiveness of the product was determined by Jang based on effectiveness, compatibility, durability and reversibility (Sassoni et al., 2016).

The consolidant was applied in three cycles, using two solvent concentrations of the nanolime product, CaLoSiL[®] E5 and CaLoSiL[®] E25. Prior to application, any loose

particles were remove from the surface with a one inch brush following Jang's procedure (Jang 2016, 46). The solution was poured in a tri-cornered beaker 50 mL at a time, making sure to coat the top and bottom surfaces of the square coupons. Any excess nanolime, remaining on the surface was blotted.



Figure 68: Nanolime consolidant was applied in three cycles. Source: Declet 2017.

For the first application, 20 mL was used to coat one square. A total of 200 mL of CaLoSiL® E5 was used to coat all the squares. The second coat, applied the following day, used CaLoSiL® E25. Around 12.5 mL was required to coat one square, and a total of 130 mL to coat all squares. The third application made use of the same concentration, and the amount used for one square coupon was less than 10 mL, and tallied up to 110 mL. These were immediately covered after every application using plastic film, and were placed in a large plastic container with two glass dishes filled with water to keep the relative humidity extremely high for the first weeks. The RH was maintained at 91%. Total curing time consisted of 28 days.

5.4.3 Shear Bond Strength

A successful grout should have an adhesion or shear strength similar or less than the adobe substrate and plaster. The aim of this test is to assess the grout's shear bond strength within the mockup assembly consisting of the plaster facsimiles, an adobe block, a wooden spacer and the grout. In any instance, the bond failure should occur within the grout or the bond interface where the substrate and grout meet. The original material must not fail. The test is not completely unbiased, as several factors may interfere with the shear strength of the grout.

The test mostly follows GCI's manual of laboratory and field test methods for injection grouts, Section 3.5, which is based on ASTM D905-08 and EN 196-1 Part 1. The friable plaster samples, both consolidated and un-consolidated, were adhered to the New Mexico handmade adobe blocks with the injection grout. The wood spacers were taped to the plaster surface to recreate the ½ and ¼ inch gaps. The surfaces were taped together with clear adhesive tape to maintain visibility and to prevent the grout from adherence.

All surfaces were prewet with deionized water for 5 minutes, and any remaining water was removed with a luer lock tip syringe and a #14 cannula. To inject the grout a catheter tip syringe with a 3.25 in. tube attached to achieve full surface contact with both planes. Assemblies were not moved during or after grouting to limit micro cracking during curing time. Immediately after, the assemblies were covered with a plastic sheet to prevent immediate shrinkage. After a week of curing, the clear adhesive tape used was carefully slit with a xacto knife and was left to cure for another week.

The tape and wooden spacer was removed prior to placing the assembly into the machine. These were set 6mm deep into the holder. Following GCI 3.5 standards, the loading rate increase was of $2400 \pm 200 \text{ N} \cdot \text{s}-1$ in compression. Simultaneously, the loading was applied at a rate of 5mm (0.20in.)/1min until failure. Once finished, the maximum

load was recorded as the breaking load in Newtons, and the grouted area's length and width was measured as well. The average shear bond strength was calculated at the end.



Figure 69: Assemblies prior to grouting. Source: Declet 2017.



Figure 70: Grout Assembly diagram. Source: Declet 2017.



Figure 71: Adobe faces were pre-wetted prior to the grouting procedure. Grouting was done by attaching a tube unto a catheter tip syringe. Source: Declet 2017.



Figure 72: Assemblies before and after testing for shear bond strength. Source: Declet 2017.

Chapter 6: Laboratory Testing (Rheology)

6.1 Flow/ Viscosity

A desirable grout is one with a low viscosity and high flow rate. The higher the Marsh cone viscosity value, the higher the viscosity, while a less viscous fluid will take a longer time to fill the container. The longest time of efflux permitted is 35 seconds. Results are indicated as seconds, and indicate the relative consistency of the fluids.

Observations: The amount of the receiving container was typically 20 ± 5 mL less than 2000 mL due to the fact that the grout residue coated the funnel. Both batches flowed easily, and absolutely no settling of course fraction occurred. For both batches, the grout temperature was between 22°C and 23°C, and the overall temperature in the room was 22.2°C and 18.9°C for the second batch.

	Marsh Flow Cone Values			
	Time of efflu	ix of water	Time of ef	flux of grout
Batches	#1	#2	#1	#2
Reading #1 (s)	5.72	4.46	14.28	20.84
Reading #2 (s)	3.98	3.89	16.05	22.62
Average Reading (s)	4.85	4.175	15.165	21.73

Table 19: Flow and viscosity test results for grout. Source: Declet 2017.

Results: Both batches resulted in slightly different times of efflux, yet the readings were 1.8 s apart. In average, the total time of efflux of the grout was 18.02 s, and the total efflux of the water was 4.51 s. In comparison to Iyer's soil grout, this formulation had a higher viscosity than her Sample D (2.5 soil:1 HMP) which averaged 12.88 s (Iyer 2014, 75, 109). Other than sharing the same ratio and use of HMP in water, the soil used by Iyer

was different than the one employed here which could explain the different times of efflux.

In comparison to other research on soil grouts, the flow time for the grout prepared by Silva was 34s for 1 cubic decimeter of water, or 34s for 1000 mL of water at 18°C (Silva et al. 2012, 7). Additionally, Silva and Lourenco tested two separate grouts, Mud grout A had a flow time of 85.9 s, and B of 36.5 s.72 Note that both grout formulations contained HMP in water to improve fluidity.

Grout B is more similar to the Tumacacori designed grout than Grout A, but the components are still very different due to the addition of limestone powder and smaller particle size (2mm).⁷³ The flow time for Mud B was 35.6s for 1000 mL, displaying a higher viscosity, and less fluidity, than the grout designed for Tumacácori (Lourenco et al. 2013, 5).

6.2 Wet Density

Results: The grout's wet density was an average of 1.87 g/cc. In terms of compatibility, the grout has a lower density than that of Tumacácori. The density of Tumacácori adobe samples analyzed in 1978 revealed the density to be between 2.46

⁷² The specimens were left to cure for a period between 27 and 35 days, at a 20°C temperature and 57.5% RH value (Lourenco et al. 2013, 4). Grout A was described as an "artificial" mud grout, 20 Kaolin powder: 80 limestone powder: 0.40 sodium hexametaphosphate. Conversely, Grout B was the "natural" mud grout consisting of 40 parts sieved soil (particle size 0.18 mm- ASTM No.80 sieve), 60 parts limestone powder, and 0.46 parts sodium hexametaphosphate.

⁷³ The soil used for Grout B had a similar plastic limit to Soil E (16.6% vs 16%), but had a lower liquid limit (23% vs 34.2%), and a lower plasticity index (7% vs 17.6%).

g/cc and 2.56 g/cc (Brown et al. 1979, 35). However, different methods were used to obtain these results.74

TUMA grout	Weight of 12mL syringe (g)	Weight of the grout + syringe (g)	Weight of the grout in syringe (g)	Wet density of grout (g× cm ⁻³)
1	4.9	27.4	22.5	1.88
2	6.3	29.1	22.8	1.90
TUMA grout	Weight of the cup (g)	Weight of the grout + cup (g)	Weight of the grout (g)	Wet density of grout (g× cm ⁻³)
1	98.63	1662.78	1564.15	1.84
2	101.3	1684.25	1582.95	1.86

In comparison, the density for the kaolin and HMP grout tested by Silva's team

varied between 1.198 g/cc and 1.347 g/cc, less dense than the grout discussed here.75 A

summary of the grout composition tested by Silva is below:



Figure 73: Silva et al. grout formulations. Source: Silva et al. "On the development of unmodified mud grouts for repairing earth constructions: rheology, strength and adhesion." ISISE, University of Minho, Portugal and Catholic University of Leuven, Belgium, 2012: 29.

⁷⁴ The first was obtained by calculating the weight change of the wet grout collected in a syringe, while the second was determined by helium pycnometry.

⁷⁵ These were mixed using a Hobart N50 planetary mixer with a wire whip paddle. The grout was first mixed for 5 min at speed 1, then for 5 min at speed 2, with a 1 min resting period between steps (Silva et al. 2012, 7). The specimens were kept in a controlled environment of 20°C and RH of 65%. Specimens achieved a constant weight in 3 to 5 days.

In comparison to an NHL 3 grout with no additives, the density (volumetric weight) is 0.70 g/cc less than the soil grout designed.⁷⁶ However, an NHL grout can expand up to 0.05", more than the soil based grout discussed.

6.3 Drying Shrinkage

Observations (saucers): The grout placed in the terra cotta saucers performed well. The grout did not crack, but it did shrink uniformly as indicated by a slight gap around the perimeter.

Observations (prisms): The specimens were allowed to dry for an additional 24 hours. After 96 hours, the prisms were partially removed from the molds while still attached to the smaller blocks that held the gauge. After two hours, the prims were released and remained attached to the gauge. Both the saucers and the prisms were placed in a controlled environment, 21.5°C average and 50% RH.

	Effoctivo	4 days	11 days	18 days	25 days	Druina	
Specimen (prism)	gage length L0 (in.)	Initial measurement after removal L1 (in.)	Measure	ement durin _i (in.)	g drying L	Shrinkage Average mean	Percent Shrinkage (S) %
1	5.438	7.646	5.41	5.344	5.372	5.943	41.82
2	5.438	6.04	4.584	4.532	4.554	4.9275	27.33
3	5.438	6.478	5.096	5.062	5.068	5.426	25.93
4	5.438	4.786	2.632	2.59	2.618	3.1565	39.87
5	5.438	6.758	5.862	5.82	5.83	6.0675	17.07
6	5.438	9.62	8.314	8.28	8.29	8.626	24.46

Table 21: Drying Shrinkage results for grout prisms. Source: Declet 2017.

⁷⁶ Chaux 100 naturelle pure 1 NHL5L 1.5 Sand (well graded sands #6 to #200). Mix is recommended for injection grout by manufacturer, St.Astier.

Results: The average percent shrinkage for the six specimens was 29.41% (standard deviation 9.56.) The change in area for the prism specimens was also recorded, averaging up to 3.84%. It is difficult to obtain comparable values with other mud grouts tested by other researchers.⁷⁷ Regarding lime grouts, Pingarrón's NHL grout cohort had little or no shrinkage at all after a year cure (Pingarrón 2006, 62).⁷⁸

7000	PROPO	RTIONS (BY V	OLUME)		
SAMPLE	NHL	S	MS	ACRYLIC IN H ₂ C	
A	2.0	1.0	1.0		
В	2.0	1.0	1.0	5% ER	
С	2.0	1.0	1.0	10% ER	
1	PROPORTIO	NS (BY WEIGH	HT IN GRAMS)	•	
SAMPLE	NHL		S	MS	
Α	960	Ī	525	960	
В	960		525	960	
С	960		525	960	
NHL - St.	Astier NHL S – S	and MS – Micro	ospheres Acrylic -	El Rey (ER)	

Figure 74: Mixed developed and characterized by Pingarrón in 2006. Source: Pingarrón Alvarez, Victoria I. Performance Analysis of Hydraulic Lime Grouts for Masonry Repair. Masters Theses (Historic Preservation), University of Pennsylvania, 2006: 26.

⁷⁷ Silva et al. abstained from characterizing the drying shrinkage in their mud grouts due the complexity of its causes, such as external factors that are hard to simulate to obtain reliable results (Silva et al. 2012, 6). Lourenco and the team. Silva, Oliveira, Lourenco, Schueremans, and Miranda did not publish drying shrinkage results for their 2013 research.

⁷⁸ Pingarrón used glazed saucers to test the drying shrinkage, not the prisms.

6.4 Expansion & Bleeding

Observations: The graduated cylinder remained tightly sealed for 24 hours. During that time, absolutely no bleeding or expansion occurred. The weight of the graduated cylinder with the grout and parafilm seal was that of 1057.13 g. Once finished the weight was 1056.5 g, with only a slight weight change of 0.63 g.

6.5 Splitting Tensile Strength

Results: As previously mentioned, the tensile strength value obtained from this test is more likely to be higher than direct tensile strength measurements. The grout developed for Tumacácori averaged 0.50 N/mm^2 (73.11 psi) in splitting tensile strength, and 0.26 N/mm^2 (37.14 psi) in compressive strength.

Mean of	Mean of Splitting	Standard deviation of	Mean of	Standard deviation of
Maximum	Tensile Strength	Splitting Tensile	Compressive	Compressive
Load (lbf)	(psi)	Strength (psi)	Strength (psi)	Strength (psi)
943.10	75.86	11.32	36.26	4.49

Table 22: Splitting Tesnsile Strength results for grout. Source: Declet 2017.



Table 23: Splitting Tensile Strength results graph. Source: Declet 2017.

Silva's rammed earth cylindrical specimens tested under compression resulted in an average of 1.26 N/mm^2 , 20% more than the grout designed for Tumacácori.⁷⁹ However, the rammed earth was not designed to be a grout.

In comparison with Pingarrón's NHL and acrylic grouts (Range= 12.58-24.85 psi), the splitting tensile strength of the grout designed for Tumacácori was considerably stronger. However, the grout had a significantly lower compressive strength than Pingarrón's grouts. Similarly, the compressive strength of St.Astier's 1:2.5 NHL 3.5 grout is stronger in compression, 290 psi after 28 days, than the grout tested in this paper.

Nevertheless, the grout's strength should not exceed that of the original adherents: the adobe substrate and the lime plaster. The untreated soil's compressive

⁷⁹ The cylindrical specimens used by Silva's team measured 7.87" in height, and 3.93" in diameter. The rammed earth specimens were manufactured with soil from Odemira, Alentejo, and due to its high clay content, the soil was corrected by adding river sand and gravel obtained from crushed granite.

strength used for the Tumacácori adobe was tested in 1978 by Charles OBannon (OBannon 1978, 30). The compressive strength was around 3000 psf (20.83 psi). However, these results are not entirely representative of the actual adobes.⁸⁰ The soil samples were treated with electro-osmotic treatment prior to the compressive strength tests.

		TREATMENT: SIL	ICA GEL AND SOL	DIUM CHLORIDE		1
Voltage Gradient v/cm	Tube End	Time of Treatment	Treated PS	E Untreated	ive Strength Increase	Decrease
1/4	anode cathode		1917 2451	3100 2800	=	38 12
1/2	anode cathode	1 Day	1055 1748	2850 2800		63 38
1	anode cathode		2961 2112	2800 2900	6 	27
1/4	anode cathode		2136 1408	2900 2900	=	26 51
1/2	anode cathode	2 Day	3956 4029	3000 2900	32 39	=
1	anode cathode		1990 *	2900 *	*	31 *
1/4	anode cathode		2476 1262	3000 3000	=	17 58
1/2	anode cathode		2184 2015	3000 3000	===	27 33
1	anode cathode	4 Day	2573 2016	3000 3000		14 33
0			2743	2900		5

Figure 75: O'Bannon compressive strength results for Tumacácori adobe soil. Source: O'Bannon, Charles E. Stabilization of Prehistoric Adobe Architecture by Electro-osmosis and Base Exchange of Ions (Phase II). Arizona: Arizona State University, 1978: 36.

On the other hand, plaster facsimiles resembling the mission's friable plaster were

tested for splitting tensile strength in 2016 by Jang. Jang found that the average splitting

tensile value of the untreated plaster was that of 451.27 psi, surpassing that of the tested

⁸⁰ Soil cylinders were trimmed to a height twice the size of the diameter. These were later capped with Cylcap, a sulfur compound.

grout (Jang 2016, 77).⁸¹ A summary below of the untreated and nanolime treated plaster samples tested by Jang:⁸²

	Control (A)	Consolidated (B)	Consolidated (C)
Sample description	Unconsolidated	28 days curing	1 year curing
Maximum force (lbf)	113.7	148.7	242.4
Mean STS(psi)	451.2	654.7	1143.1
Stand. Dev. STS(psi)	90.4	99.7	80.8

Table 24: Splitting Tensile Strength results for consolidated plaster obtained by Jean Jang (unpublished).

6.6 Capillary Water Absorption

Observations: The test was performed twice with two separate sets of samples. The first used three grout columns 5 ¼' tall, and 1" diameter, while the second set measured 4 ¼" in height, and 1 ½" in diameter. As soon as the columns were placed in the perforated metal plate inside the water filled container, they began disintegrating. During both sets, rubber stoppers were placed next to the column for support, otherwise these would fall to their sides and break, or disintegrate unevenly. The first three samples all eventually fell. Sample 3 disintegrated completely in less than 2 hours.

Anticipating similar results, for the second set, the container, metal mesh, stoppers and water were weighed before and after placing the grout column. The columns had a larger surface area than the first set, so these took longer to disintegrate and loose balance. Results were still recorded for the second set.

⁸¹ Jean Jang, ACL research associate and a recent program graduate, compared samples treated with nanolime consolidant to untreated samples and determined there was a 45% increase in splitting tensile strength. After a year of curing, Jean recently tested other consolidated samples and these saw a 153% increase in splitting tensile strength.

⁸² The results for consolidated plaster after a year have not been published yet.

Results: The weight loss was probably due to dissociation of the clays in the soil grout.

6.7 Water retention

Observations: After several tries, leaving the vacuum cap unscrewed while the vacuum was on worked the best. The valve was opened at an angle of 25° to maintain the vacuum under 100 kPa. When the vacuum tube cap was kept sealed, pressure went as high as 96 kPa.

Results: The test was performed on three different materials to perfect the assembly and to make sure the test was running consistently. A summary of the tests below:

Ingredients	Solid to Liquid ratio	Water content of the grout before suction	Weight of water extracted by suction	WRV % Water Retention Value		
NHL 3.5: Yellow	3.2:1	90.98 g	-39.9 g	143.86		
Sand: Water						
Notes: This mix is representative of hydraulic lime grouts. With the stopcock closed to the funnel (flask						
to atmospheric p	to atmospheric pressure) the pressure would not surpass 3.7 kPa. With the stopcock open, the					
pressure went as	high as 83.7 kPa, an	d water poured heavily o	lown the tube. Once the	e stopcock		
connected the fu	nnel to the atmosph	eric pressure, the pressu	re went up to 96 kPa.			
Soil B (ASTM #8	2.5: 1	61.25	-17.39	128.39		
sieve): Water						
Notes: The tube w	vas left unplugged, a	and while the stopcock w	as closed, the pressure	remained at 0.3		
kPa. The valve wa	kPa. The valve was fully opened. Soil B was assessed on Phase 1, but was not selected. It is however					
similar to Soil E, b	out water was added	l instead of HMP. It relea	sed less water than the	NHL.		
Soil B (ASTM #8	2.5: 1	109.02	-5.12	104.70		
sieve): HMP						
Notes: Water was	s substituted for HM	P to compare retention	capability. The valve wa	s not fully open, It		
was slightly rotate	ed from 0° to 25°. Th	ne vacuum was regulated	l to 2.4 kPa prior to ope	ning the		
stopcock. Once o	pen, a balanced was	reached after 40 second	ls (78.6 kPa). It was left	for an additional		
minute under a co	onstant suction rate	. The grout retained mor	e water than the previo	ous mixes.		
T	able 25. Water retenti	on and release comparison	reculte Courses Declet 20	17		

Table 25: Water retention and release comparison results. Source: Declet 2017.

WATER RETENTION AND RELEASE						
Ingredients	Solid to Liquid ratio	Water content of the grout before suction	Weight of water extracted by suction	WRV % Water Retention Value		
2.5 Soil "E": 1 HMP (Batch 1)	2.5 Soil "E": 1 2.5: 1 92.48 -4.4 104.76 IMP (Batch 1)					
2.5 Soil "E": 1 HMP (Batch 2)	2.5 Soil "E": 1 2.5: 1 89.58 -4.4 104.91 HMP (Batch 2) 104.91					
Notes: The valve w regulated to 2.4 k minute (62.4 kPa) grout retained a c	Notes: The valve was not fully open, It was slightly rotated from 0° to 25°. The vacuum was regulated to 2.4 kPa prior to opening the stopcock. Once open, a balance was reached after 1 minute (62.4 kPa). It remained for an additional minute under a constant suction rate. The grout retained a considerable amount of water in comparison to the other grouts tested.					
Т	able 26: Grout water	retension and release re	sults. Source: Declet 201	7.		

A summary of the two batches of 2.5 Soil E: 1 HMP:

6.8 Permeability (WPT)

Water vapor transmission is indicated by the slope of the curve is determined by weight loss of the total assembly over time. A strong linear relationship, known as a high correlation, is reflected by a straight line. Materials with low permeance are not expected to result in high correlation. Thicker material and moisture retaining materials take a longer amount of time to reach a steady state. On the contrary, thin materials of low permeance do not need a long test duration to reach a steady state. For instance, a low permeance coating will reduce the water vapor transmission rate and increase the time necessary for the saturated material to dry. **Observations:** The disks shrunk an average of 0.10in in diameter after a few days of curing. The temperature and RH were monitored, and kept at an average of 21.44°C and 49.86 RH%. After three weeks of curing, the samples were measured before and after placing in the oven. The specimens lost an average of 1.17% after being placed in the oven, and there was virtually no change in diameter and height of the disks during this process. The results of the WPT test were converted to $g/h \times m^2$ in order to compare with



Table 27: Average wpt rates for 6 grout specimens.

Results: The greater the weight loss, the greater the sample's permeability. The average for the six specimens tested was $5.58 \text{ g/h} \times \text{m}^2$, or $2.57 \text{ E-04 g/h} \times \text{cm}^2$. In Bass's 1998 investigation, Fort Union adobe WPT reading was $6.10 \text{ g/h} \times \text{m}^2$, which was lower than the grout cohorts Bass tested (Bass 1998, 74). These results could be compared to those obtained from the soil grout and they are quite similar, suggesting that the grout is compatible with adobe. However, WPT results for Tumacácori adobe would be needed to

confirm this.83 In comparison to the untreated plaster tested by Jang, the plaster was far

Grout Formula #	Grout Formula Ratio (weight)	Water Vapor Transmission Rate (g/h·m²)
01	1MS:1HL	8.31 ±0.03
03	1MS: 1S: 2HL	9.43 ±0.02
04	1MS: 15: 4HL	8.52 ±0.74
07	1MS:2.7S:2.5HL w/20% Rhoplex E-330 in H ₂ O	13.69 ±0.02
19	MS : 1S : 2HL w/ 10% EL REY in H ₂ O	7.00 ±0.01
20	1MS : 1HL w/ 10% EL REY in H ₂ O	6.21 ±0.02
NA	Fort Union Adobe (Boneyard)	6.10 ±0.02
MS- Cerami	c Microspheres HL- Hydrated Hydr Rhoplex and El Rey- acrylic	aulic Lime S- Quartz Sand emulsion

less permeable than the grout, with an average of 1.62 E-05 g/h \times m².

Figure 76 Angelyn Bass's tested grout formulations (1998). Source: Bass, Angelyn. Design and Evaluation of Hydraulic Lime Grouts for In Situ Reattachment of Lime Plaster to Earthen Walls. Masters Thesis, University of Pennsylvania, 1998: 73.

In comparison to other hydraulic lime grouts tested by Bass, all formulations tested were far more permeable than the 2.5 Soil: 1 HMP grout. The specimens employed were slightly larger in diameter than the ones tested here (2.75in diameter and 0.75in diameter). Those assemblies reached equilibrium in 10 days.⁸⁴ Pingarrón's testing of grouts coated with acrylic emulsion had significantly lower rates, 1.11-1.26 g/h× m² due to the coating (Pingarrón 2006, 52).

⁸³ WPT testing of the TUMA adobe was not performed due to limited availability of material.
⁸⁴ Bass's tested specimens were coated with an acrylic emulsion which in some instances decreased their wpt rates, while in another increased it (Bass 1998, 74).

6.9 Shear Bond Strength (mock-up)

Observations: Shrinkage cracks were observed in the grout layer after uncovering the assemblies. The samples were allowed to dry for three weeks before performing mechanical testing. A metal grill was placed under the assemblies for the last week of curing to assure these dried evenly. The 19 assemblies were transported on a covered cart from the laboratory to the LRSM mechanical testing room.⁸⁵ Transportation of the assemblies was somewhat problematic as the pavement is very uneven.

The operator, Dr. Alex Radin, placed a clamp on the adobe blocks in order to keep them fixed and to insure an even surface contact with the platen.⁸⁶ After testing, the samples were transported back to the ACL laboratory, where the width and length of the grouted area was recorded after breaking was measured. Photographs of each assembly were also taken to describe failure behavior. The breaking surface of each specimen was annotated as to where the break occurred (at the adobe or plaster interface or in the grout, and the fracture appearance: either conchoidal (shell-like fractures) or planar (even).

100% contact of the grout with the adhered surfaces was observed no matter how the assembly broke which indicated good injectability. In most instances the grout either broke at the interface with the adobe or in the adobe, never at the plaster interface. This reveals the grout adhered extremely well to the friable plaster. The surface shrinkage

⁸⁵ The Laboratory for Research on the Structure of Matter is located two blocks away from the School of Design.

⁸⁶ The Instron Electromechanical Testing Machine, Model 4206, was used for this test.

cracks initially observed during the drying period, were also present within the grout, yet

the grout remain well bonded to the adobe adherend even after testing

Image	Uncon solidat ed	Gap width	Observations
	(-) B1	1/2"	Shrinkage cracks were less apparent. 100% contact area. Extremely well adhered to the plaster. The grout was stronger than the adobe in some areas. The surface mostly remained flat, meaning it broke at the interface.
	(-) B2	1/2"	Shrinkage cracks visible. 100% contact area. Extremely well adhered to the plaster. Adobe retained some of the grout. Grout is less than 0.6925" thick. The surface is more conchoidal than flat.
	(-) B3	1/4"	Shrinkage cracks visible. 100% contact area. Extremely well adhered to the plaster. The top edge is conchoidal, while the rest most likely broke at the interface. Grout thickness on the side is less than 0.6020".
	(-) B4	1/4"	Shrinkage cracks visible. 100% contact area. Extremely well adhered to the plaster. The grout pulled some of the adobe on the left edge. Some of the adobe took straw and pebbles with it. The grout edges is less than 0.4270". Some conchoidal orifices, but it mostly broke at the interface.
	(-) B5	1/4"	Shrinkage cracks visible. 100% contact area. Grout extremely well adhered to the plaster. Break predominately at the interface, but the top displays conchoidal fracture within the adobe.

	(-) B6	1/4"	Shrinkage cracks visible. 100% contact area. Grout well adhered to the plaster and adobe with around 40% of the grout adhering to the adobe The surface is somewhat conchoidal.
	(-) B8	1/2"	Shrinkage cracks were less apparent. 100% contact area. Grout extremely well adhered to the plaster. to the adobe on the right side. The fractureis mostly conchoidal.
	(-) 89	1/4"	Shrinkage cracks were less apparent. 100% contact area. Grout extremely well adhered to the plaster. A large area of the adobe was adhered to the grout on the upper right corner.
	(-) B10	1/2"	Shrinkage cracks were less apparent. 100% contact area. Grout extremely well adhered to the plaster. Adobe substrate well bonded to the grout, indicating it was stronger than the grout. Less than 0.6" of grout remained attached to the adobe. There were some concoidal fracture but the fracture surface was mostly flat.
Image	Consoli dated	Gap width	Observations
	A1	1/4"	Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster. Some of the grout remained attached to the adobe but broke mostly at the interface, evidenced by flat surface. However, there are some conchoidal fractures in the adobe surface. Some of the straw from the adobe was pulled unto the grout layer.

A4	1/4"	Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster. A small section of the adobe substrate bonded to the grout layer. The surface fracture is conchoidal at the far left side of the assembly. The remaining surface is a combination.
A6	1/4"	Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster and broke at the interface (mostly flat surface).
Α7	1/4"	Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster. Grout layer is less than 0.4". Mostly broke at the interface with the adobe.
A8	1/2"	Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster. Grout bonded to the adobe on the corner upper middle section.
A9	1/4"	No shrinkage cracks. 100% contact area. Grout extremely well adhered to the plaster. The grout was stronger than the adobe causing a conchoidal pull out of around 0.8" of the adobe substrate.
A10	1/4"	Less shrinkage cracks than other assemblies. 100% contact area. Grout extremely well adhered to the plaster. Grout was weaker than the adobe, breaking at the top edge with a conchoidal surface, while the rest broke at the interface.

A11	1/2"	Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster. Some of the grout remained attached to the adobe. Some conchoidal fracture.
B11	1/2"	*First one to be tested. Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster. Fracture at the grout-adobe interface.
B14	1/2"	Shrinkage cracks are visible. 100% contact area. Grout extremely well adhered to the plaster. The grout pulled 0.2" from the adobe, but fracture mostly at the interface.

Table 28: Observations for all assemblies tested for shear bond strength. Source: Declet 2017.

Results: The average shear bond strength for assemblies with unconsolidated plaster was 4.21 lb \times in⁻², and 4.98 lb \times in⁻² for assemblies with nanolime consolidated plaster. The bond strength of the grout to the consolidated plaster was slightly higher than to the unconsolidated plaster. The average breaking strength for consolidated plaster was higher as well.

	Width of grout area w (in)	Length of grout area I (in)	Breaking load F (lb)	Shear Bond Strength (Ib*in–2)
Unconsolidated	2.78	3.69	43.23	4.21
Consolidated	2.81	3.67	51.30	4.98

Table 29: Shear Bond Strength results for assemblies. Source: Declet 2017.

	Mean of	Mean of	Standard	T-Test	T-Test
	Maximum	Shear Bond	deviation of	P Value	2-Tail P
	Load (Ibf)	Strength (psi)	SBS (psi)		
Unconsolidated	43.22666667	4.21	1.7	0.015	0.68
Consolidated	51.295	4.98	3.85		

Table 30: Analysis of shear bond strength results for assemblies. Source: Declet 2017.



 Table 31: Graph comparing shear bond strength results of un-consolidated and consolidated assemblies.

 Source: Declet 2017.

Chapter 7: Conclusions and Recommendations

The selected grout should be physically and chemically compatible with the original substrate and coatings, have sufficient flow without clumping, and its volume shrinkage once hardened should be minimal (low water content). In terms of mechanical strength, the injection grout should not create excessive stresses on the original plaster. The grout should also be lightweight, allow passage of water vapor and provide a sufficient bond strength at the interfaces. Any change or degradation over time should not introduce harmful substances or deleterious effects.

	Sample Schedule					
	Test	Desired Grout Properties	Results for TUMA Grout			
t Testing	Flow/ Viscosity	Low viscosity/ good fluidity	Both batches flowed easily, and absolutely no settling of course fraction occurred.			
	Wet Density	Low density	The grout's wet density was an average of 1.87 g/cc. In terms of compatibility, the grout has a smaller density than that of Tumacácori.			
Wet Grou	Drying Shrinkage Test (qualitative-saucers and prisms)	Minimal shrinkage	The grout placed in the terra cotta saucers performed well. The grout did not crack, but it did shrink. The average percent shrinkage for the six prisms was 29.41%, and the standard deviation is 9.56.			
	Expansion & Bleeding	No bleeding	The graduated cylinder remained tightly sealed for 24 hours. During that time, absolutely no bleeding or expansion occurred.			
esting	Water retention	Reasonable water retention	The TUMA grout showed a strong resistance to having its water absorbed.			
Dry Grout T	Permeability (water vapor transmission)	Good water vapor permeability	Low-Average permeability. Similar permeability to Fort Union adobe.			
	Splitting Tensile Strength	Tensile strength similar or less than historic materials.	The average splitting tensile value was lower than the splitting tensile value of the untreated plaster.			
Mock-up	Shear Bond Strength (adhesion)	Adhesion strength similar or less than historic materials.	Shear bond strength was lower than plaster and adobe.			

7.1 Testing Conclusion

Table 32: Overall results for grout testing. Source: Declet 2017.

Given the results, the grout appears to have performed successfully for wet and hardened properties. The desired viscosity for a grout should be low. The grout tested has a moderate viscosity, flowed easily, and due to the use of the deffloculant there was no settling of coarse fraction. The grout's wet density was also very low, and given the plaster of the mission is quite friable, any significant added weight could result in further detachment from the surface. Another desirable property of the grout is its ability to retain a significant amount of water. Once inserted in the assembly, porous materials such as the grout and plaster will try to absorb the water in the grout. By introducing a grout that is able to retain the liquid portion, the amount absorbed by the adjacent original materials is limited. In the case of soil grouts, this will allow the grout to dry slowly avoiding excessive shrinkage. The grout also did not bleed or expand during testing.

Regarding the percent shrinkage, the prism shrinkage was moderate. The grout was also vapor permeable displaying a similar reading to Fort Union adobe. However, if sufficient original Tumacacori adobe is available, permeability tests should be performed.

The grout also performed well for both tensile strength and shear bond strength. The tensile strength value of the grout was less than that of the friable plaster, both consolidated and unconsolidated. When injected and tested for shear bond strength, the grout also adhered successfully to the lime plaster and the adobe squares, possibly due to the similarity between the grout and the original materials. Overall, the successful results for the grout tested reiterate the use of compatible materials to achieve a successful grout formulation.

7.2 Future Testing and Recommendation

X-Ray Diffraction: An initial concern was the introduction of salts by using sodium hexametaphosphate. Additional testing should be performed to analyze the salts present

in the mix. Many other researchers that have used HMP in their soil grouts, such as Silva, Schueremans, Oliveira, Gyssels, Iyer, and Lourenco, have not encountered efflorescence as a result of the grout (Iyer 2014; Silva and Oliveira 2009; Silva et al. 2012; Lourenco et al. 2013). However, it is mentioned that a soil grout must present chemical stability over time, and its salt content has to be limited in order to prevent efflorescence (Silva et al. 2010, 4).

Three Point Bending Flexural Test: The New Mexico adobe used for the mockups should be tested for three point bending, to further characterize and compare its breaking load with that acquired by the grout and plaster.

In situ Preparation: The following steps to develop the grout formulation include formulating a series of in situ tests and trials. Prior to application as part of pretreatment assessment, the areas of plaster separation to be grouted should be indicated on the existing rectified images. Also, the condition of the plaster, extent of the plaster separation and gap for each plaster should be recorded. The entry points for the catheters should be determined as well. Once in situ tests are installed, the grouted area should be checked daily and monitored, including ambient temperature and relative humidity and any changes should be measured. If possible nondestructive methods of void detection and reattachment/void filling should be pursued before and after treatment to determine overall efficacy of the grouting method.
Bibliography

- Air Force Combat Climatology Center (AFCCC). "Tucson, Arizona." Engineering Weather Data Handbook. Raw Data. https://www1.ncdc.noaa.gov/pub/data/EngineeringWeatherData_CDROM/eng wx/tucson_az.pdf.
- Albert, Lewis S. Memorandum for the Superintendent of Tumacacori and Chiricahua, San Francisco, CA, November 2, 1988.
- Arendt, Nicole M. Report on the April 2010 Repair to the Plaster and Adobe Failure on the Upper WEST Exterior Wall of the Sanctuary of San Jose de. 2010.
- Arendt, Nicole M. Report on the Effects of the January 2010 Rains on the Sacristy at Tumacacori National Historic Park. 2010.
- Ashurst, John. *Mortars, Plasters and Renders in Conservation*. London: Ecclesiastical Architects' and Surveyors' Association, 1983.
- Attwell, Walter G. and Gene H. Gordon. *Report on Proposed Stabilization Mission San Jose de Tumacacori.* San Francisco, CA: United States Department of the Interior National Park Service, 1935.
- Bass, Angelyn. *Design and Evaluation of Hydraulic Lime Grouts for In Situ Reattachment of Lime Plaster to Earthen Walls*. Masters Thesis, University of Pennsylvania, 1998.
- Bass, Angelyn and Douglas Porter. Assessment, Emergency Stabilization and Treatment of Painted Plasters in the Mission Church at Tumacacori National Historic Park, School of Architecture and Planning, 2012.
- Bicer-Simisr, Beril and Leslie Rainer. *Evaluation of Lime-Based Hydraulic Injection Grouts* for the Conservation of Architectural Surfaces: A Manual of Laboratory and Field *Test Methods.* (2011), Los Angeles: Getty Conservation Institute.
- Brown, Paul Wencil, Carl R. Robbins, and James R. Clifton. "Adobe. II: Factors Affecting the Durability of Adobe Structures." *Studies in Conservation* 24, no. 1 (1979): 23-39. doi:10.2307/1505920.
- Caywood, Louis R. The Tumacacori Interpretive Program. United States Department of the Interior, National Park Service, 1944.

- Caywood, Louis R. Memorandum for the Superintendent of Southwestern National Monuments, Nogales, AZ, July 11, 1941.
- Chambers, George J. Tumacacori Preservation Project: Field Activities 1977, 1978, and 1979. Western Archeological Center, 1981.
- Chambers, George J. Memorandum for the Chief of Division of Archaeology, Tumacácori, AZ, March 12, 1986.
- Chan, Jocelyn. An Investigation of the Painted Finishes of Mission San José de Tumacácori's Façade: At the Interface of Materials Analysis, Conservation, and Cultural Confluence. Masters Thesis. University of Pennsylvania, 2016.
- Clemensen, Berle A. Historic Structure Report: A History of the Anglo Period Tumacacori National Monument Arizona. Denver Service Center, Historic Preservation Division. National Park Service. United States Department of the Interior, 1977.
- Clifton, James R. Preservation to George Cattanach of Western Archeological Center, Tucson, AZ, December 3, 1976.
- Crosby, Anthony. Historic Structure Report: Tumacacori National Monument Arizona. United States Department of the Interior, 1985.
- Crosby, Anthony. "A Preservation Monitoring System at Tumacacori National Monument." APT Bulletin of the Association for Preservation Technology 10, no.
 2, Association for Preservation Technology International (APT), 1978: 47-76. http://www.jstor.org/stable/1493612.
- Crosby, Anthony. "Monitoring Moisture at Tumacacori." *APT Bulletin of the Association for Preservation Technology* 19, no. 4, Association for Preservation Technology International (APT), 1987: 32-44. http://www.jstor.org/stable/1494147.
- Davis, John M. Davis John to Earl Jackson, Tumacácori, AZ, February 12, 1948.
- Davis, John H. John Davis to Dorothy Hall, San Francisco, CA, March 25, 1977.
- Drachman Institute Heritage Conservation. Interior Condition Assessment Report. Tumacácori National Historic Park. College of Architecture, Planning, and Landscape Architecture. The University of Arizona. In conjunction with Desert Southwest Coopertive Ecosystem Studies Unit. July 2006.

- Ferron, Amila. *The Consolidation of Earthen Surface Finishes: A Study of Disaggregating Plasters at Mesa Verde National Park.* Masters Thesis. University of Pennsylvania, 2007.
- Getty Conservation Institute. *Terra Literature Review: An Overview of Research in Earthen Architecture Conservation,* edited by Erica Avrami, Hubert Guillaud, and Mary Hardy (2008), Los Angeles: Getty Conservation Institute.
- Getty Conservation Institute. The Conservation of Decorated Surfaces on Earthen Architecture: Proceedings of an International Symposium Organized by the Getty Conservation Institute and the National Park Service, Mesa Verde National Park, Colorado, USA, September 2225, 2004, edited by Leslie Rainer and Angelyn Bass Rivera (2006), Los Angeles: Getty Conservation Institute.
- Giffords, Gloria Fraser. Sanctuaries of Earth, Stone, and Light: The Churches of Northern New Spain, 1530-1821. Tucson: U of Arizona, 2007.
- Graham, John. Tumacácori National Historical Park: Geologic Resources Inventory Report. Report no. NPS/NRSS/GRD/NRR-2011/439. U.S. Department of the Interior, Natural Resource Stewardship and Science, National Park Service. Fort Collins, CO: August 2011. https://www.nature.nps.gov/geology/inventory/publications/reports/tuma_gri_ rpt_body_print.pdf.
- Grimmer, Anne. *Preservation Briefs 22: The Preservation and Repair of Historic Stucco*. Washington: U.S. Dept. of the Interior, National Park Service, Preservation Assistance Division, 1990.
- Hamard, Erwan, Jean C. Morel, Fernanda Salgado, Alain Marcom, and Nicolas Meunier.
 "A Procedure to Assess Suitability of Plaster to Protect Vernacular Earthen Architecture." *Journal of Cultural Heritage* 14 (April 5, 2012): 109-15. http://dx.doi.org/10.1016/j.culher.2012.04.005.
- Henderson, Sam R. Stabilization Report: Tumacacori National Monument 1972. Arizona Archaeological Center, Ruins Stabilization Unit: Tucson, AZ, 1972.
- Henry, Alison, and John D. Stewart. *Practical Building Conservation. Mortars, Renders & Plasters*. Farnham: Ashgate, 2012.
- Herreras, Eleazar D, James D. Kriegh, and Hassan A. Sultan. Investigation and Inspection of Historic Structures. The Complex at Tumacacori National Monument. Second

Phase Consulting Report. United States Department of the Interior, National Park Service, 1974.

- Iyer, Nityaa Lakshmi, *Performance Evaluation of Clay Grout Formulations for Structural Cracking in Historic Earthen (Mud Brick) Buildings.* Masters Theses (Historic Preservation), University of Pennsylvania, 2014.
- Jackson, Earl. Memorandum for the Regional Director Region Three, Nogales, AZ, May 25, 1946.
- Jackson, Earl. Memorandum for the Regional Director Region Three, Tumacácori, AZ, September 26, 1947.
- Jackson, Earl. Memorandum for the General Superintendent of Southwestern National Monuments, Tumacácori, AZ, July 31, 1951.
- Jackson, Earl. Earl Jackson to Regional Director Region Three, Tumacácori, AZ, February 5, 1948.
- Jackson, Earl. Earl Jackson to Raymond E. Davis and Division of Civil Engineers at University of California, Tumacácori, AZ, April 13, 1948.
- Jackson, Earl. Earl Jackson to Rutherford J. Gettens, Tumacácori, AZ, February 27, 1949.
- Jang, Jean. Performance Evaluation of Commercial Nanolime as a Consolidant for Friable Lime Based Plaster. Masters Thesis. University of Pennsylvania, 2016.
- McHenry, Paul Graham. *Adobe and Rammed Earth Buildings: Design and Construction*. University of Arizona Press, 1989.
- McHenry, Paul Graham. Report on Research, Investigations, Conclusions and Recommendations for Moisture Control and Plastering at Tumacacori National Monument, AZ. Corrales, NM, 1978.
- Michoiová Dagmar and Palva Rovaníková. "High-Calcium Lime Mortar: The Effects of Traditional Preparation and Curing" *APT Bulletin*, Vol. 39, No. 4, Association for Preservation Technology International (APT), 2008.
- Miller, Hugh. "Unusual Weather Takes Toll on Mission Church." News Article. U.S. Department of the Interior. National Park Service. February 6, 1985.

- Moss, Jeremy. "Of Adobe, Lime, and Cement: The Preservation History of the San José De Tumacácori Mission Church." *NPS Archeology Program: Research in the Parks*, National Parks Service: U.S. Department of the Interior, 2008.
- Moss, Jeremy. "Missions of Tumacácori National Historic Park Overview Draft", South West Learning, National Parks Service.
- Mulhern, Tom. Memorandum, Tumacácori, AZ, May 31, 1985.
- O'Bannon, Charles E. Stabilization of Prehistoric Adobe Architecture by Electro-osmosis and Base Exchange of Ions (Phase II). Arizona: Arizona State University, 1978.
- Padovnik, Andreja and Francesca Piqué, Albert Jornet & Violeta Bokan-Bosiljkov. Injection Grouts for the Re-Attachment of Architectural Surfaces with Historic Value—Measures to Improve the Properties of Hydrated Lime Grouts in Slovenia. International Journal of Architectural Heritage, Vol.10, No.8, 2016: 993-1007.
- Percious, D.J. and M. Norvelle. Report on the Examination of Available Evidence on the Deterioration of the Walls of the Tumacacori Mission. Laboratory of Native Development, Systems Analysis and Applied Technology. Office of Arid Lands Studies. Tucson, AZ: University of Arizona, 1978.
- Phillips, Morgan W. "Adhesives for the Reattachment of Loose Plaster." *Bulletin of the Association for Preservation Technology* 12, no. 2 (1980): 37-63. http://www.jstor.org/stable/1493739.
- Physical Science Technician. Physical Science Technician to Chief, Division of Cultural Properties Conservation, Tumacácori, AZ, July 24, 1978.
- Pingarrón Alvarez, Victoria I. *Performance Analysis of Hydraulic Lime Grouts for Masonry Repair*. Masters Theses (Historic Preservation), University of Pennsylvania, 2006.
- Raithel, Kenneth Jr. Memorandum for the Regional Director of the Western Regional Office, Tumacácori, AZ, December 6, 1982.
- Richey, Charles A. Report of Inspection. United States Department of the Interior: National Park Service, Coolidge, AZ, 1941.
- Rickerby, Stephen, Lisa Shekede, Fan Zaixuan, Tang Wei, Qiao Hai, Yang Jinjian, and Francesca Piqué. Development and Testing of the Grouting and Soluble-Salts Reduction Treatments of Cave 85 Wall Paintings. In *Conservation of Ancient Sites* on the Silk Road, Second International Conference on the Conservation of Grotto

Sites, June 28-July 5, 2008, Mogao Grottoes, Dunhuang, Gansu Province, The People's Republic of China. Los Angeles: J. Paul Getty Trust.

- Ringenbach, Ray B. Ray B. Ringenbach (Superintendent) to Archaeologist in Charge of Ruins Stabilization, Tumacácori, AZ, September 11, 1955.
- Rigenbach, Ray. Ray Rigenbach to Superintendent of Fort Union National Monument, April 1954.
- Robbins, Carl. Characterization of Adobe Specimens for Tumacacori National Monument, Arizona. Quarterly Progress Report. Prepared for the U.S. National Park Service. 1976.
- Sewell, Joseph L. Memorandum for Participating Offices: SOAR, WACC, DSC, Tumacácori, AZ, April 4, 1984.
- Simon, Stefan and Daniel Geyer. *Comparative Testing of Earthen Grouts for the Conservation of Historic Earthen Architectural Surfaces*. Terra 2008: The 10th International Conference on the Study and Conservation of Earthen Architectural Heritage. The Getty Conservation Insititute and the Mali Ministry of Culture, 2008.
- Silva, R.A. and L.Schueremans, D.V.Oliveira, K.Dekoning, and T.Gyssels. "On the development of unmodified mud grouts for repairing earth constructions: rheology, strength and adhesion." ISISE, University of Minho, Portugal and Catholic University of Leuven, Belgium, 2012.
- Silva, R.A. and D.V.Oliveira. "Strengthening of masonry and earthen structures by means of grouting- design of grouts." ISISE, University of Minho, Portugal and Catholic University of Leuven, Belgium, 2009.
- Silva, R.A. and D.V.Oliveira, P.B. Lourenco, L.Schueremans and T.Miranda. Experimental investigation on the repair of rammed earth by means of injection of mud grouts." ISISE, University of Minho, Portugal and Catholic University of Leuven, Belgium, 2013.
- Steen, Charlie, Rutherford J. Gettens and Jimmie Trujillo. "Tumacacori Interior Decorations." Arizona Historical Society 3, no.3 (Fall 1962): 7-33. <u>http://www.jstor.org/stable/41700762</u>.
- Steen, Charlie R. Memorandum for the Associate Regional Director, Santa Fe, NM, March 5, 1946.

- Sudderth, W.W. The Nave and Bell Tower Stabilization Report 1973. Tumacacori National Monument. Ruins Stabilization Unit. Arizona Archaeological Center. Tucson, Arizona, 1974.
- Türköz, Murat and Hasan Tosun, *The use of methylene blue test for predicting swell parameters of natural clay soils.* Research Paper. Civil Engineering Department and Agricultural Faculty, Eskisehir Osmangazi University, 26480, Eskisehir, Turkey, 2010.
- Unknown Author. Report on Current Conditions of Each Historical Structure at Tumacácori National Monument. Unknown Publisher. January 1, 1941.
- Unknown Author. Report on Plaster Cracking and Leaks Associated with the West Sanctuary Window. Tumacácori National Historic Park. Unknown Publisher. July 6-8, 2009.
- Unknown Author. Tumacacori Mission Dome Project Update History. Unknown Publisher. 1986.
- Vargas, Julio and Bhawna Dandona, Marcial Blondet, Claudia Cancino, Carlos Iwaki, and Kathya Morales. *An Experimental Study of the Use of Soil-Based Grouts for the Repair of Historic Earthen Walls and a Case Study of an Early Period Buddhist Monastery*. Terra 2008: The 10th International Conference on the Study and Conservation of Earthen Architectural Heritage. The Getty Conservation Institute and the Mali Ministry of Culture, 2008.
- Vargas J., Blondet M., Cancino C., Ginocchio F., Iwaki C. and Morales K. Experimental results on the use of mud-based grouts to repair seismic cracks on adobe walls.
 In: D'Ayala D. and Fodde E. (Eds.) Preserving Safety and Significance, Proceedings of the VI International Conference on Structural Analysis of Historic Constructions 2008, Bath, UK, 2008: 1095-1099.
- Woodward, Arthur. Report of Investigation of Excavations at Tumacacori National Monument, March, 1935. Berkeley, CA, 1935.

Yancey, Charles. Charles Yancey to George S. Cattanach, Jr., Tucson, AZ, July 24, 1979.

Appendix A: Plaster Petrographic Analysis

Sampling and methodology

Sample S-13 (interior plaster) has an uncovered slip, was grinded in oil (water sensitive material) and was vacuum impregnated with an epoxy resin by consulting geologic laboratory National Petrographics Service, Inc. By mounting the section onto a slide, transmitted light is allowed to pass through. The sample was sourced January 2017 by Frank G. Matero, and was trimmed in the ACL Laboratory to fit the dimensions of the thin section.

Sample 25 was grounded to 28-30 microns thick in oil and cover slipped. Like Sample S-13, the samples was impregnated with clear epoxy. The sample was sourced from fallen plaster fragments collected by Alex Lim. The sample was trimmed and prepared by National Petrographics Service, Inc.

Both samples were analyzed at the Penn Museum's Center for the Analysis of Archaeological Materials mostly using a research grade compound transmitted microscope, Zeiss AX10 microscope. Characterization of the samples was done by analyzing the soil micromorphology, such as groundmass, and identifying inclusions and rock fragments. Rock fragments and minerals were determined by observing their optical properties, such as relief, pleochroism, birefringence, and extinction, amongst others.

Geological Context

The structure lies within the Basin and Range geological province and its located north of Nogales, Arizona. Surrounding the Tumacácori Mission Unit is the Santa Cruz River Valley of southern Arizona, which flows southward into Mexico past Sonora. The building also sits along a natural drainage system that travels from the Tumacácori Mountains to the Santa Cruz River (Moss 2008, 1). The Basin and Range province is said to have formed 15 million years ago, and the surrounding mountains were given its shape by volcanic rocks from eruptions occurring 23-27 million years ago (Graham 2012, 1). For this reason, pyroclastic materials formed from lava flow are found to be a few thousands meters thick (Graham 2012, 2).

Eroded sediment originating from the nearby mountains has covered the surface of the faults and adjacent basins. The oldest rocks in the region are granitic, igneous, intrusive rocks, which might date as far as 164 million years ago. These are classified as quartz monzonite and are characterized by 35% plagioclase, 36% potassium feldspar minerals and 20% quartz. The surface geology of the area is mainly composed of Holocene floodplain and river deposits that have eroded. The Santa Cruz River valley contains a

considerable amount of alluvium, "which generally has a high permeability typical of sand and gravel deposits but which locally may be characterized by a predominance of fine sands and silts" (Percious 1978. p.3).



Figure 77: Close-up geological map location of Tumacácori. Source: Oland, G.P and D.M. Hirschberg, Digital Geologic Map of the Tucson and Nogales: A Digital Database for the 1990 Peterson and others' Map. USGS Department of the Interior U.S. Geological Survey, 2001. http://geopubs.wr.usgs.gov/open-file/of01-275

Quaternary deposits surround the location are identified by alluvium deposited from larger streams near the mountains. Qts, defined as a basin fill deposit, are composed of older eroded alluvial deposits as described above. Surfaces are commonly found as eroded ridges and deep valleys, with varying deposit thicknesses. Deposits are often sub angular to sub rounded boulders, cobbles, and gravels compressed with layers of sand, silt and clay. Alluvium and sedimentary rocks form QTa with varying degrees of consolidation. Caliche-cemented sand, silt, and gravel deposits of conglomerate, sandstone, and siltstone, as well as small amounts of lacustrine are found in this formation. Sedimentary rocks, such as conglomerate, sandstone, and finer grained rocks are also found in the Tsm (Miocene) and Ks (Cretaceous) groups.

As previously mentioned, volcanic rocks from lava flow are found in the area Tv, such as basalt, andesite, trachyandesite, flow breccia, rhyolitic, ltitic, dacitic, and potassium metasomatized volcanic rocks. A different group of minerals and rocks is found on the

TKg group from the Paleocene period. These are granitoid rocks, described as medium to fine grained biotite hornblende granodiorite, granite, diorite, and gabbro. More granitoid rocks are found in the Jg (Jurassic) group, containing (coarse to fine grained granite, granodiorite), quartz syenite, syenodiorite, (diorite, and rhyolite), rhyolite porphyry, and aplite intrusions. Similarly, Yg (Middle Proterozoic) groups also contain granite, as well as megacrysts of K-feldspar. Outcrops in this group are composed of pegmatite, alaskite, and aplite.

Finally, metamorphic rocks are found in the Xm (Early Proterozoic) group. These have green schist, amphibolite-facies, metahypabyssal, and metaplutonic rocks.

Petrographic Results

TUMA S-13 contains several air bubbles, and does not have a coverslip like TUMA 25. This contributes to TUMA S-13's grainy appearance and pronounced alteration.

Most of the mineral found in both the exterior and interior sample indicate these were locally sourced. The identification matches the local geology, mostly igneous, granitic rocks (Tv, TKg, Jvs, Jg, Yg). Far more felsic minerals than mafic minerals were found for both samples.

Rock fragments in both samples are mostly identified as trachyandesite and andesite. For TUMA S-13, these rock fragments are very weathered. Upon close inspection, some small minerals are observed (100x). Some of these igneous rock fragments appear to be grading into a different rock, perhaps a high clay rock. Some trachyandesite fragments on both samples contain large phenocrysts of a heavily weathered mafic mineral.

Some andesite fragments found in TUMA S-13 appear to be metamorphosing with some alteration. The presence of the epidote indicates that is metamorphosing. Some andesite rock fragments are more intrusive and contain interlocking minerals. Andesite rock fragments for TUMA 25 contain less phenocrysts than other rock fragments, while others have a large inclusions of opaque minerals. Granite rock fragments on both samples have an ultramafic composition. There are more quartz inclusions than the in the Granite Rock group found for TUMA S-13. Some rock fragments for both samples contains inclusions of an altered mafic mineral that is very yellow and orange in color in both PPL and XPL.

Amphibolite rock fragments are found in the exterior plaster sample (TUMA 25), but not in TUMA S-13. Also, a larger amount of quartz and calcite minerals is found in TUMA 25 than in TUMA S-13. Potassium feldspar is also common in TUMA 25.

For TUMA 25, coarse sand appears to have been used as a filler. It also contains more individual minerals, such as calcite, than rock fragments in comparison to TUMA S-13. This might suggest the preparation of the binder for the interior and exterior plaster was different. This suggests the plaster for both the interior and exterior was prepared at different times.

Conclusion/Discussion

Most rock fragments are igneous rocks for both samples. Outcrops of metamorphic rock were far less abundant. Amphibolite rock fragments were also commonly found in TUMA 25. The rock fragments and minerals found in TUMA S-13 are slightly more weathered than those found in TUMA 25. However, this might be due the lack of coverslip on TUMA S-13. For TUMA S-13, the gypsum finish layer is very friable and there is a void underneath indicating it's detached. Conversely, the gypsum finish layer on the exterior plaster sample, TUMA 25, is attached to the rest of the layers.

Petrographic description of the fabric groups

Microstructure

TUMA S-13 (interior) is very porous and contains large voids. TUMA 25 (exterior) is porous, yet the voids are smaller in size and are evenly spaced amongst each other.

Groundmass

The matrix for both TUMA S-13 and TUMA 25 is a clay-silt matrix, mostly micrite clay. However, there is sparite silt as well with sand size crystals of calcite. It appears to be poorly consolidated. The color of the groundmass ranges from lighter browns to darker browns and to black in PPL. While in XPL, the groundmass is a darker brown. Overall, the samples have a lime binder.

Inclusions (c:f:v)

The inclusions in TUMA S-13 are very poorly sorted. The samples contains large fragments of rocks, as well as small particles. Inclusions in TUMA 25 are moderately sorted to poorly sorted. The amount of fines in TUMA 25 is larger than TUMA S-13

c:f:v_{0.125mm}= ca.45:35:20 (TUMA S-13) c:f:v_{0.125mm}= ca.25:65:10 (TUMA 25)

Group 1: TUMA S-13 (Interior Plaster Sample)

```
Fine Fraction (<0.125mm)
Predominant (>70%)
```

Calcite: Mostly found within the matrix. Light orange, pink color, <0.005mm, mode 0.005mm.

Few (5-15%)

Opaque (Red rim) Measurement typically less than 0.1mm. Typically well rounded, high sphericity, <0.12mm, mode 0.08mm. Contains reddish brown inclusions, and at times a red rim. Very few opaque minerals are square in shape.

Coarse Fraction (>0.125mm)

Dominant (50-70%)

Plagioclase Feldspar: Typically euhedral, subrounded and high sphericity. Albite twinning, <1.08mm, Mode in 0.38mm.

Orthoclase Feldspar: Typically euhedral, subrounded and high sphericity. Simple twinning, <0.38mm, Mode in 0.35mm.

Trachyandesite rock fragment: The rock is very weathered and contains fractures. The center spotting is smaller in size than the outline grains. The groundmass of this rock is brown in color and cloudy in appearance. It is very fine grained, and contains aphanitic grains in groundmass. The overall shape is subrounded with high sphericity. Mid-size rock fragment, <1.08mm, mode 0.7mm.

Rutile or Hematite? Found throughout rock fragment in different shapes: small thin veins, dots/ specks, rounded-high sphericity. However, it is too small to observe any additional details. Some of these inclusions are 0.3mm is size- Plagioclase Feldspar: Range of sizes: two 0.3mm ones found in rock fragment, rest are speckled and located throughout fragment. Mineral has albite twinning-Chloritic clay?: Yellow/Orange minerals within matrix. Alteration

mineral, perhaps a micaceous clay. Or chlorite as a clay. Has a greenish tint.

Other trachyandesite rock fragments have a finer sediment accumulated between minerals. Binder is dark (more binder than mineral grains). Some of the minerals are euhedral shaped, others are round shaped. Small rounded silica grains close to 0.10mm are found within the rock fragments. These radiate high order colors in XPL-Feldspar-Quartz-Biotite Mica-Opaque-Chlorite (inside rounded grains).

Frequent (30-50%)

Andesite rock fragment: Fragment appears to be Igneous that is being metamorphosed, with some alteration. Matrix is similar to the other rock fragment matrixes. It is brown, gray in color with very small white particles. Contains phenocrysts of feldspar, while others contain more phenocrysts of an altered mafic mineral. <1.8mm, Mode is 0.65mm.

Feldspar (weathered) - Epidote- Opaque minerals with red rim-Chloritic clay? Yellow/Orange minerals within matrix. Alteration mineral, perhaps a micaceous clay. Or chlorite as a clay. Has a greenish tint.

Other andesite rock fragments are more intrusive and contain interlocking minerals.

Calcite (weathered)- Epidote- Opaque minerals with red rim mostly 0.01mm in size- Chloritic clay?: Yellow/Orange minerals within matrix. Alteration mineral, perhaps a micaceous clay. Or chlorite as a clay. Has a greenish tint.

Granite rock fragment: These pyroclastic rocks contain interlocking grains, and almost no groundmass, except for the edges of the rock. Overall, shape is sub rounded, high sphericity. Some of the plagioclase feldspar grains within the rock fragment measure 0.6mm. <1.15mm, Mode is 0.65mm.

Plagioclase Feldspar- Rutile or Hematite? Found in minor amounts, look like veins- Opaque- Chlorite?: Very small, almost 0.025mm in

size. Faint green in PPL. High birefringence in XPL, but low relief. Small inclusion within the plagioclase feldspar.

Quartz Monzonite Porphyry rock fragment: Contains a vast quantity of mineral inclusions. Overall, it is plagioclase phenocryst (porphyries- fine grained rocks with large crystals) located within an altered groundmass, <1.73mm, Mode is 1.4mm.

Plagioclase Feldspar (spotty surface indicative of alteration, elongated, euhedral shape) - Quartz- Rutile or Hematite? Found in minor amounts. Veiny appearance. However, hard to detect due to how small the mineral grain is. - Opaque- Alteration of mafic minerals? Unable to determine. Very weathered and small. Yellow specs- Calcite grain (some have large calcite mineral) 0.7mm in size.

Common (15-30%)

Rhyolite rock fragments: Extrusive rock, containing phenocrysts of biotite and calcite. Moderate Relief. Overall well rounded with high sphericity. Matrix might be sparitic. More sand size particles. Matrix is mostly composed of gray and black specs, instead of brown specs like the other rocks. Some contain chlorite minerals altering to biotite. <0.95mm, Mode is 0.9mm.

Feldspar- chlorite- biotite- calcite; feldspar; Chlorite altering to biotite? Mineral is pleochroic, ranging from a very pale green to a brown green. It also appears to have a single plane of cleavage-opaque.

Calcite: A majority of the calcite minerals are very weathered, and might be going through alteration. Usually, these are distinguishable from feldspar due to the differing cleavage planes. Most of these grains are euhedral shaped. Some of the calcite found has simple twinning. <0.5mm, mode is 0.37mm.

Quartz: Very hard to distinguish from feldspar since sample is so weathered. Typically euhedral, subrounded and high sphericity, <0.2mm, Mode is 0.175mm.

Very Few (2-5%)

Few (5-15%)

Igneous rock fragment? Very weathered rock with only a few minerals, the rest is composed of very what appears to be a very weathered plagioclase feldspar. The rock fragment is distinguished by parallel lines across the fragment. More Intrusive than extrusive. Opaque minerals near the rock fragment but none located within the rock. <1.38mm, Mode is 0.8mm.

Quartz: too small to be able to differentiate. However, cleavage is not apparent- Feldspar: very weathered plagioclase feldspar with albite twinning- Biotite Mica: color increases with increasing Fe (iron content). Strong pleochroism: pale yellow to pale green to orange brown. Somewhat blotchy appearance- Chloritic clay? Yellow/Orange minerals within matrix. Alteration mineral, perhaps a micaceous clay. Or chlorite as a clay. Has a greenish tint.

Biotite: commonly found as long laths or euhedral shaped rectangles, 1 cleavage, pleochroism, some are 0.5 mm long and 0.02 mm thick. Some are a strong orange reddish color in PPL, <0.26mm, mode 0.20mm.

Very Rare (<0.5%)

Rare (0.5-2%)

Epidote: Mostly subrounded with low sphericity, <0.5mm, mode 0.35mm. More epidote is found within rock fragments, than as separate minerals.

Opaque (Red rim) typically well rounded, high sphericity, <0.6mm, no mode, average 0.34mm. Contains reddish brown inclusions, and at times a red rim.

Sanidine Feldspar Typically euhedral, subrounded and high sphericity, <0.4mm, Mode in 0.4mm.

Muscovite? Typically elongated. High birefringence colors, however grain is too small to define, <0.17mm, mode 0.15mm.

Group 2: TUMA 25 (Exterior plaster sample)

Fine Fraction (<0.125	mm)
Predominant (>70%)	
	Calcite: Grains mostly found within the matrix. Light orange, pink
	color, <0.005mm, mode 0.005mm.
Frequent (30-50%)	
	Quartz: Some are subrounded with high sphericity and anhedral,
	<0.1mm, mode 0.07mm.
Common (15-30%)	
· · ·	Epidote: Smaller minerals of epidote found within gypsum finish.
	Subrounded with low to high sphericity in shape. Very high relief,
	<0.125mm, mode 0.035mm.
Few (5-15%)	
100 (3 13/0)	Onaque: The onaque minerals have rutile or hematite in them
	<0.085mm mode 0.025mm
Very Few (2-5%)	
	Amphibale: Pleachraism ranges light green to dark green Less
	elongated than Biotite Mica. Initially the mineral appears to have a
	one plane cleavage but the angel at the edges suggests that it has
	two planes. It also is also subangular with low subaricity and
	mostly eubedral <0.075mm mode 0.075mm
$P_{aro} (0 5.2\%)$	
Nale (0.3-276)	Piotite: Has that characteristic red erange and yellow color as the
	biotite minorals observed in TLIMA S 12. In DDL it is pleashrois
	biotite initialis observed in TOWA 5-15. In PPL, it is predciroic
	ranging from a deep yellow orange color to a brown red color,
	similar to oxidized minerals, <0.1mm, mode 0.1mm.
	Plagiaciasa Foldspar <0.125mm mode 0.125mm
	Chlorite: Smaller minerals of chlorite found near enidote
	<0.1mm, mode 0.1mm.
	- ,
Very Rare (<0.5%)	
	Alteration of matic minerals? Unable to determine. Very
	weathered and small. Yellow orange in both PPL and XPL. Moderate
	biretringence in XPL, moderate relief. Some look like laths,
	<0.125mm, mode 0.125mm.

Coarse Fraction (>0.125mm) Dominant (50-70%)

Quartz: Some of the quartz observed are extremely weathered, and so it is hard to distinguish from calcite or feldspar. However, these did not show cleavage. Some are subrounded with high sphericity and anhedral, <0.5mm, mode 0.15mm.

Trachyandesite rock fragments: The rock fragment is light gray and dark brown, with a spotty appearance (PPL). It contains fractures. The center spotting is smaller in size than the outline grains. The groundmass of this rock is brown in color and cloudy in appearance. It is very fine grained, and contains aphanitic grains in groundmass. The overall shape is subrounded with high sphericity. <1.25mm, Mode is 1.25mm.

Micrite? Rounded grains, radiates high order colors in XPL. Cleavage is hard to detect, not a rhomb calcite either- Quartz-Plagioclase Feldspar- Rutile or Hematite? Found throughout rock fragment in different shapes: small thin veins, dots/ specks, and rounded-high sphericity. However, it is too small to observe any additional details- Chloritic clay? Yellow/Orange minerals within matrix. Alteration mineral, perhaps a micaceous clay. Or chlorite as a clay. Has a greenish tint- Biotite Mica (few mica inclusions): Angular, low sphericity, elongated.

Andesite rock fragment: Fragment appears to be Igneous that is being metamorphosed, with some alteration. Matrix is similar to the other rock fragment matrixes. It is brown, gray in color with small white grains. Some are elongated but some are more equant in shape within the matrix, <0.8mm, mode 0.75mm.

Feldspar-Quartz- Epidote- Opaque minerals with red rim- Chloritic clay? Yellow/Orange minerals within matrix. Alteration mineral, perhaps a micaceous clay. Or chlorite as a clay. Has a greenish tint-Biotite Mica (few mica inclusions): Angular, low sphericity, elongated.

Frequent (30-50%)

Plagioclase Feldspar: Typically euhedral, subrounded and high sphericity. Albite twinning, <0.625mm, Mode in 0.2mm.

Common (15-30%)

Few (5-15%)

Calcite: A majority of the calcite minerals are very weathered, and might be going through alteration. Usually, these are distinguishable from feldspar due to the differing cleavage planes. Most of these grains are euhedral shaped, almost a perfect triangle or rectangle, <0.45mm, mode 0.225mm.

Amphibolite rock fragment: Subangular with low sphericity. Mostly composed of amphibole and quartz. Matrix is gray in color with very small fragments. Large phenocrysts of Quartz compose the Amphibolite rock fragment. Smaller inclusions of what appears to be amphibole are also found as well. Very few amphibolite rock fragments contain green specs in PPL, which are black in XPL, and are non pleochroic. These are two small to characterize. <1.125mm, mode 0.25mm.

Quartz- Amphibole- Green Specs?

Chloritic Clay Fine Grain rock fragment? Subrounded with high sphericity. Deep yellow-orange-brown color in both XPL and PPL. No pleochroism. More of an intrusive rock, characterized by small inclusions. Radiating tones in lighter yellow mineral in XPL, <1.25mm, mode 0.625mm.

Quartz Monzonite Porphyry: (Igneous Group) Plagioclase phenocrysts (porphyries- fine grained rocks with large crystals) located within an altered groundmass. More of an aphanitic extrusive rock, <1.25mm, mode 0.25mm.

Plagioclase Feldspar- Quartz- Rutile or Hematite? Found in minor amounts. Veiny appearance. However, hard to detect due to how small the mineral grain is. - Opaque- Alteration of mafic minerals? Very weathered and small. Yellow specs- Calcite grain.

Potassium Feldspar (Sanidine): Very euhedral in shape. Two perfect planes of cleavage. Goes into extinction, but has no twinning. High Relief. <0.5mm, mode 0.45mm.

Orthoclase Feldspar: Typically euhedral, subrounded and high sphericity. Simple twinning, <0.25mm, mode 0.15mm.

Igneous rock fragment? Very weathered rock with only a few minerals, mostly composed of weathered plagioclase feldspar, <1mm, mode 0.35mm.

Feldspar, Quartz, Biotite Mica: color increases with increasing Fe (iron content). Strong pleochroism: pale yellow to pale green to orange brown-Chloritic clay? Yellow/Orange minerals within matrix. Alteration mineral, perhaps a micaceous clay. Or chlorite as a clay. Has a greenish tint.

Very Few (2-5%)

Granite: Pyroclastic rocks, interlocking grains, and almost no groundmass. This rock group appears to have an ultramafic composition. Overall shape is subrounded to subangular, low sphericity. Some of the plagioclase feldspar grains measuring 2mm within a 2mm fragment, <2.2mm, mode 1.5mm.

Plagioclase Feldspar (weathered) - Quartz- Rutile or Hematite: Found in minor amounts, look like veins- Opaque- Alteration of mafic minerals? Very weathered and small. Yellow specs. Moderate birefringence in XPL, moderate relief. Small inclusion within the matrix- Calcite

Rhyolite: Some are extremely weathered. Overall well rounded with high sphericity. Matrix might be sparitic. More sand size particles, <0.8mm, mode 0.25mm.

Feldspar- Chlorite altering to biotite- Biotite- Calcite- Opaque.

Opaque: (Red rim) typically well rounded, high sphericity. Contains reddish brown inclusions, and at times a red rim, <0.25mm, mode 0.2mm.

Amphibole, <0.625mm, mode 0.25mm.

Chlorite, <0.2mm, mode 0.15mm.

Epidote: Mostly subrounded with low sphericity, <0.25mm, mode 0.2mm.

Rare (0.5-2%) **Biotite:** commonly found as long laths or euhedral shaped rectangles, 1 cleavage, and pleochroism. Some are a strong orange reddish color in PPL, <1mm, mode 0.15mm. Very Rare (<0.5%) Isotropic Mineral, <0.2mm, mode 0.2mm. **Photomicrographs:**

Group 1: TUMA S-13 (interior plaster sample)



SAMPLE TUMA S-13 Thin Section (PPL)

ORIGIN: Mission San José de Tumacácori, Tumacácori National Historic Park (Tucson, Arizona) RECEIVED: January 2017

IMAGING: AxioVision Material Science Software for Research and Engineering

MICROSCOPE: Zeiss AX10

OBJECTIVE: 50 x ZOOM: N/A

TRINOCULAR MAG: 1 x LIGHT SOURCE: halogen

FILTERS: daylight COLOR TEMP: N/A

Figure: Thin section of TUMA S-13 (PPL) obtained from the interior plaster of the Nave East Wall.



SAMPLE TUMA S-13 Thin Section (XPL)

ORIGIN: Mission San José de Tumacácori, Tumacácori National Historic Park (Tucson, Arizona) RECEIVED: January 2017

IMAGING: AxioVision Material Science Software for Research and Engineering

MICROSCOPE: Zeiss AX10

OBJECTIVE: 50 x ZOOM: N/A

TRINOCULAR MAG: 1 x LIGHT SOURCE: halogen

FILTERS: daylight COLOR TEMP: N/A

Figure: Thin section of TUMA S-13 (XPL) obtained from the interior plaster of the Nave East Wall.

Group 2: TUMA 25 (exterior plaster sample)



Figure: Thin section of TUMA 25 (XPL) obtained from the exterior façade.

Appendix B: Characterization of Soils

Combined Wet and Dry Sieving Results

	М хт (g) Weight of Sample	Μ cτ (g) Weight of evaporating dish	M₁(g) Total weight of coarse particles	M sτ (g) Weight of coarse soil particles	After Sieving	Margin of Error
ADOBE	164.57	405.98	531.72	125.74	125.58	0.12724 7
SOIL A	154.46	369.7	478.17	108.47	108.4	0.06453 4
SOIL B	159.45	376.11	478.92	102.81	102.65	0.15562 7
SOIL E	153.73	372.53	456.54	84.01	83.94	0.08332 3

SOIL A

			SOIL A SIE	VE TEST DA	TA		
ASTM Sieve Number	Screen Size (μm)	Mass of container (g)	Mass of sample & container (g)	Mass retained (g)	Percent mass retained	Percent on or above	Percent Passing
				M _r	%M _r	%M _{rt}	%M _{pt}
		Mc	M ₂	(M ₂ - M _c)	(M _r /M _s)	Σ %Mr	100% - M _{rt} %
					*100%	(on or above)	
8	2360	2	12.09	10.09	9.31	9.31	90.69
16	1180	1.88	12.15	10.27	9.47	18.78	81.22
30	600	1.88	12.78	10.9	10.06	28.84	71.16
50	300	1.8	17.8	16	14.76	43.60	56.40
100	150	1.8	35.6	33.8	31.18	74.78	25.22
200	75	1.86	22.64	20.78	19.17	93.95	6.05
PAN	0	1.84	8.4	6.56	6.05	100.00	0.00
				108.4	100		

SOIL B							
			SOIL B SIEVE	TEST DATA	4		
ASTM Sieve	Screen Size	Mass of	Mass of Sample & Mass Percer		Percent	Percent on	Percent
Number	(μm)	(g)	container (g)	container retained retained (g) (g) a		or above	Passing
				Mr	%M _r	%M _{rt}	%M _{pt}
		Mc	M ₂	(M ₂ - M _c)	(Mr/Ms)	Σ %M _r	100% - M _{rt} %
					*100%	(on or above)	
8	2360	1.86	6.98	5.12	4.99	4.99	95.01
16	1180	1.85	8.46	6.61	6.44	11.43	88.57
30	600	2.12	12.40	10.28	10.01	21.44	78.56
50	300	2.11	25.04	22.93	22.34	43.78	56.22
100	150	2.04	36.19	34.15	33.27	77.05	22.95
200	75	1.95	18.88	16.93	16.49	93.54	6.46
PAN	0	1.85	8.48	6.63	6.46	100.00	0.00
				102.65	100.00		

SOIL E

			SOIL E SIEVE	TEST DATA	4		
ASTM Sieve Number	Screen Size (μm)	Mass of container (g)	Mass of sample & container (g)	Mass retained (g)	Percent mass retained	Percent on or above	Percent Passing
				M _r	%Mr	%M _{rt}	%M _{pt}
		Mc	M ₂	(M ₂ - M _c)	(M _r /M _s)	Σ %M _r	100% - M _{rt} %
					*100%	(on or above)	
	2360	1.96	7.17	5.21	6.21	6.21	93.79
16	1180	1.99	13.80	11.81	14.07	20.28	79.72
30	600	1.96	14.67	12.71	15.14	35.42	64.58
50	300	2.00	19.17	17.17	20.46	55.88	44.12
100	150	1.81	24.45	22.64	26.97	82.85	17.15
200	75	1.96	12.51	10.55	12.57	95.42	4.58
PAN	0	1.90	5.75	3.85	4.59	100.00	0.00
				83.94	100.00		

ADOBE							
			ADOBE S	SIEVE TEST	DATA		
ASTM Sieve	Screen Size	Mass of container	Mass of sample &	Mass	Percent mass	Percent on	Percent
Number	(µm)	(g)	container (g)	retained (g)	retained	or above	Passing
				Mr	%M r	%M _{rt}	%M _{pt}
		Mc	M ₂	(M ₂ - M _c)	(Mr/Ms)	Σ %M _r	100% - M _{rt} %
					*100%	(on or above)	
8	2360	1.82	7.28	5.46	4.35	4.35	95.65
16	1180	1.93	10.88	8.95	7.13	11.48	88.52
30	600	1.95	20.19	18.24	14.52	26.00	74.00
50	300	1.95	43.75	41.8	33.29	59.29	40.71
100	150	1.88	44.62	42.74	34.03	93.32	6.68
200	75	1.89	8.71	6.82	5.43	98.75	1.25
PAN	0	1.88	3.45	1.57	1.25	100.00	0.00
				125.58	100.00		

_	Coarse Sand	Medium Sand	Fine Sand	Fines	Total
ADOBE	4.35	21.65	67.32	6.68	100.00
SOIL A	9.31	19.53	45.94	25.22	100.00
SOIL B	4.99	16.45	55.61	22.95	100.00
SOIL E	6.21	29.21	47.43	17.16	100.00



SOIL A	
Weight of beaker (g)	200.62
Total weight of sample	
(g)	355.08
Weight of the soil	
sample (g)	154.46

								After Meniscus		1									
	Time of	Elapsed		Hydrometer Reading			Meniscus	Correction	X (Dispersion		Corrected			% Finer of	Effective Depth				
Date	reading	time (min)	Temp (C°)	(Ra)	A	В	Correction (Ra)	(Rmc)	Agent correction)	Ct	Reading (Rc)	a	Ws	whole sample	(L)	L/t	к	D (mm)	D (µm)
1/24/2017	5:15 PM	0.5	18	48	0	0.001	1	49	4.6	-0.5	42.9	0.99	154.46	27.50	8.3	16.6	0.0138	4.07430976	4074.31
1/24/2017	5:16 PM	1	18	47	0	0.001	1	48	4.6	-0.5	41.9	0.99	154.46	26.86	8.4	8.4	0.0138	2.89827535	2898.28
1/24/2017	5:17 PM	2	18	45	0	0.001	1	46	4.6	-0.5	39.9	0.99	154.46	25.57	8.8	4.4	0.0138	2.0976177	2097.62
1/24/2017	5:19 PM	4	18	43	0	0.001	1	44	4.6	-0.5	37.9	0.99	154.46	24.29	9.1	2.275	0.0138	1.50831031	1508.31
1/24/2017	5:23 PM	8	18	40	0	0.001	1	41	4.6	-0.5	34.9	0.99	154.46	22.37	9.6	1.2	0.0138	1.09544512	1095.45
1/24/2017	5-30 PM	15	18	37	0	0.001	1	38	4.6	-0.5	31.9	0.99	154.46	20.45	10.1	0 673333333	0.0138	0.82056891	820.57
1/24/2017	5:45 PM	30	18	34	0	0.001	1	35	4.6	-0.5	28.9	0.99	154.46	18.52	10.1	0.35	0.0138	0.59160798	591.61
1/24/2017	6.15 DM	60	10	20	0	0.001	-	21	4.0	0.5	20.5	0.99	154.46	15.05	11.3	0 196666667	0.0130	0.42204028	122.05
1/24/2017	7.15 PM	120	10	30	0	0.001	4	31	4.0	-0.5	24.5	0.99	154.40	13.50	11.2	0.180000007	0.0138	0.43204338	432.03
1/24/2017	7.15 PIVI	120	10	20	0	0.001	-	27	4.0	-0.5	20.9	0.99	154.40	13.40	11.5	0.099100007	0.0136	0.31490739	514.51
1/25/2017	3:00 PM	1335	1/	24	0	0.001	1	25	4.6	-0.7	18./	0.99	154.46	11.99	12.2	0.009138577	0.014	0.0955959	95.60
1/25/2017	6:00 PM	1515	16	22	0	0.001	1	23	4.6	-0.9	16.5	0.99	154.46	10.58	12.5	0.008250825	0.0141	0.09083405	90.83
1/26/2017	3:00 PM	2775	17	21	0	0.001	1	22	4.6	-0.7	15.7	0.99	154.46	10.06	12.7	0.004576577	0.014	0.0676504	67.65
1/26/2017	5:00 PM	2895	17	21	0	0.001	1	22	4.6	-0.7	15.7	0.99	154.46	10.06	12.7	0.004386874	0.014	0.06623348	66.23
1/26/2017	10:00 PM	3195	17	20.5	0	0.001	1	21.5	4.6	-0.7	15.2	0.99	154.46	9.74	12.8	0.00400626	0.014	0.06329502	63.30
1/27/2017	3:00 PM	4215	17	20	0	0.001	1	21	4.6	-0.7	14.7	0.99	154.46	9.42	12.9	0.003060498	0.014	0.05532177	55.32
1/27/2017	10:00 PM	4635	16	20	0	0.001	1	21	4.6	-0.9	14.5	0.99	154.46	9.29	12.9	0.002783172	0.0141	0.05275577	52.76
1/28/2017	3:00 PM	5655	15.5	20	0	0.001	1	21	4.6	-1	14.4	0.99	154.46	9.23	12.9	0.002281167	0.0146	0.04776157	47.76
1/30/2017	6:00 PM	8715	15	19	0	0.001	1	20	4.6	-1.1	13.3	0.99	154.46	8.52	13	0.001491681	0.0142	0.03862229	38.62
1/31/2017	10:00 PM	10395	15	19	0	0.001	1	20	4.6	-1.1	13.3	0.99	154.46	8.52	13	0.001250601	0.0142	0.03536384	35.36
2/2/2017	10:00 PM	13275	16	20	0	0.001	1	21	4.6	-0.9	14.5	0.99	154.46	9.29	12.9	0.000971751	0.0141	0.03117293	31.17
2/6/17	6:00 PM	18795	16	19	0	0.001	1	20	4.6	-0.9	13.5	0.99	154.46	8.65	13	0.000691673	0.0141	0.02629968	26.30
2/9/17	7:00 PM	23175	16	19	0	0.001	1	20	4.6	-0.9	13.5	0.99	154.46	8.65	13	0.000560949	0.0141	0.02368437	23.68
2/12/17	4:00 PM	27315	16	19	0	0.001	1	20	4.6	-0.9	13.5	0.99	154.46	8.65	13	0.000475929	0.0141	0.0218158	21.82
2/14/17	8:00 PM	30435	16	19	0	0.001	1	20	4.6	-0.9	13.5	0.99	154.46	8.65	13	0.00042714	0.0141	0.02066736	20.67
2/16/17	7:00 PM	33255	17	18.5	0	0.001	1	19.5	4.6	-0.7	13.2	0.99	154.46	8.46	13.1	0.000393926	0.0141	0.01984756	19.85
2/18/17	2:00 PM	35835	16	19.5	0	0.001	1	20.5	4.6	-0.9	14	0.99	154.46	8.97	12.95	0.000361379	0.0141	0.01900996	19.01
2/22/17	10:00 PM	42075	19	19	0	0.001	1	20	4.6	-0.3	14.1	0.99	154.46	9.04	13	0.000308972	0.0136	0.0175776	17.58
2/24/17	8:00 PM	44835	21	18	0	0.001	1	19	4.6	0.2	13.6	0.99	154.46	8.72	13.2	0.000294413	0.0133	0.01715846	17.16
2/27/17	9:00 PM	49215	19	18	0	0.001	1	19	4.6	-0.3	13.1	0.99	154.46	8.40	13.2	0.000268211	0.0136	0.01637715	16.38
3/1/17	10:00 PM	52155	19.5	18	0	0.001	1	19	4.6	-0.3	13.1	0.99	154.46	8.40	13.2	0.000253092	0.0139	0.01590886	15.91
3/4/17	8.00 PM	56355	15.5	18.5	0	0.001	1	19.5	4.6	-0.5	13.75	0.99	154.46	8.81	13.1	0.000233052	0.0133	0.01524647	15.25
2/7/17	11:00 PM	60955	10	10.5	0	0.001	1	10	4.0	0.15	12.1	0.99	154.46	8.40	12.2	0.000232433	0.0142	0.01324047	14.72
2/10/17	10.00 PM	65115	15	10	0	0.001	1	19	4.0	-0.3	14.4	0.99	154.40	0.22	13.2	0.000210903	0.0130	0.01472783	14.75
3/10/17	10:00 PM	60215	10	19	0	0.001		20	4.0	0.15	14.4	0.99	154.40	9.23	13	0.000199647	0.0141	0.01412964	14.15
3/13/17	8:00 PIVI	69315	10	18.5	0	0.001		19.5	4.0	-0.15	13./5	0.99	154.46	8.81	13.1	0.000188992	0.0141	0.013/4/45	13.75
3/15/17	11:00 PM	72375	16	18.5	0	0.001	1	19.5	4.6	-0.15	13.75	0.99	154.46	8.81	13.1	0.000181002	0.0141	0.01345369	13.45
3/1//1/	10:00 PM	/5195	16.5	18.5	0	0.001	1	19.5	4.6	-0.15	13./5	0.99	154.46	8.81	13.1	0.000174214	0.0145	0.013199	13.20
3/20/17	11:00 PM	79455	17	18	0	0.001	1	19	4.6	-0.3	13.1	0.99	154.46	8.40	13.2	0.000166132	0.014	0.01288921	12.89
3/23/17	10:00 PM	83715	16.5	18	0	0.001	1	19	4.6	-0.3	13.1	0.99	154.46	8.40	13.2	0.000157678	0.0145	0.01255698	12.56
3/26/17	3:00 PM	87615	17.5	17.5	0	0.001	1	18.5	4.6	-0.4	12.5	0.99	154.46	8.01	13.25	0.00015123	0.0139	0.01229755	12.30
3/29/17	7:00 PM	92175	20	17	0	0.001	1	18	4.6	-0.5	11.9	0.99	154.46	7.63	13.3	0.000144291	0.0134	0.01201211	12.01
4/2/17	6:00 PM	97875	20	16	0	0.001	1	17	4.6	-0.7	10.7	0.99	154.46	6.86	13.5	0.000137931	0.0134	0.0117444	11.74
4/5/17	7:00 PM	102255	18	16	0	0.001	1	17	4.6	-0.7	10.7	0.99	154.46	6.86	13.5	0.000132023	0.0138	0.01149012	11.49
4/9/17	7:00 PM	108015	18	18	0	0.001	1	19	4.6	-0.3	13.1	0.99	154.46	8.40	13.2	0.000122205	0.0138	0.01105465	11.05
4/13/17	7:00 PM	113775	20	18	0	0.001	1	19	4.6	-0.3	13.1	0.99	154.46	8.40	13.2	0.000116018	0.0134	0.01077119	10.77
4/17/17	6:00 PM	119475	22	14	0	0.001	1	15	4.6	0.7	10.1	0.99	154.46	6.47	13.8	0.000115505	0.0131	0.01074734	10.75

264.68
424.13
159.45

							Maniscus	Meniscus (Corrected	X (Dispersion		Corrected			% Finer of			l l		
Date	ne of readi	insed time (n	Temp (C°)	vdrometer Reading (Re	Δ.	в	Correction (Ra)	Reading) (Rmc)	Agent correction)	Ct	Reading (Rc)	a	Ws	whole sample	1	L/t	к	D (mm)	D (um)
1/24/2017	5.15 PM	0.5	18	59	0	0.001	1	60	4.6	-0.5	53.9	0.99	159.45	33.80	66	13.2	0.0138	0 1174734	117 4734
1/24/2017	5:16 PM	1	18	57	0	0.001	1	58	4.6	-0.5	51.9	0.99	159.45	32.55	7	7	0.0138	0.1174734	117.4734
1/24/2017	5:17 PM	2	18	56	0	0.001	1	57	4.6	-0.5	50.9	0.99	159.45	31.92	71	#VALUE!	0.0138	0.1174734	117.4734
1/24/2017	5:19 PM	4	18	54	0	0.001	1	55	4.6	-0.5	48.9	0.99	159.45	30.67	7.4	1.85	0.0138	0.1174734	117.4734
1/24/2017	5:23 PM	8	18	52	0	0.001	1	53	4.6	-0.5	46.9	0.99	159.45	29.41	7.8	0.975	0.0138	0.1174734	117.4734
1/24/2017	5:30 PM	15	18	49	0	0.001	1	50	4.6	-0.5	43.9	0.99	159.45	27.53	8.3	0.5533333333	0.0138	0.1174734	117.4734
1/24/2017	5:45 PM	30	18	44	0	0.001	1	45	4.6	-0.5	38.9	0.99	159.45	24.40	9.1	0.303333333	0.0138	0.1174734	117.4734
1/24/2017	6:15 PM	60	18	41	0	0.001	1	42	4.6	-0.5	35.9	0.99	159.45	22.51	9.6	0.16	0.0138	0.1174734	117.4734
1/24/2017	7:15 PM	120	18	38	0	0.001	1	39	4.6	-0.5	32.9	0.99	159.45	20.63	10.1	0.084166667	0.0138	0.1174734	117.4734
1/25/2017	3:00 PM	1335	17	34	0	0.001	1	35	4.6	-0.7	28.7	0.99	159.45	18.00	10.7	0.008014981	0.014	0.1183216	118.3216
1/25/2017	6:00 PM	1515	16	31	0	0.001	1	32	4.6	-0.9	25.5	0.99	159.45	15.99	11.2	0.007392739	0.0141	0.11874342	118.7434
1/26/2017	3:00 PM	2775	17	29	0	0.001	1	30	4.6	-0.7	23.7	0.99	159.45	14.86	11.5	0.004144144	0.014	0.1183216	118.3216
1/26/2017	5:00 PM	2895	17	29	0	0.001	1	30	4.6	-0.7	23.7	0.99	159.45	14.86	11.5	0.003972366	0.014	0.1183216	118.3216
1/26/2017	10:00 PM	3195	17	28	0	0.001	1	29	4.6	-0.7	22.7	0.99	159.45	14.24	11.7	0.003661972	0.014	0.1183216	118.3216
1/27/2017	3:00 PM	4215	17	27.5	0	0.001	1	28.5	4.6	-0.7	22.2	0.99	159.45	13.92	11.8	0.002799526	0.014	0.1183216	118.3216
1/27/2017	10:00 PM	4635	16	27	0	0.001	1	28	4.6	-0.9	21.5	0.99	159.45	13.48	11.9	0.002567422	0.0141	0.11874342	. 118.7434
1/28/2017	3:00 PM	5655	15.5	27	0	0.001	1	28	4.6	-1	21.4	0.99	159.45	13.42	11.9	0.002104332	0.0146	0.12083046	120.8305
1/30/2017	6:00 PM	8715	15	26	0	0.001	1	27	4.6	-1.1	20.3	0.99	159.45	12.73	12	0.001376936	0.0142	0.11916375	119.1638
1/31/2017	10:00 PM	10395	15	25.5	0	0.001	1	26	4.6	-1.1	19.8	0.99	159.45	12.42	12.1	0.001164021	0.0142	0.11916375	119.1638
2/2/2017	10:00 PM	13275	16	23	0	0.001	1	24	4.6	-0.9	17.5	0.99	159.45	10.98	12.5	0.00094162	0.0141	0.11874342	. 118.7434
2/6/17	6:00 PM	18795	16	23	0	0.001	1	24	4.6	-0.9	17.5	0.99	159.45	10.98	12.5	0.00066507	0.0141	0.11874342	118.7434
2/9/17	7:00 PM	23175	16	21	0	0.001	1	22	4.6	-0.9	15.5	0.99	159.45	9.72	12.9	0.000556634	0.0141	0.11874342	. 118.7434
2/12/17	4:00 PM	27315	16	20	0	0.001	1	21	4.6	-0.9	14.5	0.99	159.45	9.09	13	0.000475929	0.0141	0.11874342	118.7434
2/14/17	8:00 PM	30435	16	17	0	0.001	1	18	4.6	-0.9	11.5	0.99	159.45	7.21	13.5	0.000443568	0.0141	0.11874342	118.7434
2/16/17	7:00 PM	33255	17	16	0	0.001	1	17	4.6	-0.7	10.7	0.99	159.45	6.71	13.7	0.000411968	0.0141	0.11874342	118.7434
2/18/17	2:00 PM	35835	16	14	0	0.001	1	15	4.6	-0.9	8.5	0.99	159.45	5.33	14	0.00039068	0.0141	0.11874342	118.7434
2/22/17	10:00 PM	42075	19	12	0	0.001	1	13	4.6	-0.3	7.1	0.99	159.45	4.45	14.3	0.000339869	0.0136	0.11661904	116.619
2/24/17	8:00 PM	44835	21	11.5	0	0.001	1	12.5	4.6	0.2	7.1	0.99	159.45	4.45	14.4	0.000321178	0.0133	0.11532563	115.3256
2/27/17	9:00 PM	49215	19	11.5	0	0.001	1	12.5	4.6	-0.3	6.6	0.99	159.45	4.14	14.4	0.000292594	0.0136	0.11661904	116.619
3/1/17	10:00 PM	52155	19.5	11.5	0	0.001	1	12.5	4.6	-0.3	6.6	0.99	159.45	4.14	14.4	0.0002761	0.0139	0.11789826	117.8983
3/4/17	8:00 PM	56355	15	12	0	0.001	1	13	4.6	-0.15	7.25	0.99	159.45	4.55	14.3	0.000253749	0.0142	0.11916375	119.1638
3/7/17	11:00 PM	60855	19	11.5	0	0.001	1	12.5	4.6	-0.3	6.6	0.99	159.45	4.14	14.4	0.000236628	0.0136	0.11661904	116.619
3/10/17	10:00 PM	65115	16	11	0	0.001	1	12	4.6	0	6.4	0.99	159.45	4.01	14.5	0.000222683	0.0141	0.11874342	118.7434
3/13/17	8:00 PM	69315	16	11	0	0.001	1	12	4.6	-0.15	6.25	0.99	159.45	3.92	14.5	0.00020919	0.0141	0.11874342	. 118.7434
3/15/17	11:00 PM	72375	16	11	0	0.001	1	12	4.6	-0.15	6.25	0.99	159.45	3.92	14.5	0.000200345	0.0141	0.11874342	. 118.7434
3/17/17	10:00 PM	75195	16.5	11	0	0.001	1	12	4.6	-0.15	6.25	0.99	159.45	3.92	14.5	0.000192832	0.0145	0.12041595	120.4159
3/20/17	11:00 PM	79455	17	11	0	0.001	1	12	4.6	-0.3	6.1	0.99	159.45	3.83	14.5	0.000182493	0.014	0.1183216	118.3216
3/23/17	10:00 PM	83715	16.5	10.5	0	0.001	1	11.5	4.6	-0.3	5.6	0.99	159.45	3.51	14.6	0.000174401	0.0145	0.12041595	120.4159
3/26/17	3:00 PM	87615	17.5	10	0	0.001	1	11	4.6	-0.4	5	0.99	159.45	3.14	14.7	0.000167779	0.0139	0.11789826	117.8983
3/29/17	7:00 PM	92175	20	10	0	0.001	1	11	4.6	-0.5	4.9	0.99	159.45	3.07	14.7	0.000159479	0.0134	0.11575837	115.7584
4/2/17	6:00 PM	97875	20	9.5	0	0.001	1	10.5	4.6	-0.7	4.2	0.99	159.45	2.63	14.75	0.000150702	0.0134	0.11575837	115.7584
4/5/17	7:00 PM	102255	18	9.5	0	0.001	1	10.5	4.6	-0.7	4.2	0.99	159.45	2.63	14.75	0.000144247	0.0138	0.1174734	117.4734
4/9/17	7:00 PM	108015	18	9	0	0.001	1	10	4.6	-0.3	4.1	0.99	159.45	2.57	14.8	0.000137018	0.0138	0.1174734	117.4734
4/13/17	7:00 PM	113775	20	9	0	0.001	1	10	4.6	-0.3	4.1	0.99	159.45	2.57	14.8	0.000130081	0.0134	0.11575837	115.7584
4/17/17	6:00 PM	119475	22	8	0	0.001	1	9	4.6	0.7	4.1	0.99	159.45	2.57	15	0.000125549	0.0131	0.11445523	114.4552

SOIL E	
Weight of beaker (g)	178.24
Total weight of sample	
(g)	331.97
Weight of the soil	
sample (g)	153.73

								Meniscus										
		× 0					Meniscus	(Corrected	X (Dispersion		Corrected		61.02	% Finer of		00000		2000 B 60 6
Date	ne of readi	ipsed time (n	r Temp (C°)	ydrometer Reading (Re	A	В	Correction (Ra)	Reading) (Rmc)	Agent correction)	Cł	Reading (Rc)	a	Ws	whole sample	L	L/t	к	D (mm) D (μm)
1/24/2017	5:15 PM	0.5	18	64	0	0.001	1	65	4.6	-0.5	58.9	0.99	153.73	38.31	5.9	11.8	0.0138	3.43511281 3435.113
1/24/2017	5:16 PM	1	18	63	0	0.001	1	64	4.6	-0.5	57.9	0.99	153.73	37.66	6	6	0.0138	2.44948974 2449.49
1/24/2017	5:17 PM	2	18	60	0	0.001	1	61	4.6	-0.5	54.9	0.99	153.73	35.71	6.5	3.25	0.0138	1.80277564 1802.776
1/24/2017	5:19 PM	4	18	57	0	0.001	1	58	4.6	-0.5	51.9	0.99	153.73	33.76	7	1.75	0.0138	1.32287566 1322.876
1/24/2017	5:23 PM	8	18	55	0	0.001	1	56	4.6	-0.5	49.9	0.99	153.73	32.46	7.3	0.9125	0.0138	0.95524866 955.2487
1/24/2017	5:30 PM	15	18	52	0	0.001	1	53	4.6	-0.5	46.9	0.99	153.73	30.51	7.8	0.52	0.0138	0.72111026 721.1103
1/24/2017	5:45 PM	30	18	49	0	0.001	1	50	4.6	-0.5	43.9	0.99	153.73	28.56	8.3	0.276666667	0.0138	0.52599113 525.9911
1/24/2017	6:15 PM	60	18	46	0	0.001	1	47	4.6	-0.5	40.9	0.99	153.73	26.61	8.8	0.146666667	0.0138	0.38297084 382.9708
1/24/2017	7:15 PM	120	18	43	0	0.001	1	44	4.6	-0.5	37.9	0.99	153.73	24.65	9.2	0.076666667	0.0138	0.27688746 276.8875
1/25/2017	3:00 PM	1335	17	34	0	0.001	1	35	4.6	-0.7	28.7	0.99	153.73	18.67	10.7	0.008014981	0.014	0.08952643 89.52643
1/25/2017	6:00 PM	1515	16	31	0	0.001	1	32	4.6	-0.9	25.5	0.99	153.73	16.59	11.2	0.007392739	0.0141	0.08598104 85.98104
1/26/2017	3:00 PM	2775	17	29	0	0.001	1	30	4.6	-0.7	23.7	0.99	153.73	15.42	11.5	0.004144144	0.014	0.06437503 64.37503
1/26/2017	5:00 PM	2895	17	29	0	0.001	1	30	4.6	-0.7	23.7	0.99	153.73	15.42	11.5	0.003972366	0.014	0.06302671 63.02671
1/26/2017	10:00 PM	3195	17	28	0	0.001	1	29	4.6	-0.7	22.7	0.99	153.73	14.77	11.7	0.003661972	0.014	0.06051423 60.51423
1/27/2017	3:00 PM	4215	17	27	0	0.001	1	28	4.6	-0.7	21.7	0.99	153.73	14.12	11.9	0.00282325	0.014	0.05313427 53.13427
1/27/2017	10:00 PM	4635	16	26.5	0	0.001	1	27.5	4.6	-0.9	21	0.99	153,73	13.66	11.95	0.002578209	0.0141	0.05077607 50.77607
1/28/2017	3:00 PM	5655	15.5	26	0	0.001	1	27	4.6	-1	20.4	0.99	153,73	13.27	12	0.002122016	0.0146	0.04606534 46.06534
1/30/2017	6:00 PM	8715	15	25	0	0.001	1	26	4.6	-11	19.3	0.99	153.73	12.55	12.2	0.001399885	0.0142	0.03741504 37.41504
1/31/2017	10:00 PM	10395	15	24.5	0	0.001	1	25.5	4.6	-1.1	19.5	0.99	153.73	12.55	12.2	0.001183261	0.0142	0.03/39856 3/ 39856
2/2/2017	10:00 PM	13275	15	24.5	0	0.001	1	23.5	4.0	-1.1	17.5	0.99	153.73	11 38	12.5	0.0001183201	0.0142	0.03068582 30.68582
2/2/2017	6:00 PM	19705	16	23	0	0.001	1	24	4.0	-0.5	17.5	0.99	153.73	11.50	12.5	0.00054102	0.0141	0.03000302 30.00302
2/0/17	7:00 PM	22175	10	23	0	0.001	1	24	4.0	-0.9	17.5	0.99	153.73	10.72	12.5	0.000548004	0.0141	0.02378890 23.78890
2/3/17	7:00 PIVI	25175	10	22	0	0.001	1	23	4.0	-0.9	10.5	0.99	153.73	10.73	12.7	0.000348004	0.0141	0.02340949 23.40949
2/12/17	4:00 PM	2/313	16	10	0	0.001	1	22	4.0	-0.9	12.5	0.99	153.73	0.08	12.9	0.000472208	0.0141	0.021/31/3 21./31/3
2/14/17	3.00 PM	30433	10	19	0	0.001	1	20	4.0	-0.9	13.5	0.99	153.73	0.70	13.2	0.000433711	0.0141	0.02082373 20.82373
2/10/17	7:00 PM	33255	1/	18.5	0	0.001	1	19.5	4.0	-0.7	13.2	0.99	153./3	8.59	13.25	0.000398436	0.0141	0.01996087 19.96087
2/18/17	2:00 PM	35835	10	17.5	0	0.001	1	18.5	4.0	-0.9	12	0.99	153./3	7.81	13.4	0.000373936	0.0141	0.01933743 19.33743
2/22/17	10:00 PM	42075	19	14.5	0	0.001	1	15.5	4.0	-0.3	9.6	0.99	153.73	6.24	13.9	0.000330362	0.0136	0.0181/588 18.1/588
2/24/17	8:00 PM	44835	21	13	0	0.001	1	14	4.6	0.2	8.6	0.99	153./3	5.59	14.2	0.000316/1/	0.0133	0.017/9654 17.79654
2/2//1/	9:00 PM	49215	19	12.5	0	0.001	1	13.5	4.6	-0.3	7.6	0.99	153./3	4.94	14.25	0.000289546	0.0136	0.01/01605 1/.01605
3/1/17	10:00 PM	52155	19.5	12	0	0.001	1	13	4.6	-0.3	7.1	0.99	153./3	4.62	14.3	0.000274183	0.0139	0.01655846 16.55846
3/4/17	8:00 PM	56355	15	12.5	0	0.001	1	13.5	4.6	-0.15	7.75	0.99	153./3	5.04	14.25	0.000252861	0.0142	0.01590161 15.90161
3///1/	11:00 PM	60855	19	11.5	0	0.001	1	12.5	4.6	-0.3	6.6	0.99	153./3	4.29	14.4	0.000236628	0.0136	0.01538272 15.38272
3/10/17	10:00 PM	65115	16	12	0	0.001	1	13	4.6	0	7.4	0.99	153./3	4.81	14.3	0.000219611	0.0141	0.01481929 14.81929
3/13/17	8:00 PM	69315	16	12	0	0.001	1	13	4.6	-0.15	7.25	0.99	153.73	4.72	14.3	0.000206305	0.0141	0.01436331 14.36331
3/15/17	11:00 PM	72375	16	12	0	0.001	1	13	4.6	-0.15	7.25	0.99	153.73	4.72	14.3	0.000197582	0.0141	0.01405639 14.05639
3/17/17	10:00 PM	75195	16.5	11.5	0	0.001	1	12.5	4.6	-0.15	6.75	0.99	153.73	4.39	14.4	0.000191502	0.0145	0.01383843 13.83843
3/20/17	11:00 PM	79455	17	11.5	0	0.001	1	12.5	4.6	-0.3	6.6	0.99	153.73	4.29	14.4	0.000181235	0.014	0.01346234 13.46234
3/23/17	10:00 PM	83715	16.5	11.5	0	0.001	1	12.5	4.6	-0.3	6.6	0.99	153.73	4.29	14.4	0.000172012	0.0145	0.01311534 13.11534
3/26/17	3:00 PM	87615	17.5	11.5	0	0.001	1	12.5	4.6	-0.4	6.5	0.99	153.73	4.23	14.4	0.000164355	0.0139	0.01282012 12.82012
3/29/17	7:00 PM	92175	20	11	0	0.001	1	12	4.6	-0.5	5.9	0.99	153.73	3.84	14.5	0.000157309	0.0134	0.01254231 12.54231
4/2/17	6:00 PM	97875	20	10	0	0.001	1	11	4.6	-0.7	4.7	0.99	153.73	3.06	14.7	0.000150192	0.0134	0.01225527 12.25527
4/5/17	7:00 PM	102255	18	11	0	0.001	1	12	4.6	-0.7	5.7	0.99	153.73	3.71	14.5	0.000141802	0.0138	0.01190808 11.90808
4/9/17	7:00 PM	108015	18	10	0	0.001	1	11	4.6	-0.3	5.1	0.99	153.73	3.32	14.7	0.000136092	0.0138	0.01166586 11.66586
4/13/17	7.00 PM	113775	20	10	0	0.001	1	11	4.6	-0.3	51	0.99	153.73	3.32	14.7	0.000129202	0.0134	0.01136672 11.36672
4/17/17	6:00 PM	110475	20	10	0	0.001	1	11	4.0	0.5	6.1	0.99	152.72	3.52	14.7	0.000123202	0.0134	0.01109226 11.00226
-+/ 1 / / 1 /	0.00 PIVI	1134/3	44	1 10	0	1 0.001	1 I	1 11	4.0	0.7	0.1	0.33	133./3	3.37	1 14./	10.000123030	0.0131	0.01103220 111.03220

	ADOBE
215	Weight of beaker (g)
	Total weight of sample
379.65	(g)
	Weight of the soil
164.57	sample (g)
- 10	sample (9)

								Meniscus	¥ (B)					0/ =:					
Data	a of sound		Tama (C?)	udaamatan Dandina (D.		в	Meniscus	(Corrected	A (Dispersion	~	Corrected		We	% Finer of	1	1/4	~	D (mm)	D (um)
1/24/2017	ne or reda	psea time (n	10 10	yarometer kedaing (ke	A .	D 0.001		Redding) (Rmc)	Agent correction)	0.5	Redding (KC)	a	164.57	10.00	10.1	20.2	0.0139	D (mm)	D (μm)
1/24/2017	5:15 PIVI	0.5	10	30	0	0.001	1	39	4.0	-0.5	32.9	0.99	164.57	19.99	10.1	20.2	0.0138	2 10274200	2102 744
1/24/2017	5:10 PIVI	2	10	37	0	0.001	1	30	4.0	-0.5	31.9	0.99	164.57	19.38	10.2	5.2	0.0138	3.193/4300	3193.744
1/24/2017	5.17 PIVI	2	10	30	0	0.001	1	37	4.0	-0.5	30.9	0.99	164.57	10.70	10.4	3.2	0.0130	2.28035085	1620 195
1/24/2017	5:19 PM	4	18	35	0	0.001	1	36	4.6	-0.5	29.9	0.99	164.57	18.17	10.5	2.625	0.0138	1.62018517	1620.185
1/24/2017	5:23 PIVI	0	18	33	0	0.001	1	34	4.0	-0.5	27.9	0.99	104.57	16.95	10.9	1.3625	0.0138	1.16/261/5	1107.202
1/24/2017	5:30 PM	15	18	31	0	0.001	1	32	4.6	-0.5	25.9	0.99	164.57	15.74	11.2	0.746666667	0.0138	0.86409876	864.0988
1/24/2017	5:45 PM	30	18	28	0	0.001	1	29	4.6	-0.5	22.9	0.99	164.57	13.92	11./	0.39	0.0138	0.6244998	624.4998
1/24/2017	6:15 PM	60	18	25	0	0.001	1	26	4.6	-0.5	19.9	0.99	164.57	12.09	12.2	0.2033333333	0.0138	0.45092498	450.925
1/24/201/	7:15 PM	120	18	23	0	0.001	1	24	4.6	-0.5	17.9	0.99	164.57	10.88	12.5	0.104166667	0.0138	0.322/4861	322./486
1/25/2017	3:00 PM	1335	17	19	0	0.001	1	20	4.6	-0.7	13.7	0.99	164.57	8.32	13.2	0.00988764	0.014	0.09943662	99.43662
1/25/2017	6:00 PM	1515	16	17	0	0.001	1	18	4.6	-0.9	11.5	0.99	164.57	6.99	13.5	0.008910891	0.0141	0.09439752	94.39752
1/26/2017	3:00 PM	2775	17	15.5	0	0.001	1	16.5	4.6	-0.7	10.2	0.99	164.57	6.20	13.9	0.005009009	0.014	0.07077435	70.77435
1/26/2017	5:00 PM	2895	17	15.5	0	0.001	1	16.5	4.6	-0.7	10.2	0.99	164.57	6.20	13.9	0.004801382	0.014	0.069292	69.292
1/26/2017	10:00 PM	3195	17	15	0	0.001	1	16	4.6	-0.7	9.7	0.99	164.57	5.89	13.8	0.004319249	0.014	0.06572099	65.72099
1/27/2017	3:00 PM	4215	17	15	0	0.001	1	16	4.6	-0.7	9.7	0.99	164.57	5.89	13.8	0.003274021	0.014	0.05721906	57.21906
1/27/2017	10:00 PM	4635	16	15	0	0.001	1	16	4.6	-0.9	9.5	0.99	164.57	5.77	13.8	0.002977346	0.0141	0.05456506	54.56506
1/28/2017	3:00 PM	5655	15.5	15	0	0.001	1	16	4.6	-1	9.4	0.99	164.57	5.71	13.8	0.002440318	0.0146	0.04939958	49.39958
1/30/2017	6:00 PM	8715	15	14	0	0.001	1	15	4.6	-1.1	8.3	0.99	164.57	5.04	14	0.001606426	0.0142	0.04008024	40.08024
1/31/2017	10:00 PM	10395	15	14	0	0.001	1	15	4.6	-1.1	8.3	0.99	164.57	5.04	14	0.001346801	0.0142	0.03669879	36.69879
2/2/2017	10:00 PM	13275	16	14	0	0.001	1	15	4.6	-0.9	8.5	0.99	164.57	5.16	14	0.001054614	0.0141	0.03247482	32.47482
2/6/17	6:00 PM	18795	16	14	0	0.001	1	15	4.6	-0.9	8.5	0.99	164.57	5.16	14	0.000744879	0.0141	0.02729247	27.29247
2/9/17	7:00 PM	23175	16	14	0	0.001	1	15	4.6	-0.9	8.5	0.99	164.57	5.16	14	0.000604099	0.0141	0.02457843	24.57843
2/12/17	4:00 PM	27315	16	14	0	0.001	1	15	4.6	-0.9	8.5	0.99	164.57	5.16	14	0.000512539	0.0141	0.02263932	22.63932
2/14/17	8:00 PM	30435	16	13.5	0	0.001	1	14.5	4.6	-0.9	8	0.99	164.57	4.86	14.1	0.000463282	0.0141	0.021524	21.524
2/16/17	7:00 PM	33255	17	13.5	0	0.001	1	14.5	4.6	-0.7	8.2	0.99	164.57	4.98	14.1	0.000423996	0.0141	0.02059117	20.59117
2/18/17	2:00 PM	35835	16	13.5	0	0.001	1	14.5	4.6	-0.9	8	0.99	164.57	4.86	14.1	0.00039347	0.0141	0.01983608	19.83608
2/22/17	10:00 PM	42075	19	13	0	0.001	1	14	4.6	-0.3	8.1	0.99	164.57	4.92	14.2	0.000337493	0.0136	0.01837097	18.37097
2/24/17	8:00 PM	44835	21	13	0	0.001	1	14	4.6	0.2	8.6	0.99	164.57	5.23	14.2	0.000316717	0.0133	0.01779654	17.79654
2/27/17	9:00 PM	49215	19	13	0	0.001	1	14	4.6	-0.3	8.1	0.99	164.57	4.92	14.2	0.00028853	0.0136	0.01698617	16.98617
3/1/17	10:00 PM	52155	19.5	12.5	0	0.001	1	13.5	4.6	-0.3	7.6	0.99	164.57	4.62	14.25	0.000273224	0.0139	0.01652949	16.52949
3/4/17	8.00 PM	56355	15	13.5	0	0.001	1	14.5	4.6	-0.15	8 75	0.99	164 57	5 32	14.1	0.0002502	0.0142	0.0158177	15 8177
3/7/17	11:00 PM	60855	19	13	0	0.001	1	14	4.6	-0.3	81	0.99	164 57	4.92	14.2	0.000233342	0.0136	0.01527552	15 27552
3/10/17	10.00 PM	65115	16	13.5	0	0.001	1	14.5	4.6	0.0	89	0.99	164.57	5.41	14.1	0.00021654	0.0141	0.0147153	14 7153
2/12/17	8.00 PM	60215	16	12.5	0	0.001	1	14.5	4.6	_0.15	9.75	0.99	164.57	5.22	14.1	0.000203419	0.0141	0.01426251	14 26251
3/15/17	11:00 PM	72275	10	13.5	0	0.001	1	14.5	4.0	-0.15	0.75	0.99	164.57	5.32	14.1	0.000203419	0.0141	0.01426231	12 05775
3/13/17	10:00 PM	72373	10	13.5	0	0.001	1	14.5	4.0	-0.15	0.75	0.99	104.57	5.52	14.1	0.000194819	0.0141	0.01333773	13.33773
3/1//1/	10:00 PM	75195	10.5	13	0	0.001	1	14	4.0	-0.15	8.25	0.99	104.57	5.01	14.2	0.000138842	0.0145	0.01374199	13.74199
3/20/17	11:00 PM	/9455	1/	13	0	0.001	1	14	4.6	-0.3	8.1	0.99	164.57	4.92	14.2	0.0001/8/18	0.014	0.01336853	13.30853
3/23/17	10:00 PM	83/15	16.5	13	0	0.001	1	14	4.6	-0.3	8.1	0.99	164.57	4.92	14.2	0.000169623	0.0145	0.01302394	13.02394
3/26/17	3:00 PM	87615	17.5	12.5	0	0.001	1	13.5	4.6	-0.4	7.5	0.99	164.57	4.56	14.25	0.000162643	0.0139	0.01275317	12.75317
3/29/17	7:00 PM	92175	20	12	0	0.001	1	13	4.6	-0.5	6.9	0.99	164.57	4.19	14.3	0.00015514	0.0134	0.01245551	12.45551
4/2/17	6:00 PM	97875	20	11	0	0.001	1	12	4.6	-0.7	5.7	0.99	164.57	3.46	14.5	0.000148148	0.0134	0.01217161	12.17161
4/5/17	7:00 PM	102255	18	11	0	0.001	1	12	4.6	-0.7	5.7	0.99	164.57	3.46	14.5	0.000141802	0.0138	0.01190808	11.90808
4/9/17	7:00 PM	108015	18	10.5	0	0.001	1	11.5	4.6	-0.3	5.6	0.99	164.57	3.40	14.6	0.000135166	0.0138	0.01162611	11.62611
4/13/17	7:00 PM	113775	20	10.5	0	0.001	1	11.5	4.6	-0.3	5.6	0.99	164.57	3.40	14.6	0.000128323	0.0134	0.01132799	11.32799
4/17/17	6:00 PM	119475	22	10	0	0.001	1	11	4.6	0.7	6.1	0.99	164.57	3.71	14.7	0.000123038	0.0131	0.01109226	11.09226

Appendix C: Grout Rheology Calculations

• Flow/ Viscosity

Batch #1 was prepared on 03/01/2017. Batch #2 was prepared on 03/15/2017.

Surrounding Conditions	Batch 1	Batch 2		
Room Temperature (°C)	22.2	18.9		
Relative Humidity (%)	44	23		

Temperature Reading	Batch 1	Batch 2
Mixing water (°C)	18	16.5
Grout (°C)	22	23

Duration of mixing	Time
Batch 1	5 min
Batch 2	5 min

Time of efflux of grout	Batch 1	Batch 2
Reading #1 (s)	14.28	20.84
Reading #2 (s)	16.05	22.62
Average Reading (s)	15.165	21.73

18.4475

Time of efflux of water	Batch 1	Batch 2	
Reading #1 (s)	5.72	4.46	
Reading #2 (s)	3.98	3.89	
Average Reading (s)	4.85	4.175	4.5125

• Wet Density

2.3. Part I Laboratory Testing Procedure (GCI 2011, 21):87

The wet density value (lab testing) was calculated using the following formulas:

$$\rho_{wet} = \frac{M_g}{400}$$
$$M_g = M_t - M_0$$

 $M_0(g)$: Weight of the cup

⁸⁷ Performed on March 2, 2017.

 $M_t(g)$: Total weight of the grout and cup $M_g(g)$: Weight of the grout ρ_{wet} (g \times cm^{-3}): Wet density of the grout

Specimen	Weight of the cup (g)	Weight of the grout + cup (g)	Weight of the grout (g)	Wet density of grout (g*cm–3)
1	98.63	1662.78	1564.15	1.84
2	101.3	1684.25	1582.95	1.86

4.5. Part II Field Testing Procedures (GCI 2011, 81):88

The wet density value (field testing) was calculated using the following formula:

*Used a 12ml syringe, instead of a 5ml syringe.

$$\rho_{\rm wet} = \frac{M_g}{12}$$

M_g(g): Weight of the grout

 $\rho_{\rm wet}$ (g \times cm^{-3}): Wet density of the grout

Specimen	Weight of 12mL syringe (g)	Weight of the grout + syringe (g)	Weight of the grout in syringe (g)	Wet density of grout (g*cm–3)
1	4.9	27.4	22.5	1.88
2	6.3	29.1	22.8	1.90

• Drying Shrinkage (ASTM C1148-92a)

The percent shrinkage, S, of the six specimens was calculated using the following formula:

$$S = \left[\frac{(L_1 - L)}{L_0}\right] \times 100$$

Where:

L0 = effective gage length, cm (in.),

L1 = initial measurement after removal from moist cure, cm, (in.), and

L = measurement during or after drying, cm (in.)

⁸⁸ Performed on March 15, 2017.

Grout Name	TUMA Soil Grout						
Grout Proportions	2.5: 1 (solid to water)						
Operator	Nicole Declet						
Date	02/14/2017						

*A length comparator as specified in the ASTM was used to measure the prisms.

Specime n (prism)	Effective gage	4 days	11 days	18 days	25 days	Drying Shrinkage	Percent Shrinkage
	length LO	Initial	Measu	Measurement during		Average	(S)
	(in.)	measurement after	drying L (in.)			mean	
		removal L1 (in.)					
1	5.438	7.646	5.41	5.344	5.372	5.943	41.82
2	5.438	6.04	4.584	4.532	4.554	4.9275	27.33
3	5.438	6.478	5.096	5.062	5.068	5.426	25.93
4	5.438	4.786	2.632	2.59	2.618	3.1565	39.87
5	5.438	6.758	5.862	5.82	5.83	6.0675	17.07
6	5.438	9.62	8.314	8.28	8.29	8.626	24.46

*Results that were less than 20% different from the average are shown in yellow.

Specime	4 days				11 days			
n (prism)	Length (in)	Width (in)	Height (in)	Area	Length (in)	Width (in)	Height (in)	Area
1	0.938	0.906	5.875	4.993	0.938	0.875	5.813	4.771
2	0.969	0.875	5.906	5.008	0.938	0.875	5.875	4.822
3	0.938	0.906	5.875	4.993	0.844	0.875	5.844	4.316
4	0.969	0.875	5.875	4.981	0.938	0.813	5.813	4.433
5	0.938	0.844	5.844	4.627	0.938	0.828	5.813	4.515
6	0.969	0.90625	5.906	5.186	0.969	0.938	5.844	5.312

The length, width and height for each prism was calculated every 4, 11, 18, and 25 days.

Specime	18 days				25 days			
n	Length	Width	Height	Area	Length	Width	Height	Area
(prism)	(in)	(in)	(in)		(in)	(in)	(in)	
1	0.938	0.875	5.813	4.771	0.938	0.875	5.813	4.771
2	0.938	0.844	5.875	4.651	0.938	0.844	5.875	4.651
3	0.906	0.875	5.844	4.633	0.906	0.875	5.844	4.633
4	0.938	0.813	5.813	4.433	0.938	0.844	5.813	4.602

5	0.906	0.828	5.813	4.361	0.906	0.844	5.813	4.445
6	0.969	0.906	5.844	5.131	0.969	0.906	5.844	5.131



• Expansion & Bleeding 2.2. Part I Laboratory Testing Procedure (GCI 2011, 18):

• •

The following formulas are used to calculate the Expansion and Bleeding of the grout:

Expansion, E (%) =
$$\frac{V_g - V_0}{V_0} \times 100$$

Bleeding, B (%) = $\frac{V_t - V_g}{V_0} \times 100$
Combined expansion, CE (%) = $\frac{V_t - V_0}{V_0} \times 100$
Final Bleeding, FB (%) = $\frac{V_w}{V_0} \times 100$

 V_0 (mL): Volume of the sample at the beginning of the test

 $V_t \ (mL)$: Volume of the sample at prescribed intervals, measured at the upper surface of water layer

 $V_{g}~(mL)$: Volume of grout portion of sample at prescribed intervals, measured at the upper surface of grout

$V_{w}\ (mL):$ Volume of decanted bleed water

Grout Name	TUMA Soil Grout	Temperature (C°)	21
Grout	2.5: 1 (solid to water)	Date	3/2/2017
Proportions			
Operator	Nicole Declet	Room	ACL Laboratory

Time	Interva	Volume of	Volume of	Expansion	Combined	Bleeding
	1	sample (upper	grout portion	%	Expansion	Expansion
		surface of water	(upper surface		%	
		layer) (mL)	of grout) (mL)			
3:52:00	0.15	400	400	0	0	0
PM						
4:07:00	0.3	400	400	0	0	0
PM						
4:22:00	0.45	400	400	0	0	0
PM						
4:37:00	1	400	400	0	0	0
PM						
5:37:00	2	400	400	0	0	0
PM						
6:37:00	3	400	400	0	0	0
PM						
7:37:00	4	400	400	0	0	0
PM						
8:37:00	5	400	400	0	0	0
PM						
9:37:00	6	400	400	0	0	0
PM						
10:37:0	7	400	400	0	0	0
0 PM						
11:37:0	8	400	400	0	0	0
0 PM						

Volume of sample at the beginning of test (mL)	400
Volume of decanted bleed water	0
Final Bleeding	0

• Splitting Tensile Strength 2.5. Part I Laboratory Testing Procedure (GCI 2011, 28):

The following formula was used to calculate the splitting tensile strength:

$$f = \frac{2 \times F}{\pi \times d \times 1}$$

Where:

F (N): Breaking Load

d (mm): Specimen diameter

I (mm): Specimen length

f (N \times mm⁻²): Splitting Tensile Strength

Grout Name	TUMA Soil Grout	Age of specimen	42 days	
		(days)		
Grout	2.5: 1 (solid to water)			
Proportions		Date	April 6, 2017.	
Operator	Nicole Declet			

Specim	Length	Diame	Breakin	Area of	Compr	Compr	Splittin	Splitting	Notes:
en	of	ter of	g Load	loaded	essive	essive	g	Tensile	
	specim	speci	Total	surface	Strengt	Streng	Tensile	Strengt	
	en	men	Maxim	in²	h in psi	th in	Streng	h	
			um			psi	th in	(f(N*m	
			Load in			(f(N*m	psi	m-2))	
			lbf			m-2))			
STS 2	3.806	1.8945	848.59	28.2758	30.011	0.207	74.960	0.517	200 lbs/v
				0087	17471		91234		0.02 in/v
STS 4	3.8285	1.898	994.53	28.4725	34.929	0.241	87.175	0.601	200 lbs/v
				623	41694		28507		0.02 in/v
STS 7	3.7005	1.892	1040.1	27.6042	37.679	0.26	94.624	0.652	200 lbs/v
			2	9892	63834		2073		0.02 in/v
STS 9	3.7805	1.885	1000.0	27.9549	35.773	0.247	89.383	0.582	200 lbs/v
			4	647	25211		45178		0.02 in/v
STS 10	3.7725	1.892	733.4	28.0320	26.162	0.18	65.447	0.451	200 lbs/v
				4228	91716		17011		0.02 in/v
STS 11	3.7735	1.9135	1041.9	28.4211	36.659	0.253	91.909	0.634	100 lbs/v
			2	868	97509		81697		0.02 in/v

*All results that differed by more 20% were discarded, ones that differed by 20% are shown in yellow.
Mean of	Mean of	Standard	Mean of	Standard
Maximum Load	Splitting	deviation of	Compressive	deviation of
(lbf)	Tensile	Splitting Tensile	Strength (psi)	Compressive
	Strength (psi)	Strength (psi)		Strength (psi)
943.10	75.86	11.32	36.26	4.49



• **Capillary water absorption** *2.7. Part I Laboratory Testing Procedure* (GCI 2011, 35):

Calculations used to calculate the capillary water absorption:

$$m = \frac{\Delta M_t}{\pi \times \left(\frac{d^2}{2}\right)} \times 10^3$$

 $\Delta M_{t} = M_{t} - M_{0}$

I(mm): Length of the specimen

d(mm): Diameter of the specimen

 $M_0(g)$: Dry weight of the specimen at time t

t(s): Time

 M_0 (g): Weight of the specimen at time t

 ΔM_t (g): Weight of absorbed water after rime t

$M(\mathrm{kg}\times\mathrm{m}^{-2})$: Weight of absorbed water per unit area

Grout Name	TUMA Soil Grout				
Grout Proportions	2.5: 1 (solid to water)				
Operator	Nicole Declet				
Date	21-Mar-17				

		3:20:3										
Time	3:20:0	0	3:22:0	3:25:0	3:30:0	3:35:0	3:50:0	4:20:0	5:20:0	6:20:0	7:20:0	8:20:0
<i>t</i> (s)	0 PM	PM	0 PM	0 PM	0 PM	0 PM	0 PM	0 PM	0 PM	0 PM	0 PM	0 PM
Interv												
al (s)	30	1	2	5	10	15	30	60	120	180	240	300
Mt	216.34	215.52	214.59	213.18	210.98	209.07	201.81	184.36	160.84	142.14	118.45	91.76
ΔMt	-0.12	-0.94	-1.87	-3.28	-5.48	-7.39	-14.65	-32.1	-55.62	-74.32	-98.01	-124.7
	-	-	-	-	-	-	-	-	-	-	-	-
m	6.84E-	5.36E-	1.07E-	1.87E-	3.12E-	4.21E-	8.35E-	1.83E-	3.17E-	4.24E-	5.59E-	7.11E-
(kg*m	05	04	03	03	03	03	03	02	02	02	02	02
-2)												

Specimen 1:

Speci	Length	Diame	Dry	Dry	Мо	Contai	Containe	Container	After
men	(in)	ter (in)	weight of	weight	Dry	ner	r+ Mesh+	+Mesh+St	experime
no.			the	П	weig	(Wg)	Stoppers	opper+Wa	nt
			specimen		ht III			ter	
			(t=0)						
1	4.25	1.495	241.93	216.3	216.	1047.5	1167.77	2049.13	2248.36
					46	6			
2	4.25	1.476	250.64	218.3	218.	966.1	1087.26	1957.94	2160.4
					27				
3	4.125	1.479	237.48	206.09	206.	963.94	1084.12	1877.05	2066.05
					04				

Specimen 2:

Time	3:20:0	3:20:3	3:22:0	3:25:0	3:30:0	3:35:0	3:50:0	4:20:0	5:20:0	6:20:0	7:20:0	8:20:0
t(s)	0 PM											
Interv												
al (s)	30	1	2	5	10	15	30	60	120	180	240	300
Mt	218.23	217.32	216.35	215	212.98	211.08	206.4	192.33	170.82	146.57	129.6	111.32
												-
ΔMt	-0.04	-0.95	-1.92	-3.27	-5.29	-7.19	-11.87	-25.94	-47.45	-71.7	-88.67	106.95
	-	-	-	-	-	-	-	-	-	-	-	-
m	2.34E-	5.55E-	1.12E-	1.91E-	3.09E-	4.20E-	6.94E-	1.52E-	2.77E-	4.19E-	5.18E-	6.25E-
(kg*m	05	04	03	03	03	03	03	02	02	02	02	02

Specimen 3:

Time t(s)	3:20:0 0 PM	3:20:3 0 PM	3:22:0 0 PM	3:25:0 0 PM	3:30:0 0 PM	3:35:0 0 PM	3:50:0 0 PM	4:20:0 0 PM	5:20:0 0 PM	6:20:0 0 PM	7:20:0 0 PM	8:20:0 0 PM
Interv al (s)	30	1	2	5	10	15	30	60	120	180	240	300
Mt	206.41	205.56	204.42	203.1	200.9	198.86	193.13	183.27	158.59	133.57	120.82	106.21
ΔMt	0.37	-0.48	-1.62	-2.94	-5.14	-7.18	-12.91	-22.77	-47.45	-72.47	-85.22	-99.83

m (kg*m −2)	2.15E- 04	- 2.80E- 04	- 9.43E- 04	- 1.71E- 03	- 2.99E- 03	- 4.18E- 03	- 7.52E- 03	- 1.33E- 02	- 2.76E- 02	- 4.22E- 02	- 4.96E- 02	- 5.81E- 02
-------------------	--------------	-------------------	-------------------	-------------------	-------------------	-------------------	-------------------	-------------------	-------------------	-------------------	-------------------	-------------------

• Water retention 3.2. Part I Laboratory Testing Procedure (GCI 2011, 51):

The water retention value was calculated using the following:

 M_W (g): Weight of the water used during grout mixing

 $M_{dg}\;$ (g): Total weight of dry grout ingredients used during grout mixing

- M_1 (g): Weight of perforated dish and wet filter paper
- M_2 (g): Weight of perforated dish and wet filter paper with grout
- M_3 (g): Weight of perforated dish and wet filter paper with grout after suction

 M_g (g): Weight of grout in the perforated dish

$$M_{G} = M_{2} - M_{1}$$

 ω : Water to grout weight ratio

$$\omega = \frac{M_W}{M_W + M_{dg}}$$

 W_1 (g): Water content of the grout before suction

W₂ (g): Weight of water extracted by suction

$$W_1 = \omega \times M_G$$

WRV (%): Water retention value

$$WRV = \left(1 - \frac{W_2}{W_1}\right) \times 100$$

Grout Name	TUMA Soil Grout	Temperature (C°)	21
Grout		RH (%)	30
Proportions	2.5: 1 (solid to water)	Date	4/11/2017
Oracitati			ACL
Operator	Nicole Declet	Room	Laboratory

Specimen #	Mw (g)	Mdg (g)	ω
1	124.33	415.17	0.23
2	124.29	414.55	0.23

Specimen #	M1 (g)	M2 (g)	Mg (g)	W1 (g)	M3 (g)	W2 (g)	WRV %
1	271.2	672.48	401.28	92.48	668.08	-4.4	104.76
2	270.21	658.45	388.24	89.58	654.05	-4.4	104.91

PRACTICE TESTS FOR COMPARISON: #1

Grout			
Name	NHL 3.5: Yellow Sand: Water	Temperature (C°)	21
Grout		RH (%)	30
Proportions	3.2: 1 (solid to water)	Date	4/11/2017

-

Specimen #	Mw (g)	Mdg (g)	ω
1	139.8	445.23	0.24

Specimen #	M1 (g)	M2 (g)	Mg (g)	W1 (g)	M3 (g)	W2 (g)	WRV %
1	272.64	651.74	379.1	90.98	611.84	-39.9	143.86

PRACTICE TESTS FOR COMPARISON: #2

Grout		Temperature	
Name	Soil B (ASTM #8 sieve): Water	(C°)	21
Grout		RH (%)	30
Proportions	2.5: 1 (solid to water)	Date	4/11/2017

Specimen #	Mw (g)	Mdg (g)	ω
1	81.26	256.26	0.24

Specimen #	M1 (g)	M2 (g)	Mg (g)	W1 (g)	M3 (g)	W2 (g)	WRV %
1	273.31	528.5	255.19	61.25	511.11	-17.39	128.39

PRACTICE TESTS FOR COMPARISON: #3

Grout		Temperature	
Name	Soil B (ASTM #8 sieve): HMP	(C°)	21
Grout		RH (%)	30
Proportions	2.5: 1 (solid to liquid)	Date	4/11/2017

Specimen #	Mw (g)	Mdg (g)	ω
1	124.53	343.51	0.27

Specimen #	M1 (g)	M2 (g)	Mg (g)	W1 (g)	M3 (g)	W2 (g)	WRV %
1	273.27	677.06	403.79	109.02	671.94	-5.12	104.70

• Permeability (WPT)

The water vapor transmission rate was calculated using the following formula:

WVT =
$$\frac{G}{tA}$$

Where G= weight change (grams)

t= time (hours)

G/t= slope of the straight line (g/h)

A= test area (cm²)

WVT= rate of water vapor transmission (g/h/cm²)

DATE	TIME	INTERVAL	DISK 1	DISK 2	DISK 3	DISK 4	DISK 5	DISK 6
			Mn (g)	Mn (g)	Mn (g)	Mn (g)	Mn (g)	Mn (g)
3/14/2017	8:00:00	0.00	146.58	148.34	143.67	151.44	142.62	144.85
	PM							
3/14/2017	8:05:00	0.08	146.52	148.28	143.61	151.37	142.57	144.79
	PM							
3/14/2017	8:15:00	0.25	146.54	148.29	143.63	151.39	142.58	144.80
	PM							
3/14/2017	8:30:00	0.50	146.53	148.3	143.62	151.38	142.57	144.80
	PM							
3/14/2017	9:00:00	1.00	146.52	148.28	143.63	151.37	142.57	144.79
	PM							
3/14/2017	11:00:00	3.00	146.53	148.3	143.63	151.38	142.58	144.8
	PM							
3/15/2017	1:00:00	17.00	146.55	148.27	143.62	151.37	142.58	144.79
	PM							
3/15/2017	6:00:00	22.00	146.54	148.24	143.63	151.37	142.59	144.8
	PM							
3/15/2017	11:00:00	27.00	146.53	148.19	143.63	151.33	142.58	144.79
	PM							
3/16/2017	1:00:00	41.00	146.5	148.08	143.62	151.27	142.57	144.74
	PM							
3/16/2017	10:00:00	50.00	146.45	147.99	143.58	151.2	142.53	144.7
	PM							
3/17/2017	1:00:00	65.00	146.36	147.81	143.5	151.07	142.46	144.59
	PM							
3/17/2017	10:00:00	74.00	146.29	147.72	143.46	151	142.4	144.52
	PM							
3/18/2017	8:00:00	96.00	146.12	147.45	143.33	150.79	142.27	144.34
- /20 /20/7	PM	424.00		4.47.04	4 4 9 9 7	450.40		4 4 2 . 0 2
3/20/2017	1:00:00	134.00	145.79	147.01	143.05	150.43	141.99	143.98
2/20/2017		144.00	4 45 74	146.02	142.07	450.22	1 1 1 0 1	1 4 2 00
3/20/2017	11:00:00	144.00	145.71	146.92	142.97	150.33	141.91	143.89
2/21/2017	12:00:00	160.00	145 50	146 77	142.96	150.21	141 70	142 77
5/21/2017	12.00.00	109.00	145.59	140.77	142.00	150.21	141.79	145.77
2/22/2017	2.00.00	195.00	1/5 2/	146.45	142.64	1/0 05	1/1 58	1/2 52
3/22/2017	2.00.00 DM	195.00	145.54	140.45	142.04	149.95	141.50	145.55
2/22/2017	5.00.00	222.00	1/15 12	1/6 12	1/12/12	1/0 60	1/1 25	1/12 27
5/25/2017	DM	222.00	145.12	140.12	142.45	149.09	141.55	145.27
3/24/2017	12:00:00	241.00	144.96	145 92	142.26	149 51	141.2	143 1
5, 24, 2017	PM	241.00	1	1-3.52	172.20		±-71.2	175.1
3/25/2017	3.00.00	244.00	144 71	145.62	142 04	149 27	140 97	142.85
0,20,2017	PM	244.00	1 1 1 1 1	143.02	112.04	1-15.27	110.57	112.05
3/26/2017	3:00.00	268.00	144 49	145 3	141 83	149	140 75	142 59
-,,,,	PM							
3/27/2017	1:00:00	290.00	144.25	145.04	141.63	148.75	140.53	142.37
	PM							

	7:00:00	320.00	143.97	144.7	141.38	148.45	140.23	142.07
3/28/2017	PM							
3/29/2017	7:00:00	344.00	143.72	144.42	141.14	148.17	139.96	141.78
	PM							
3/31/2017	6:00:00	391.00	143.28	143.82	140.73	147.67	139.49	141.31
	PM							
4/3/2017	2:00:00	459.00	142.63	143.08	140.15	147.02	138.9	140.67
	PM							

Change in						
weight (g)	0.74	0.92	0.66	0.82	0.74	0.78
Diameter						
(d) in	1.90	1.92	1.90	1.90	1.90	1.89
Diameter						
(d) mm	48.26	48.77	48.26	48.26	48.26	48.01
Diameter						
(d) m	0.05	0.05	0.05	0.05	0.05	0.05
Diameter						
(d) cm	4.83	4.88	4.83	4.83	4.83	4.80
Area (a) in						
cm	18.31	18.69	18.31	18.31	18.31	18.09
Time						
(interval)						
hours	76.00	76.00	76.00	76.00	76.00	76.00
	0.04	0.04	0.04	0.04	0.04	0.04
g/t	0.01	0.01	0.01	0.01	0.01	0.01
g/t/a	5.32E-04	6.48E-04	4.74E-04	5.89E-04	5.32E-04	5.67E-04
units	g/(h/cm^2)	g/(h/cm^2)	g/(h/cm^2)	g/(h/cm^2)	g/(h/cm^2)	g/(h/cm^2)

	Same result in different units (to compare with outside reports)						
Area (a) in							
m	0.001828287	0.00186713	0.001828287	0.001828287	0.001828287	0.001809394	
g/t/a	5.33	6.48	4.75	5.90	5.33	5.67	
units	g(h/m^2)	g(h/m^2)	g(h/m^2)	g(h/m^2)	g(h/m^2)	g(h/m^2)	

Average	5.57E-04	g/(h/cm^2)
Average	5.58	g(h/m^2)



• Shear Bond Strength (mock-up) 3.5. Part I Laboratory Testing Procedure (GCI 2011, 62):

The shear bond strength of the assemblies was calculated by using the following formula:

$$f_{sb} = \frac{F}{w \times l}$$

Where:

w(mm): Width of failed grout area

I(mm): Length of failed grout area

F(N): Breaking Load

 $f_{sb}(N \times mm^{-2})$: Shear Bond Strength

Grout Name	TUMA Soil Grout	Age of	
Grout	2.5: 1 (solid to water)	specimen	21 days
Proportions		(days)	
Operator	Dr. Alex Radin	Date	April 6, 2017.

Unconsolidated	Gap width	Width of failed grout area w (in)	Length of failed grout area I (in)	Breaking load F (lb)	Shear Bond Strength (Ib*in–2)
(-) B1	1/2"	2.8125	3.6805	38.01	3.67196486
(-) B2	1/2"	2.6585	3.743	27.67	2.780690591

(-) B3	1/4"	2.999	3.753	66.59	5.916351725
(-) B4	1/4"	2.611 3.655 29		29.3	3.070247364
(-) B5	1/4"	2.793 3.783 53.27		53.27	5.041681656
(-) B6	1/4"	2.8535	3.7705	62.82	5.838766533
(-) B8	1/2"	2.731	3.599	38.4	3.90685846
(-) B9	1/4"	2.558	3.6295	57.8	6.225589737
(-) B10	1/2"	2.7235	3.695	12.12	1.204372408

Consolidated	Gap width	Width of failed grout area w (in)	Length of failed grout area L (in)	Breaking load F (lb)	Shear Bond Strength (Ib*in–2)
A1	1/4"	2.907	3.65	56.73	5.346565447
A4	1/4"	2.747	3.657	30.21	3.007233187
A6	1/4"	2.8465	3.708	49.84	4.722012366
A7	1/4"	2.7495	3.7055	57.36	5.630002673
A8	1/2"	2.889	3.78	22.19	2.031973129
A9	1/4"	2.756	3.6695	28.57	2.825036967
A10	1/4"	2.877	3.726	161.19	15.0367986
A11	1/2"	2.738	3.7325	24.44	2.391486543
B11	1/2"	2.725	3.6025	41.25	4.201974928
B14	1/2"	2.711	3.779	23.05	2.249906758

	Width of grout	Length of grout	Breaking load	Shear Bond Strength	
	area w (in)	area l (in)	F (lb)	(lb*in–2)	
Unconsolidated	2.78	3.69	43.23	4.21	
Consolidated	2.81	3.67	51.30	4.98	

	Mean of Maximum Load (lbf)	Mean of Shear Bond Strength(psi)	Standard deviation of SBS (psi)	Variance	T-Test P value	T-Test 2-Tail P
Non- consolidated	43.2266667	4.21	1.7	3.85	0.015	0.683
Consolidated	51.295	4.98	3.85	14.8	0.015	0.005



Index

Α

В

bleeding (expansion)1, v, 2, 81, 90, 91, 117 brick......9, 13, 19, 46

С

50, 53, 58, 79, 83, 84, 125, 126, 127, 128, 129, 141

D

density..1, v, 1, 15, 54, 81, 87, 88, 114, 115, 116, 132, 166, 167

Ε

earthen ... 1, v, 1, 2, 46, 48, 49, 52, 53, 55, 56, 57, 58, 59, 60, 61, 63, 83, 92, 94, 140 expansion 1, 2, 16, 81, 90, 117, 169

F

facsimiles.....1, iv, 2, 103, 107, 109, 120 friable (plaster)....1, iv, 2, 19, 102, 104, 107, 109, 120, 126, 132, 146

G

gypsum .9, 13, 16, 29, 38, 39, 44, 49, 50, 58, 146, 151

Η

```
HMP......v, 1, 61, 65, 84, 85, 113, 114, 115, 122,
124, 133, 176
hydraulic 1, 12, 13, 14, 44, 46, 47, 48, 52, 57, 59,
60, 93, 96, 122, 124
L
```

lime . 1, v, 1, 2, 4, 9, 12, 13, 14, 18, 20, 21, 25, 27, 28, 29, 30, 31, 32, 34, 35, 36, 37, 39, 40, 41, 42, 44, 46, 47, 48, 49, 50, 52, 57, 59, 60, 61, 84, 93, 102, 104, 117, 119, 122, 124, 132, 146

М

mortar 1, 9, 13, 17, 21, 28, 32, 35, 36, 41, 61, 62, 63, 90

Ν

nanolime...... 1, 2, 61, 107, 108, 120, 129

Ρ

- painted 1, 9, 13, 19, 20, 21, 22, 28, 29, 40, 41, 44, 49, 61
- permeability 1, 2, 18, 54, 64, 81, 99, 101, 124, 132, 144
- plaster..1, iii, iv, v, xii, 13, 31, 39, 41, 43, 61, 103, 105, 108, 135, 137, 138, 139, 141, 143, 147

R

reattachment......1, 2, 41, 42, 46, 84, 134

S

mud1, v, 9, 17, 28, 35, 42, 50, 51, 54, 86, 102, 114, 115, 117, 140, 141

122, 124, 141, 168, 170, 171, 173, 175, 176, 179

Т

tensile strength iv, xii, 61, 92, 118, 120, 171, 172

V

viscosity 1, xii, 1, 30, 54, 55, 56, 57, 58, 65, 81, 84, 86, 97, 107, 113, 114, 132

W

wash (gypsum)......9, 13, 32, 37, 39